



Happy Link Claude TLDR Ticket Summary

AI-powered support ticket analysis — generated 2026-05-21

Confidential | Internal Use Only

TICKET OVERVIEW

Ticket: #121534

Category: PR (Product Replacements)

Subject: 合約fgw5500無法重置

Status: New

Updates: 221

URL: <https://support.linksys.com/staff/ticket/121534>

CUSTOMER DETAILS

Name: 王小姐

Phone: —

Email: beme98249819@gmail.com

Country: —

DEVICE DETAILS

Model Number: FGW5500

Warranty Start Date: —

Serial Number: —

Warranty Status: Unknown

Warranty/RMA

Hardware Failure

THE PROBLEM

Customer Ms. Wong (Annie Wong) has a Linksys FGW5500 contract router that cannot be reset and is completely unresponsive (no lights, no WiFi). She originally sought repair or replacement under warranty, but since the product is EOL/discontinued, the case escalated to a refund and RMA dispute. The customer strongly objects to a Tango Card gift card refund and demands a cash refund via FPS or cheque, and is also experiencing difficulty reaching the distributor Synnex/CSL for after-sales handling.

ACTIONS TAKEN

- Agent advised customer to hold reset button for 20 seconds — no response (no WiFi, no lights)
- Support requested purchase receipt, SN photo, power adapter photo, and video of the failed reset for warranty documentation
- Customer provided photos and video attachments
- Case escalated internally to Kris Qin and Ivan Chen
- Support confirmed product is EOL/discontinued and no replacement available
- Proposed proportional refund of HKD 213.71 via Tango Card digital gift card
- Customer repeatedly and emphatically refused Tango Card refund, demanding cash via FPS (ID: 166115469) or crossed cheque payable to Wong Mi Ha Annie
- Customer issued a formal complaint letter with a deadline of April 10, 2026, threatening Consumer Council complaint and social media exposure
- Case escalated to Ashley Alayon (Customer Advocacy) and Zither Calvin
- Multiple call-back attempts made by Kris — most went to voicemail; eventually reached customer on May 11
- Customer agreed to contact Synnex (distributor) for RMA; Synnex WhatsApp contact +852 5594 1080 provided
- Customer reported Synnex only responded with a chatbot and directed her to call 1010 (her ISP CSL/HK)

- Support further escalated to Sales team regarding Synnex contact issues
- Ashley advised customer to contact CSL directly at 2512 3123
- Customer noted 1010 only called to sell her a new plan, not to address the router issue
- Agent Kris called customer on May 18 and advised her to contact CSL; customer requested email confirmation
- Internal note logged: Synnex confirmed product is out of stock
- Ashley asked team whether customer has called CSL (status as of May 21 unknown)

Summary: Support attempted a factory reset (failed), collected warranty documentation, escalated the EOL product to a prorated refund via Tango Card (rejected by customer), then escalated to management and redirected the customer to distributor Synnex and then to ISP CSL for RMA/after-sales handling, with multiple failed call-back attempts throughout.

Insights: There is a major unresolved dispute: the customer firmly refuses the only refund method offered (Tango Card) and the product is confirmed out of stock with no direct replacement, leaving no clear resolution path. The case has been bounced between Linksys support, distributor Synnex, and ISP CSL without any party taking full ownership, causing significant customer frustration and escalating complaint risk.

NEXT STEPS

- Confirm whether customer has successfully contacted CSL at 2512 3123 and whether CSL is providing an actionable resolution
- If CSL cannot resolve the issue, determine whether an alternative cash refund method (FPS/cheque) can be authorized by Linksys management given the customer's documented refusal of the Tango Card
- Provide the customer with a clear single point of contact and a definitive resolution timeline to prevent further escalation to the Consumer Council or social media

TIMELINE (31 ENTRIES)

DATE	AUTHOR	SUMMARY
2026-03-13	Customer	Customer called to report FGW5500 router is completely non-functional; reset attempt failed (no WiFi, no lights); support collected email for warranty claim.
2026-03-13	Support (zhiliang.chen)	Support sent warranty documentation request to customer (purchase receipt, SN photo, power adapter photo) and internally flagged case to Kris Qin and Ivan Chen.
2026-03-13	Support	Support requested a video of the failed reset as additional warranty evidence.
2026-03-16	Customer	Customer submitted photos and a Google Drive video link as requested warranty documentation.
2026-03-18	Support	Support noted the Google Drive link was inaccessible and asked customer to re-send as attachments.
2026-03-18	Customer	Customer re-sent photos and a video file as direct email attachments; also expressed confusion about what documentation was needed.
2026-03-18	Support	Support confirmed receipt of video and internally notified Kris Qin that video had been received.
2026-03-19	Support	Support confirmed the router is a contract device and asked customer to provide the contract start date image for refund calculation.
2026-03-19	Customer	Customer submitted contract start date image.
2026-03-20	Support (zhiliang.chen)	Support informed customer that the product is discontinued and offered a prorated refund of HKD 213.71 via Tango Card digital gift card.

2026-03-20	Customer	Customer questioned what a digital card is and objected to only receiving ~HKD 213 when she has 4 months left on her contract.
2026-03-23	Support	Support explained the Tango Card process — rewards link sent via email, usable across multiple brands.
2026-03-23	Customer	Customer replied three times stating 'Disagree, Disagree, Disagree' — firmly rejecting the Tango Card refund.
2026-03-24	Customer	Customer followed up asking why there was no response and requested someone contact her.
2026-03-28	Support	Support reiterated that the Tango Card is the only available refund method.
2026-03-30	Customer	Customer sent a formal written complaint demanding cash refund via FPS or cheque, citing fair trade violations, service quality issues, and setting a deadline of April 10, 2026 with threats of Consumer Council complaint and social media exposure.
2026-03-30	Support	Support attempted to call customer but customer did not answer.
2026-04-03	Support (Kris Qin)	Case escalated to Ashley Alayon (Customer Advocacy) with full summary of customer demands and recommended talking points including Synnex referral option.
2026-05-04	ashley.alayon@linksys.com	Ashley Alayon reviewed the case and instructed Ivan Chen and Kris Qin to take ownership and provide detailed handling instructions including contacting Synnex for RMA.
2026-05-07	Support (Kris Qin)	Kris attempted to call customer at 5:00 PM but could not reach her; left a voicemail and emailed customer to schedule a call-back.
2026-05-07	Customer	Customer replied requesting a call between 12:00–14:00 the next day and provided an alternative phone number (98249819).
2026-05-08	Support (Kris Qin)	Support called customer multiple times between 12:30 and 17:23 — all calls went to voicemail; customer complained support had not called; support explained and apologized via email.
2026-05-11	Support (Kris Qin)	Successfully reached customer by phone; informed her to contact Synnex for RMA; customer agreed; support sent formal email with Synnex WhatsApp contact details (+852 5594 1080).
2026-05-11	Support (internal)	Internal note logged: Synnex confirmed product is out of stock.
2026-05-11	Customer	Customer reported that Synnex's WhatsApp only responded with a chatbot and she could not reach a real person.
2026-05-12	Support (Kris Qin)	Kris escalated to Ashley Alayon noting customer could not reach Synnex and risk of further complaint.
2026-05-13	ashley.alayon@linksys.com	Ashley escalated the Synnex contact issue to the Sales team for further guidance.
2026-05-14	ashley.alayon@linksys.com	Ashley advised team that per Sales (Davis), customer should be directed to contact her ISP CSL/HK.
2026-05-15	Support (Kris Qin)	Kris called customer; customer reported Synnex directed her to 1010 (CSL), but 1010 only tried to sell her a new plan and did not address the router issue; customer expressed concern about personal data.
2026-05-18	Support (Kris Qin)	Kris called customer, explained the 1010 situation, directed her to contact CSL at 2512 3123, and sent a formal email with CSL contact details as requested by customer.
2026-05-21	ashley.alayon@linksys.com	Ashley asked Kris and Xiao Ge Ji internally whether the customer has called CSL — status of resolution still unknown.

