December 18, 1957

MEMO TO: Messrs. G. A. Blaauw
F. P. Brooks
W. Buchholz
E. F. Codd
E. W. Coffin
H. G. Jones
H. G. Kolsky
Miss E. McDonough
Messrs. B. Moncreiff
D. W. Sweeney

SUBJECT: Project 7000 – Local Inquiry Stations

I would appreciate your consideration of the following items with respect to the part on the manual dealing with the Local Inquiry Station (IQS). A current goal is to service an IQS by a medium speed channel as well as a low speed one.

1. The EXCESSIVE INPUT light will require an extra line from the Exchange. (Elimination of this light should cause a CANCEL interrupt when the ECW reaches a zero count. This also requires special provision by the Exchange. If this situation is simply ignored, a normal END-OF-OPERATION will be initiated with no indication to the program that the message is incomplete, and the keyboard will lock.)

2. The CHECK light will require an extra line if it is to indicate errors recognized at places other than the IQS itself.

3. Is the BINARY mode desirable? Are any modifications of it requested?

4. Should the RESERVED light be dispensed with?

Jack C. Gibson

Jack C. Gibson

JCG/jcv