
By T.C. Chen Oct 1960

Life History of a Problem Solved on the 7030




Incorporate symbolic equivalents of numeric patches. Reassemble to obtain clean listing and clean binary deck if there have been many patches redebugging is needed.

T.C.C. Oct. 1960

7030 Special Registers (Locations 0.0 - 31.0)

(Shaded areas contain zero bits)



(P) Protected regardless of boundary specifications. (R): Read only.

T.C.C. Oct. 1960