```
1 $NOMOD51
2 $INCLUDE (8051.MCU)
         ; Reset Vector
4
5
         ORG
              0000H
6
         JMP
               START
7
8
         ORG
               0100H
9 START:
10
         MOV TMOD, #10H
         MOV TL1, #78H
11
         MOV TH1, #0ECH
12
         SETB TR1
13
         MOV R0, #9
14
15
16 LOOP:
17
         CALL DISPLAY
18
19
20 JMP LOOP
21
22 DISPLAY:
23
         MOV A, #01H
    HT1:
24
25
         MOV P3, A
26
         MOV P2, R0
27
         CALL Delay_5ms
28
         RR A
         CJNE A, #01H, HT1
29
30
         RET
31 RET
32
33 DELAY_5MS:
34
         MOV TL1, #78H
         MOV TH1, #0ECH
35
         SETB TR1
36
37
         JNB TF1, $
38 RET
39
         END
```

40