Sprint 4

We are going GOLD! This sprint was the most brutal. A week after GDC, we got all our horses, and that's when a lot of people's sets flipped. These last two weeks have been crunch getting in Art, fixing bugs, implementing final features, and tuning the horse controller. This sprint, I also did some bug fixes, software stuff like feature implementation, UI Design and implementation, and making the horse controller as good as it can be. The controls and code of the controller itself are solid, but there are issues with wires getting disconnected and Bluetooth not being as responsive, but I think it is caused by the former. I spent a lot of time on this project because I deeply care about it and want to see it succeed at conventions.

Situation: The Horse steering was just a mess and unresponsive, or it read the wrong input, making it hard to get through the track; they would also disconnect randomly

Task: Fix how turning works by either simplifying/altering the code or using a different sensor. We also need to find a way to make it so the wires don't come unplugged. We already have a plan B for Bluetooth, as I have an option to make these controllers work on a hardwire connection.

Action: We designed potential fixes with a rotary encoder as a Plan B, but I took the hardware code and modified it to be simple and reduce variance with the sensor. To make sure the wire connects to the breadboard, we are brainstorming ideas like hot glue, tape, and more.

Result: The turning looks and feels much smoother and better to control; the wires still come undone with tape, so we need to continue making sure they stay put.