




USB




12MHz Clock





Flash



SPI



Status Bar



Sheet: /MCU/
File: MCU.kicad_sch

Title: AuraMon

Size: A4 Date:
KiCad E.D.A. 9.0.2

Rev: v0.1
Id: 2/7

1 2 3 4 5 6

A

A

B


B

C

C

D

D




Sheet: /Modbus/
File: Modbus.kicad_sch


Title: AuraMon

Size: A4 Date:
KiCad E.D.A. 9.0.2

Rev: v0.1
Id: 3/7

1 2 3 4 5 6






1 2 3 4 5 6

A

B

C

D



Sheet: /Power/
File: Power.kicad_sch





Title: AuraMon

Size: A4 Date:
KiCad E.D.A. 9.0.2

Rev: v0.1
Id: 6/7

1 2 3 4 5 6

1 2 3 4 5 6

Reset**Indicators****Bus Bar****Pair**

Sheet: /Control/
File: Control.kicad_sch

Title: AuraMon

Size: A4 Date:
KiCad E.D.A. 9.0.2

Rev: v0.1
Id: 7/7

1 2 3 4 5 6