

වාරිමාර්ග දෙපාර්තමේන්තුව நீர்ப்பாசனத் திணைக்களம்





වාරීමාර්ග අධාක්ෂ நீர்ப்பாசனத பணிப்பாளர் Director of Irrigation	011-2591125 முகவரி } 230, த	ു.ප. 1138, രെംද്വാര്വേത
දුරකථනය(පොදු) தொலைபேசி(பொது) Telephone(General)	විද්යුත් ලිපිනය ஈ.யெய்ஸ் முகவரி E-mail Address	වෙබ් අඩවිය இணையதளம் } www.irrigation.gov.lk Web site
මගේ අංකය எனது இல My No. DI/Hydro/103(V)	මබේ අංකය உழது இல Your No.	දිනය නිය Date } 2025.01.19

ප.ව. 4.30 වේලාව :-

2025.01.21 දින ප.ව. 4.30 දක්වා වලංගුවේ. Valid till 4.30 PM on 21th of January 2025

ගංවතුර අනතුරු ඇහවීමේ නිවේදන : - 02 වර්ණය - රතු **Flood Warning Message** : Number - 02 Colour - Red



මල්වතු ඔය දෝණිය - Malwathu Oya Basin

මල්වතු ඔය දෝණියේ ඉහළ හා පහල පුදේශවලට අද සවස 4.00 වන විට සැලකිය යුතු වර්ෂාපතනයක් ලැබී ඇත. තවදුරටත් වර්ෂාව ලැබෙමින් පවතින අතර ඊට අමතරව නාච්චාදුව ජලාශයේ පිටවාන් දොරටු විවෘත කර මේ වනවිට තත්පරයට සණ අඩි 3700 ක් තරම් සීගුතාවයකින් මල්වතු ඔයට ජලය පිටවාන් දමමින් පවතී. මෙම තත්වය මක වාරිමාර්ග දෙපාර්තමෙන්තුව මගින් නඩක්තු කරනු ලබන ජල මාපක වල විශ්ලේෂණය අනුව මෙකැන් සිට පැය 48 ක් දක්වා කාලය **වෙන්ගලවෙඩඩිකුලම්, මඩු, මුසාලෛ, නැනඩ්ඩාන්** යන පාදේශීය ලේකම් කොට්ඨාශ වලට අයත් ගංවතුර නිම්නයේ පිටාර තැන්නට අයත් පුදේශ වලට **මහ ගංවතුර තත්ත්වයක්** ඇතිවිය හැකි බවට අනතුරු අහවනු ලැබේ. මේ හේතුවෙන් මල්වතු ඔය අවට පහත් බිම් හරහා වැටී ඇති දැනට යටවී පවතින මාර්ග දැඩි අවධානම්කාරී වනු ඇත. මේ තත්වය සම්බන්ධයෙන් දැඩි සැළකිල්ලකින් කටයුතු කරන ලෙස එම පුදේශ වල පදිංචි මහජනතාවගෙන් සහ පුදේශ හරහා ගමන් ගන්නා වාහන පදවන්නන්ගෙන් ඉල්ලා සිටිනු ලැබේ. තවද මේ සම්බන්ධයෙන් අවශා පියවර ගන්නා ලෙස ආපදා කළමනාකරණ අංශවලින් ඉල්ලා සිටිනු ලැබේ.

A considerable rainfall has been occurred in Up and mid-stream areas of Malwathu Oya as of 4.00 pm today. In addition, Nachchaduwa reservoir is now spilling at a rate of **3700 cubic feet per second**. By analyzing that situation and river water levels of hydrological stations in Malwathu Oya, it is warned that there is a possibility of occurring a Major flood situation in lowline areas of Malwathu Oya valley situated in Vengalacheddikulam, Madu, Mussalei and Nanaddan DS Divisions. As a result, already inundated roads may become highly vulnerable and dangerous for crossing. The residents and vehicle drivers running through those areas are requested to high attention in this regard. Disaster Management Authorities are requested to take adequate actions in this regards.

ඉංජි. එල්.එස්. සූරියබණ්ඩාර

Eng. L.S. Sooriyabandara Director of Irrigation drology Disaster Management) Hydrology & Disaster Management Division Irrigation Department 230 Rauddhaloka Mawatha, Colombo 07.

වාරිමාර්ග අධානක්ෂ (ජලවිදාහා හා ආපදා කළමනාකරණ)