

වාරිමාර්ග දෙපාර්තමේන්තුව நீர்ப்பாசனத் திணைக்களம்

IRRIGATION DEPARTMENT



(HYDROLOGY AND DISATER MANAGEMENT DIVISION)

্তি বে ক্ষেত্র নাজান্ত প্রত Му No. В DI/Hydro/103(V)	ඔබේ අංකය உ.µது இහ Your No.	දිනය නිස Date } 2025.01.19
දුරකථනය(පොදු) මනුතාහරීයମ්(විධානු) Telephone(General)	විද්යුත් ලිපිනය ஈ.ගෙරා්ම (ආසාගි) E-mail Address	වേබ අඩවිය இணையதளம் Web site
වාරීමාර්ග අධාක්ෂ நீர் ப் பா சன த பணிப்பாளர் Director of Irrigation Fax	011-2591125 முகவரி 230, த.பெ.	. 1138, බෞද්ධාලෝක මාවක,කොළඹ07, •ලංකාව I138,பௌத்தாலோக்கமாவத்தை,கொழும்பு 07,இலங்கை lox 1138, BauddhalokaMawatha, Colombo 07, Sri Lanka

Time :-5.00 PM වේලාව :-ප.ව. 5.00

2025.01.21 දින ප.ව. 5.00 දක්වා වලංගුවේ. Valid till 5.00 PM on 21st of January 2025

ගංවතුර අනතුරු ඇහවීමේ නිවේදන : - 01 වර්ණය - ඇම්බර් **Flood Warning Message** : Number - 01 Colour – Amber

දැදුරු ඔය ලදු්ණිය - Deduru Oya Basin

දැදුරු ඔය දෝණියේ ඉහළ හා මධා පුදේශවලට ඇදහැලුණු සැලකිය යුතු වර්ෂා තත්වය හේතුකොටගෙන දැදුරු ඔයෙහි ජල මට්ටම ගංවතුර මට්ටමට ආසන්නව පවතී. කවද **දැදුරු ඔය ජලාශයේ** පිටවාන් දොරටු විවෘත කර මේ වනවිට තත්පරයට සණ අඩි 16000 ක් තරම් සීගුතාවයකින් දැදුරු ඔයට ජලය මුදාහරිමින් පවතී. මේ වනවිට ජලාශයට ලැබෙන ජල ධාරිතාව අනුව මෙම පුමාණය ඉදිරියේදි තව දුරටත් වැඩි කිරීමට සිදුවිය හැකිය. මේ තත්වය මත දෝණියේ පිහිටි වාරියපොල, නිකවැරටිය, මහව, කොබෙයිගනේ, බිංගිරිය, පල්ලම, හලාවත, ආරච්චිකට්ටුව සහ රස්නායකපුර යන පුාදේශීය ලේකම් කොට්ඨාශ වලට අයත් ගංවතුර නිම්නයේ පහළ පුදේශ වලට **ගංවතුර** තත්ත්වයක් ඇතිවිය හැකි බවට අනතුරු අභවනු ලැබේ. මේ තත්වය සම්බන්ධයෙන් දැඩි සැළකිල්ලකින් කටයුතු කරන ලෙස එම පුදේශ වල පදිංචි මහජනතාවගෙන් සහ පුදේශ හරහා ගමන් ගන්නා වාහන පදවන්නන්ගෙන් ඉල්ලා සිටිනු ලැබේ. තවද මේ සම්බන්ධයෙන් අවශා පියවර ගන්නා ලෙස ආපදා කළමනාකරණ අංශවලින් ඉල්ලා සිටිනු ලැබේ.

A considerable rainfall has been occurred in Up and mid stream areas of Deduru Oya as of 5.00 pm today. **Deduru Oya reservoir** is now spilling at a rate of **16000 cubic feet per second**. By analyzing that situation and river water levels of hydrological stations in Deduru Oya, it is warned that there is a possibility of occurring a flood situation in lowline areas of Deduru Oya valley situated in Wariyapola, Nikaweratiya, Mahawa, Kobeigane, Bingiriya, Pallama, Chilaw, Arachchikattuwa and Rasnayakapura DS Divisions. As a result there is a high possibility of inundating Off-Roads running through flood plains of Deduru Oya. It is requested to pay high attention in this regard by the residents in those area and vehicle drivers running through those areas. Disaster Management Authorities are requested to take adequate actions in this regards.

1.1.1. Bud ඉංජි. එල්.එස්. සුරියඛණ්ඩාර

Eng. L.S. Sooriyabandara **Director of Irrigation** (Hydrology Disaster Management) Hydrology & Disaster Management Division Irrigation Department 230 Rauddhaloka Mawatha, Colombo 07.

වාරිමාර්ග අධානක්ෂ (ජලවිදාහා හා ආපදා කළමනාකරණ)