



වාරිමාර්ග දෙපාර්තමේන්තුව
நீர்ப்பாசனத் திணைக்களம்
IRRIGATION DEPARTMENT

(HYDROLOGY AND DISASTER MANAGEMENT DIVISION)



වාරිමාර්ග අධ්‍යක්ෂ
நீர்ப்பாசனத் திணைக்களம்
Director of Irrigation } 011-2581636

ෆැක්ස්
பக்ஸ் } 011-2591125
Fax

ලිපිනය
முகவரி } 230, තැ.පෙ. 1138, බොද්ධාලෝක මාවත, කොළඹ 07, ශ්‍රී ලංකාව
Address } 230, த.பெ.1138, பொத்தாலோக்கமாவத்தை, கொழும்பு 07, இலங்கை
230, P.O. Box 1138, Bauddhaloka Mawatha, Colombo 07, Sri Lanka

දුරකථනය (පොදු)
தொலைபேசி (பொது)
Telephone (General) } 011-2590145

විද්‍යුත් ලිපිනය
ஈ.மெயில் முகவரி } ddhydrology@gmail.com
E-mail Address

වෙබ් අඩවිය
இணையதளம் } www.irrigation.gov.lk
Web site

මගේ අංකය
எனது இல
My No. } DI/Hydro/103(V)

ඔබේ අංකය
உமது இல
Your No. }

දිනය
திகதி } 2025.11.28
Date

2025.11.30 දින ප.ව 3.00 දක්වා වලංගුවේ.

Valid till 3.00 PM on 30th of November 2025

Time :- 3.00 PM

වේලාව :- ප.ව. 3.00

ගංවතුර අනතුරු ඇඟවීමේ නිවේදන : අංක - 05
Flood Warning Message : Number - 05

වර්ණය - රතු
Colour - Red



ගම්පහ නගරය සඳහා විශේෂ ගංවතුර අනතුරු ඇඟවීම
අත්තනගලු ඔය ද්‍රෝණිය - Aththanagalu Oya Basin

අත්තනගලු ඔය ද්‍රෝණියේ ධාරා ප්‍රදේශවල බොහෝ ස්ථානවලට මේ වනවිට අධික වර්ෂාපතනයක් ලැබෙමින් පවතී. එම වර්ෂා තත්ත්වය සහ වාරිමාර්ග දෙපාර්තමේන්තුව මගින් අත්තනගලු ඔය ද්‍රෝණිය තුළ නඩත්තු කරනු ලබන ගංගා ජල මාපකවල ජල මට්ටම් විශ්ලේෂණය අනුව ඉදිරි පැය 6 ක කාලය තුළ ගම්පහ නගරය හා ඒ අවට අත්තනගලු ඔය සහ උරුවල් ඔය නිම්නවල පහත්බිම් ප්‍රදේශවලට මහ ගංවතුර තත්ත්වයක් ඇතිවිය හැකි බවට අනතුරු අඟවනු ලැබේ. මේ තත්ත්වයෙන් ජීවිත හා දේපළ ආරක්ෂා කර ගැනීම පිණිස දැඩි සැලකිල්ලෙන් කටයුතු කරන ලෙස එම ප්‍රදේශවල පදිංචි මහජනතාවගෙන් සහ මෙන්ම නගරයේ වෙළඳසැල් හිමිකරුවන්ගෙන්ද ඉල්ලා සිටිනු ලැබේ. ඔවුන්ගේ ආරක්ෂාව සඳහා අවශ්‍ය පියවර ගන්නා ලෙස ආපදා කළමනාකරණ අංශ වලින් ඉල්ලා සිටිනු ලැබේ.

Heavy rainfall is currently being experienced in many catchment areas of the Attanagalu Oya Basin. Based on the prevailing rainfall conditions and the analysis of river water levels recorded at river gauging stations maintained by the Irrigation Department within the Attanagalu Oya Basin, **it is hereby warned that within the next 6 hours, a Major Flood Situation may occur in the low-lying areas of the Attanagalu Oya and Uruwal Oya valleys, including Gampaha town and its surrounding areas.** The public residing in these areas, as well as drivers and passengers traveling through these regions, are strongly requested to exercise extreme caution in order to safeguard their lives and property. **Disaster Management authorities are requested to take all necessary measures to ensure public safety.**

Eng. L.S. Sooriyabandara
Director of Irrigation
(Hydrology - Disaster Management)
Hydrology & Disaster Management Division
Irrigation Department
230 Bauddhaloka Mawatha, Colombo 07.

ඉංජි. එල්.එස්.සූරියබණ්ඩාර
වාරිමාර්ග අධ්‍යක්ෂ (ජල විද්‍යා හා ආපදා කළමනාකරණ)