



වාරිමාර්ග දෙපාර්තමේන්තුව
நீர்ப்பாசனத் திணைக்களம்
IRRIGATION DEPARTMENT



(HYDROLOGY AND DISASTER MANAGEMENT DIVISION)

වාරිමාර්ග අධ්‍යක්ෂ
நீர்ப்பாசனத் திணைக்களம்
Director of Irrigation } 011-2581636

ෆැක්ස්
பக்ஸ் } 011-2591125
Fax

ලිපිනය
முகவரி } 230, තැ.පෙ. 1138, බොද්ධාලෝක මාවත, කොළඹ 07, ශ්‍රී ලංකාව
Address } 230, ත.பெ.1138, பொத்தாலோக்கமாவத்தை, கொழும்பு 07, இலங்கை
230, P.O. Box 1138, BaudhalokaMawatha, Colombo 07, Sri Lanka

දුරකථනය (පොදු)
தொலைபேசி (பொது) } 011-2590145
Telephone (General)

විද්‍යුත් ලිපිනය
ஈ.மெயில் முகவரி } directorhyg@gmail.com
E-mail Address

වෙබ් අඩවිය
இணையத்தளம் } www.irrigation.gov.lk
Web site

මගේ අංකය
எனது இல } DI/Hydro/103(V)
My No.

ඔබේ අංකය
உமது இல }
Your No.

දිනය
திகதி } 2025.11.28
Date

2025.11.30 දින පෙ.ව.3.30 දක්වා වලංගුවේ.

Valid till 3.30 AM on 30th of November 2025

Time :- 3.30 AM

වේලාව :- පෙ.ව. 3.30

ගංවතුර අනතුරු ඇඟවීමේ නිවේදන : අංක - 02

Flood Warning Message : Number - 02

වර්ණය - රතු

Colour - Red



යාන් ඔය දෝණිය - Yan Oya Basin

යාන් ඔය දෝණියේ ඉහළ සහ මධ්‍යම ධාරා ප්‍රදේශවලට අධික වර්ෂාපතනයක් ලැබෙමින් නිසා සහ යාන් ඔය පිටවන මගින් මේ වන විට ජලය පිට කරමින් පවතින බැවින් ද යාන් ඔය පහල ප්‍රදේශවලට මහ ගංවතුර තත්ත්වයක් ඇතිවිය හැකි බවට මින් අනතුරු අඟවනු ලැබේ. මෙම ගංවතුර තත්ත්වය හේතුවෙන් සිදුවිය හැකි අනතුරු අවම කරගැනීමට අවශ්‍ය පියවර ගන්නා ලෙස යාන් ඔය පහල ප්‍රදේශවල වෙසෙන මහජනතාවගෙන් සහ ප්‍රදේශ හරහා ගමන් ගන්නා රියදුරන්ගෙන් ඉල්ලා සිටිනු ලැබේ. විශේෂයෙන් කුවිවවෙලි, පදවි ශ්‍රී පුර, පදවිය, කැබිතිගොල්ලුව, ගෝමරන්කඩවල, හොරොවිපතන, මොරාවුව, කහටගස්දිගිලිය හා ගලෙන්බිඳුණුව යන ප්‍රාදේශීය ලේකම් කොට්ඨාශවල යාන්ඔය ආශ්‍රිත පහත් බිම්වල වෙසෙන ජනතාව සහ එම ප්‍රදේශ හරහා ගමන් කරන රථ වාහන රියදුරන් සහ මගීන් දැඩි විමසිල්ලෙන් පසුවිය යුතුය. මේ සම්බන්ධයෙන් අවශ්‍ය පියවර ගන්නා ලෙස ආපදා කළමනාකරණ අංශ වලින් ඉල්ලා සිටිනු ලැබේ.

Due to the heavy rainfall occurring in the upper and middle catchment areas of the Yan Oya Basin, and as water is currently being released through the Yan Oya spillway, hereby a warning is issued that a **Major Flood Situation** may occur in the lower reaches of the Yan Oya. The public residing in the lower areas of the Yan Oya are requested to take necessary measures to minimize possible risks arising from this flood situation. Vehicle drivers travelling through these areas are also advised to act with extreme caution. In particular, the residents living in the low-lying areas along the **Yan Oya in the Divisional Secretariat Divisions of Kuchchaveli, Padavi Sripura, Morawewa, Padaviya, Kebithigollewa, Gomarankadawala, Horowpothana, Kahatagasdigiliya, and Galenbindunuwewa**, as well as motorists and passengers travelling through these areas, should remain highly vigilant. **The Disaster Management Authorities** are requested to take all necessary actions in this regard.

Eng. L.S. Sooriyabandara
Director of Irrigation
(Hydrology - Disaster Management)
Hydrology & Disaster Management Division
Irrigation Department
230 Baudhaloka Mawatha, Colombo 07.

ඉංජි. එල්.එස්.සූරියබණ්ඩාර

වාරිමාර්ග අධ්‍යක්ෂ (ජල විද්‍යා හා ආපදා කළමනාකරන)