

වාරිමාර්ග දෙපාර්තමේන්තුව

நீர்ப்பாசனத் திணைக்களம்

IRRIGATION DEPARTMENT





වාරිෂාර්ශ අධාාක්ෂ நீர்ப்பாசனத பணிப்பாளர் Director of Irrigation	011-2591125 முகவரி 230, த.பெ.11	l138, ெெද්ධාලෝක මාවත,කොළඹ07,இரு:කාව 38,பௌத்தாலோக்கமாவத்தை,கொழும்பு 07,இலங்கை x 1138, BauddhalokaMawatha, Colombo 07, Sri Lanka
දුරකථනය(පොදු)	විද්යුත් ලිපිනය	වෙබ් අඩවිය
මதாலைபேசி(பொது)	අ.ඛගඨාර (மුසඹෝ } directorhyg@gmail.com	இணையதளம்
Telephone(General)	E-mail Address	Web site
©ன் අ∗කය	ඔබේ අංකය	දිනය
எனது இல	உமது இல	නිස
My No. } DI/Hydro/103(V)	Your No.	Date } 2025.10.20
2025.10.21 දින මධා හැන්න 12.00 දක්වා වලංගුවේ. Valid till 12.00 noon on 21st of October 2025		
ගංවතුර අනතුරු ඇඟවීමේ නිවේදන :	අංක 01	වර්ණය - ඇම්බර්
Flood Warning Message	Number 01	Colour – Amber

දැදුරු ඔය ලදුන්ණිය - Deduru Oya Basin

දැදුරු ඔය දෝණීයේ ඉහළ හා මධා පුවේශවලට ඇදහැලුණු සැලකිය යුතු වර්ෂා තත්ත්වය හේතුකොටගෙන දැදුරු ඔයෙහි ජල මට්ටම ගංවතුර මට්ටමට ආසන්නව පවතී. තවද දැදුරු ඔය ජලාශයේ පිටවාන් දොරටු විවෘත කර මේ වනවිට තත්පරයට සණ අඩි 16250 ක් තරම් සීගුතාවයකින් දැදුරු ඔයට ජලය මුදාහරිමින් පවතී. වම් වනවිට ජලාශයට ලැබෙන ජල ධාරිතාව අනුව මෙම පුමාණය ඉදිරියේදී තව දුරටත් වැඩි කිරීමට සිදුවිය හැකිය. වම් තත්වය මත දැදුරු ඔය දෝණියේ පිහිටි වාරියපොල, නිකවැරටිය, මහව, කොබෙයිගනේ, බිංගිරිය, පල්ලම, හලාවත, ආරච්චිකට්ටුව සහ රස්තායකපුර යන පුාදේශීය ලේකම් කොට්ඨාශ වලට අයත් ගංවතුර නිම්නයේ පහළ පුවේශ වලට ගංවතුර තත්ත්වයක් ඇතිවිය හැකි බවට අනතුරු අහවනු ලැවේ. මේ තත්ත්වය සම්බන්ධයෙන් දැඩි සැළකිල්ලකින් කටයුතු කරන ලෙස එම පුදේශවල පදිංචි මහජනතාවගෙන් සහ පුවේශ මාර්ග හරහා ගමන් ගන්නා වාහන පදවත්නන්ටගන් ඉල්ලා සිටිනු ලැබේ. තවද වම් සම්බන්ධයෙන් අවශා පියවර ගන්නා ලෙස ආපදා කළමනාකරණ අංශවලින් ඉල්ලා සිටිනු ලැබේ.

A considerable rainfall has been occurred in Up and mid stream areas of Deduru Oya as of 5.00 am today. Deduru Oya reservoir is now spilling at a rate of 16250 cubic feet per second. By analyzing that situation and river water levels of hydrological stations in Deduru Oya, it is warned that there is a possibility of occurring a flood situation in lowline areas of Deduru Oya valley situated in Wariyapola, Nikaweratiya, Mahawa, Kobeigane, Bingiriya, Pallama, Chilaw, Arachchikattuwa and Rasnayakapura DS Divisions. As a result, there is a high possibility of inundating Off-Roads running through flood plains of Deduru Oya. It is requested to pay high attention in this regard by the residents in those area and vehicle drivers running through those areas. Disaster Management Authorities are requested to take adequate actions in this regards.

ඉංජි. එල්.එස්.සූරියබණ්ඩාර

Eng. L.S. Seeriyabandera
Director of Irrigation
(Hydrology - Disester Management)
Hydrology & Disester Management Division
Irrigation Department

වාරිමාර්ග අධා ක්ෂ (ජලවිදාහ හා ආපදා කළමිතා කරිණි) Mawatha, Colombo 07.