




- 2. solder
- 3. component
- 4. componentmask
- 5. soldermask
- 6. plated-drill
- 7. topsilk
- 8. bottomsilk
- 9. topassembly
- 10. bottomassembly
- 11. fab























ot, 298 holes total Title: card - Fabrication Drawing Ruthor: Windell H. Oskay Date: Sat Nov. 8 85:52:42 2888 UTC Maximum Dimensions: 3588 mils wide, 2888	+ + + + + + + + + + + + + + + + + + + +	× × × × × × × × × × × × × × × × × × ×	x x x x x x x x x x x x x x x x x x x	2888 mils	
out, 298 hales total Title: card - Fabrication Drawing Ruthor: Windell H. Oskay Date: Sat Nov 8 85:52:42 2888 UTC Maximum Dimensions: 3588 mils wide	+ +	x x x x x x x x x x x x x x x x x x x	× × × × × × × × × × × × × × × × × × ×		
Nere are 5 different drill sizes used in this layout, 298 holes total   Symbol   Diam. (Inch)   Count   Plated?	× × ×	x x x x x x x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x	of this 10 mil recto	
6 5 different drill sizes us  10 00 00 00 00 00 00 00 00 00 00 00 00 0		x x x x x x x x x x x x x x x x x x x	* * * * * * * * * * * * * * * * * * *	is the centerline	
There are 5 differ Symbol Diam. (I)	<b>≻ °</b> ≻ °	x x x x x x x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x	Board outline	