Report Generated by Test Manager

Title: Baseline_Test_report

Author:

Date: 02-Apr-2023 22:11:23

Test Environment

Platform: MACI64 MATLAB: (R2022a)

Summary

Name	Outcome	(Seconds)		
Results: 2023-Apr-02 21:55:33	②	31.941		
New Test Case 1	Ø	31.898		

Results: 2023-Apr-02 21:55:33

Result Type: Result Set

Parent: None

 Start Time:
 02-Apr-2023 21:55:38

 End Time:
 02-Apr-2023 21:56:10

 Outcome:
 Total: 1, Passed: 1

Aggregated Coverage Results

Analyzed Model	Sim Mode	Complexity	Decision	Execution
Vehicle Speedometer Module	Normal	10	100%	100%

Back to Report Summary

New Test Case 1

Test Result Information

Result Type: Test Case Result

Parent: Results: 2023-Apr-02 21:55:33

Start Time: 02-Apr-2023 21:55:38 End Time: 02-Apr-2023 21:56:10

Outcome: Passed

Test Case Information

Name: New Test Case 1

Type: Baseline Test

Baseline Name: baseline1

Baseline File: /Users/jamesbond/Desktop.xlsx

Test Case Requirements

Description: TFT_Cluster_Speedometer_Req_1818.slreqx:TFT_Cluster_Spee


dometer_Req_1818

Document: ../../Desktop/TFT_Cluster_Speedometer_Req_1818.slreqx

Baseline Comparison

Name	Ab s Tol	Re I To I	Lea d Tol	La g To I	Ma x Diff	Data Type 1	Unit s 1	Samp le Time 1	Data Type 2	Unit s 2	Samp le Time 2	Inter p	Sync	Lin k to Plo t
Out_VehicleSpeed_Di splay	0	 0 	0		 0 1	fxp_slope_bias_sc aling	 		ufix16_Sp		0.01	zoh	unio III n	<u>Lin</u> <u>k</u>

Name	Ab s Tol	Re I To I	Lea d Tol	La g To I	Ma x Diff	Data Type 1	Unit s 1	Sampl e Time 1	Data Type 2	Unit s 2	Sampl e Time 2	Inter p	Sync
Out_VehicleSpeed_Dis play	I I I 0 I	0 1	0 1	1 1 1 0 1	0	fxp_slope_bias_scal ing			ufix16_Sp 01		0.01	zoh	l unio l n



Back to Report Summary Back to Criteria Results

Simulation

System Under Test Information

Model: Vehicle_Speedometer_Module

Release: Current

Simulation Mode: normal

Override SIL or PIL Mode: 0

Configuration Set: Configuration

External Input Name: input

External Input File: /Users/jamesbond/Desktop/nv.xls

Start Time: 0 Stop Time: 10

Checksum: 1959822732 1146748841 1462711833 2177022575

Simulink Version: 10.5 Model Version: 1.43

Model Author: jamesbond

Date: Sun Apr 02 13:49:32 2023

User ID: jamesbond

Model Path: /Users/jamesbond/Desktop/TFT Speedometer

Module/Vehicle Speedometer Module.slx

Solver Name: FixedStepDiscrete

Solver Type: Fixed-Step

Fixed Step Size: 0.01

Simulation Start Time: 2023-04-02 21:55:39 Simulation Stop Time: 2023-04-02 21:55:53

Platform: MACI64

Simulation Logs:

Inconsistent numeric values for port 1 of '<u>Vehicle Speedometer Module/In AuxFilt SpeedValue</u>': Output value (uint8(0)) at major time step 0 is less than minimum (uint8(1)) from 'Vehicle Speedometer Module/In AuxFilt_SpeedValue'

Inconsistent numeric values for port 1 of 'Vehicle Speedometer Module/Avg VehicleSpeed': Output value (fi([],0,16,0.01,0,'int',uint16(29000))) at major time step 1.05 is greater than maximum (fi([],0,16,0.01,0,'int',uint16(28000))) from 'Vehicle Speedometer Module/Avg VehicleSpeed'

Back to Report Summary