

1Rear Storage Box Mod..pdf

Reference	SSM66537
Models	F-TYPE / X152
Title	Rear Storage Box Door Opens When Locking Vehicle
Category	Body
Last modified	11-Jul-2013 00:00:00
Symptom	107000 Interior Trim
	<p><u>Issue:</u> The lockable rear interior storage box (cubby box) door may open when locking the vehicle doors.</p> <p><u>Cause:</u> There are two separate causes depending on the VIN range. Vehicles built up to K03276 could have an issue with the storage box latch. Vehicles from K03277 to K03880 may be having the storage box lid preloaded by the left hand rubber stop for the storage box door.</p>
Content	<p><u>Action:</u> For vehicles up to VIN K03276 please submit a Technical Assistance Request for further assistance. For vehicles from VIN K03277 to VIN K03880 remove the rubber stop on the left hand side of the rear storage box and cover the hole with suitable felt tape. See attached picture.</p>