



AJ20P4 Check Engine MIL

2018 onwards Discover Sport, RR Evoque, RR(PHEV), RR Sport (PHEV), RR Velar, F TYPE, F PACE, E PACE, XE, XF equipped with AJ20P4

Customer Voice:

- The Check Engine MIL is on.

Technical Description:

- Multiple DTCs may be present.
- OV is identified on a 5V reference signal line.

Status:

- Inspect the wire harness for the coolant pump.
- Damage may have occurred during a previous repair, so the pulley may need to be removed to perform a full inspection.
- Make repairs as necessary.



PRINTED COPIES ARE UNCONTROLLED