

SOTA UPDATES

NGI 21A, PIVI 30.2



	NGI	PIVI
Affected Models	2016 – 2022 Discovery, Discovery Sport, Evoque, Velar, Range Rover Sport, Range Rover, E-Pace, F-Pace, I-Pace, XE, XF, F-type, XJ with NGI	20-22MY Defender, 21-22MY Discovery Sport, Discovery, Evoque, Velar, F-PACE, E-PACE, I-PACE, XF with PIVI
Software version	21B- NGI	IP31 (3.0.0)
Total Complete	10,591	64,445
SOTA Campaign Launch Date	15-November 2021	8-November 2021
Notes	<p>21B Resolves the voice guidance concerns when using Apple CarPlay.</p> <p>*Additional enhancements are listed in the Release notes available on TOPlx</p>	<p>IP31 Includes numerous bug fixes, and also activates wireless CarPlay and Android Auto functionality to all PIVI vehicles.</p> <p>*Release notes available on TOPlx *Customer email has been sent advising of new features *Retailer bulletin NAS 21.11.008 released on GRP</p>



PRINTED COPIES ARE UNCONTROLLED