

# Latest Vehicle Concern Fixes

## POWERTRAIN



### AJ20P4 Cooling Fan Noise

18MY Onward F PACE, F TYPE, XE, XF, E PACE, Discovery Sport, RR Evoque, RR Velar equipped with AJ20P4

#### Customer Voice:

- There is a noise from the front of the car.

#### Technical Description:

- The engine cooling fan is running at 100% duty cycle.

#### Status:

- An issue has been identified with the released software that may lead to unsuccessful downloads.
- Field Service Actions N451 and H291 have been suspended until the issue with the software can be rectified.
- JLRTB02030NAS1 is currently under discussions for revision and has been removed from publication in TOPIx.

