

## CAMPAIGN LAUNCH STATUS SERVICE ACTIONS AND RECALLS -STATUS UPDATES



SERVICE ACTIONS N451 AND H291	
EFFECTIVE JUNE 10 <sup>TH</sup> 2020 . THESE 2 CAMPAIGNS HAVE BEEN SUSPENDED	IT HAS BEEN DETERMINED THAT THE NEW SOFTWARE IS MISSING CERTAIN PARTS OF THE CALIBRATION WHICH WILL RESULT IN UNSUCCESSFUL DOWNLOADS
VEHICLES MAY CONTINUE TO BE RETAILED PENDING CAMPAIGN RE-ISSUE	VEHICLES WILL NOT FLAG OPEN IN DDW, TOPIX AND BBSS
RE-LAUNCH TIMING	UPDATED PATHFINDER SOFTWARE IS EXPECTED TO BE AVAILABLE BY JULY 10 <sup>TH</sup> , 2020. PLEASE REVIEW SSM'S 74857 (JAGUAR) AND 74756 (LAND ROVER) FOR REPAIR INFORMATION PRIOR TO CAMPAIGN RE-LAUNCH.
RECALL H283 XF FUEL TANK FLANGE LEAKING	
SAFETY RECALL H283 10MY XF WITH 4.2L V8 ENGINE FUEL TANK FLANGE LEAKING	THIS RECALL LAUNCH HAS BEEN DELAYED BY A PARTS PRODUCTION STOPPAGE DUE TO A RECENT SUPPLIER FACTORY SHUT DOWN. LAUNCH IS NOW PLANNED FOR THE WEEK OF JULY 6TH