

MPD UPDATE
Powertrain



<p>F-TYPE equipped with AJ133 engine idle instability</p>	<p>Problem Description:</p> <ul style="list-style-type: none"> The customer experiences a dip in engine RPM which may result in a flashing "D" indicator and possibly an engine stall condition. The engine can be restarted on the next key cycle. <p>Current Status:</p> <ul style="list-style-type: none"> A revised PCM calibration is currently under development and expected to be available in Pathfinder in early December 2019. <p>Recommended Actions:</p> <ul style="list-style-type: none"> Diagnose/Rectify DTCs that are stored. Raise a TA and include flight recorder data for analysis. 		<p>KPI's</p> <table border="1"> <tr> <td>Total VIN Count</td> <td>Status</td> </tr> </table>	Total VIN Count	Status	<p>Issue Owner</p> <p>Matt Priestner</p>
Total VIN Count	Status					

