

SOTA UPDATES

NGI 21A, PIVI 30.2



	NGI	PIVI
Affected Models	2016 – 2022 Discovery, Discovery Sport, Evoque, Velar, Range Rover Sport, Range Rover, E-Pace, F-Pace, I-Pace, XE, XF, F-type, XJ with NGI	20-22MY Defender, 21-22MY Discovery Sport, Discovery, Evoque, Velar, F-PACE, E-PACE, I-PACE, XF with PIVI
Software version	21A- NGI	IP31 (3.0.0)
Total Complete	1,685,003 globally completed	500 in initial cohort (8-Nov)
SOTA Campaign Launch Date	5-May 2021	8-November 2021
Notes	<p>21A SOTA campaign suspended due to an issue where CarPlay voice guidance would not work for navigation apps, such as Waze.</p> <p>21B will resolve this issue and release is on hold due to issues found during validation</p> <p>*Release notes are available on TOPIx</p>	<p>IP31 Includes numerous bug fixes, and also activates wireless CarPlay and Android Auto functionality to all PIVI vehicles.</p> <p>*Release notes will be available on TOPIx</p>