

Reference	SSM65737
Models	F-TYPE / X152
Title	Date Format - Does not retain MM/DD/YYYY setting
Category	Electrical
Last modified	06-Jun-2013 00:00:00
Symptom	204000 Instrumentation
<p>Concern</p> <p>When attempting to set the date format within the Touch Screen, a customer may not be able to select and retain the MM/DD/YYYY format.</p>	
<p>Cause</p> <p>The software in the instrument cluster may not be at latest level.</p>	
<p>Correction</p> <p>If this concern has been identified by a customer, the software in the Instrument Cluster will need to be updated. The, <i>Configure Existing - Instrument Cluster Control Module</i>, routine in SDD will need to be performed. SDD with DVD134.03 and calibration file 135 loaded or later will be required. EX53-14C026-AG, or Content later, is the software level which will contain the fix for this concern.</p>	
<p>Affected VIN range</p> <p>K00001 - K00734</p> <p>*K00735 and later build vehicles will have the correct software level.</p>	
<p>NOTE: The date is only viewable from the <i>Settings > Time / Date</i> menu. The date will not be displayed in the Instrument Cluster before or after the Instrument Cluster software update. This is the intended design intent.</p>	
<p>NOTE: The concern has already been rectified in the build plant. The concern will only affect a small number of F-Types. A further bulletin communication is expected before end June 2013.</p>	