

Reference	SSM37157
Models	S-TYPE / X200 X-TYPE / X400 XF / X250 XJ / X350 XJ V8 / X308
Title	LED Trailer light boards
Category	Electrical
Last modified	12-Aug-2010 00:00:00
Symptom	203000 Basic Electrical
Content	<p>Please note that as yet Jaguar vehicles with bulb failure monitoring systems for trailer light failure sensing are not compatible with trailer light boards that have LED based illumination. As a result of this the LED lighting on the trailer board may flicker during the sensing function. (This issue will also present itself if fitting LED rear light clusters available in the aftermarket(Non-Jaguar approved Accessory)</p> <p>Based upon this we recommend that trailer light boards with standard incandescent bulbs only are fitted.</p>