

2018.0 RANGE ROVER (LG), 415-01

IMC (INFOTAINMENT MASTER CONTROLLER) (G2935050)

INCONTROL© TOUCH PRO 21B

Software Release Date: 2021-11-16

SOFTWARE RELEASE NOTES

NOTE

THE SOFTWARE UPDATE FOR THIS RELEASE NOTE IS AVAILABLE ON THE FOLLOWING SYSTEMS -

- Software Over The Air (SOTA)

INTRODUCTION

This document contains the following information:

New features included in this release

- [Baidu CarLife](#)

Issues fixed in this release

- [4x4i Screen](#)
- [Apple CarPlay](#)
- [Instrument Panel Cluster Control Module B \(IPCB\)](#)
- [Compass View](#)
- [Hotspot Connectivity](#)
- [DVD](#)
- [Electric Vehicle \(EV\) Charging](#)
- [Media Player](#)
- [Steering wheel controls](#)
- [Rear Seat Entertainment \(RSE\)](#)
- [Self-Learning Car](#)
- [Settings](#)
- [System](#)
- [Timed Climate](#)

NEW FEATURES INCLUDED IN THIS RELEASE**(CHINESE I-PACE ONLY)****BAIDU CARLIFE**

- Baidu CarLife feature is now available
-

ISSUES FIXED IN THIS RELEASE**4X4I SCREEN**

- The screen will show the correct pitch and roll angle of the vehicle

APPLE CARPLAY

- Turn by turn voice guidance will now work in Apple CarPlay Maps

INSTRUMENT PANEL CLUSTER CONTROL MODULE B (IPCB)

- When playing FM radio source the IPCB will no longer show a Gray background

COMPASS VIEW

- The north indicator "N" in compass view will be updated when there is a theme change

HOTSPOT CONNECTIVITY

- Improved stability of Hotspot functionality

DVD

- Improved stability of DVD functionality

ELECTRIC VEHICLE (EV) CHARGING

- Charging port will flash green instead of blue when charging

MEDIA PLAYER

- Album art is now available in media library

STEERING WHEEL CONTROLS

- Improved stability of Steering wheel control functionality after using rear media feature

REAR SEAT ENTERTAINMENT (RSE)

- Video can now be played on both rear screens at the same time
- In the rear right screen, the text for passenger and driver seats are no longer swapped in German

SELF-LEARNING CAR

- Improved stability of self learning car mode

SETTINGS

- In the Chattanooga region in USA near the Eastern/Central time zone border the infotainment time is now no longer 1 hour behind in Auto mode
- Telematic Control Unit Module (TCU) installation popup will no longer display message in English while the language is set to Chinese

SYSTEM

- Improved stability on start up

TIMED CLIMATE

- Timed climate icon will no longer appear on Interactive Display Module 'A' (IDMA) while vehicle is in motion

K N O W N I S S U E S I N T H I S R E L E A S E

THERE ARE NO KNOWN ISSUES IN THIS SOFTWARE RELEASE.