

TECHNICAL TOPICS

POWERTRAIN



AJ20-P4 engine- Coolant leak from Thermostat	18- 22MY: E-PACE/F-TYPE 17-22MY: F-PACE/XE/ XF
<p>Customer Voice:</p> <ul style="list-style-type: none">- Thermostat coolant leak - Evident fluid leak from the engine compartment and the "Coolant Level Low" warning message may be on the cluster <p>Technical Description:</p> <ul style="list-style-type: none">- MIL might be associated with P0128 DTC- Evidence of a leak from thermostat.- No evident fresh leak but only dried up coolant deposit is seen on the body of the thermostat <p>Status:</p> <ul style="list-style-type: none">- Check the coolant pipes on top of / around the thermostats for any leak / damage pipes which has possibility of leaking coolant to the thermostat body.- New Pinpoint test has been added to TOPIx <p>Refer to TOPIx section 303-03a pinpoint test F</p>	 E300398



PRINTED COPIES ARE UNCONTROLLED