



Latest Vehicle Concern Fixes

POWERTRAIN

Check Engine MIL with DTC P0299-00 stored	18MY onward RR Evoque, Discovery Sport, F-PACE, F-TYPE, XE, XF, E-PACE equipped with AJ20P4
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• The Check Engine MIL is on.• There is a lack of power from the engine. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• The DTC P0299-00 is stored in the PCM. <p><u>Status:</u></p> <ul style="list-style-type: none">• Perform diagnosis steps outlined in the TOPIx Workshop Manual for the DTC stored.• If the turbo is identified as the root cause, we are seeking parts for analysis.• Create an EPQR and include a session file, the details and results of the diagnostic steps performed, and contact information to support PRR.	

