

TECHNICAL TOPICS

BODY/CHASSIS



Convertible Top Inoperative (Stuck Closed)

14 – 22MY F-TYPE

Customer Voice:


- A customer may report that the convertible top does not open from the closed position.

Technical Description:

- This may be caused by a number of potential root causes.

Status:

- The procedure to manually open the convertible top that is stuck in the closed position to allow service work to be conducted has now been added to the TOPIx Workshop Manual.
- Please refer to Workshop Manual > Section 501-08 Folding Top > General Procedures > Folding Top Manual Stow Operation.
- This procedure requires two people working together to slowly move the top to the open position in an even manner under constant pressure.



E293409
Manually open the folding top.



PRINTED COPIES ARE UNCONTROLLED