

TECHNICAL TOPICS

ELECTRICAL



<p>NGI 21A Update Suspended</p> <p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- IMC Update 21A will not install <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- An issue was identified with the 21A IMC Update which prevented the vehicles from completing the installation <p><u>Status:</u></p> <ul style="list-style-type: none">- The NGI 21A IMC Update was re-deployed via TOPIx only on 19-Apr-21- 21A will provide:<ul style="list-style-type: none">- Improved Infotainment stability- Solution for CarPlay freeze when cable is removed- Additional enhancements to support Audionostics- Please refer to release notes for additional details in TOPIx (Documents>>Software)	<p>16 - 21MY E PACE, F PACE, I PACE, F TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport equipped with NGI</p> 
---	--

