


TECHNICAL TOPICS

POWERTRAIN



Transmission leak diagnosis with trace powder	MY20 -MY22 Defender, RR Evoque , RR Velar, Disco Sport, Discovery, RR Sport, Range Rover, XF, E-Pace, F-Pace, XE, F-Type.
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- Transmission fluid leaks <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- The proper way to diagnose a transmission fluid leak <p><u>Status:</u></p> <ul style="list-style-type: none">- Thoroughly coat the potential leak locations using a suitable leak detector spray.- Run the vehicle up to operating temperature, raise the ramp and use a suitable inspection lamp to identify the source of the transmission oil leak.- Once the source of the leak has been identified, refer to the relevant technical bulletin or refer to the relevant section of the workshop manual and repair as necessary <p>Refer to Topix section 307-01a</p>	 A close-up photograph of a car's transmission housing. A blue rectangular highlight is applied to the lower left side of the housing, specifically around a flange where various hoses and bolts are attached. This highlights the area where a leak might occur during the diagnosis process.



PRINTED COPIES ARE UNCONTROLLED