

# TECHNICAL TOPICS

## ELECTRICAL



### Navigation Voice Control

20-21MY L663, 21MY Discovery Sport, Discovery, Evoque, Velar, F-PACE, E-PACE, I-PACE, XF

#### Customer Voice:

- Navigation Voice Control does not function

#### Technical Description:

- System language incorrectly set to “UK English” not “US English”

#### Status:

- If a customer has issues with the Navigation voice commands, please check the System language setting first. If the system language is set to “UK English” the Navigation voice commands will not function.
- The “Feedback Accent” can be set to British English if the customer desires a British accent from voice prompts.
- Please verify the system language is set to, “US English” when completing step 11 of the PDI (Configure the vehicle to market and set Customer/Retailer options.)



PRINTED COPIES ARE UNCONTROLLED