

TECHNICAL TOPICS

ELECTRICAL



Quiescent Drain Concerns

Customer Voice:

- Customer reports numerous concerns, such as low battery warning message on startup, or vehicle will not start after sitting.

Technical Description:

- Battery Quiescent Drain can be occurring from many different issues

Status:

- Due to the often-difficult nature to diagnose Quiescent Drain concerns, TOPIx section 414-01 – Flat Battery Diagnostics is consistently being updated to support with accurately pin-pointing the source of the quiescent drain.

17-22MY Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport, XE, XF, F-PACE, F-TYPE, E-PACE

