

Reference	SSM66117
Models	F-TYPE / X152
Title	F-Type Chassis/Body Noises
Category	Chassis
Last modified	06-Jun-2013 00:00:00
Symptom	304000 Suspension System
Content	<p><u>Issue:</u> Noises/knocking from the chassis/body</p> <p><u>Cause:</u> Under investigation</p> <p><u>Action:</u> When investigating a noise complaint that is believed to be emanating from the chassis or body, we would ask that you attempt to capture a sound recording and report the case by either an EPQR or a TA before disassembling any components. If you are unable to record the noise, please contact the Technical Helpline for guidance. Please provide full details of the driving conditions when the noise is heard. If noted when crossing speed bumps please provide dimensions on size/height of the speed bump as well as road speed. This will enable engineers to reproduce the conditions to assist in root cause determination</p>