

# TECHNICAL TOPICS

## ELECTRICAL



### Infotainment Updates

16 – 20MY E PACE, F PACE, I PACE, F TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport, & Defender equipped with InControl Touch Pro or Pivi

Activity	Purpose	Vehicles	Completion	Notes
H251 & N377 - InControl Touch Pro Updates	To update InControl Touch Pro vehicles to the latest IMC software level, and to enable SOTA updates moving forward.	16–18MY Cross Car Line	Land Rover 76% completed +2 Jaguar 80% completed +1	Update performed via Pathfinder / SDD at retailer to bring the vehicle to a SOTA capable level. NDU for SDD has been released 3-Sep
IMC 20C1 Software Release	Provide additional bug fixes and infotainment stability 20C1 –Resolve X152 & X351 missing InControl Apps & RSE SOTA improvements	16-20MY Cross Car Line	49,900 Successful Updates	20C1 supersedes 20C 15-Jan-21
TCU v19.2	Provide additional stability for SOTA updates and resolve Remote App concerns.	16-20MY Cross Car Line	12,360 Customer Updates 3,270 Updates via TOPIx	Customer Update for TCU v18.2 TOPIX Update for TCU v14.2 – Fix on Fail
Pivi IP27.1 (OS 2.0.6)	Latest update for Pivi to provide improvements and address known issues.	20MY L663 Defender	7,255 Successful Updates	OS 2.0.6 Launched to customer 27-Nov-20



PRINTED COPIES ARE UNCONTROLLED