

Reference	SSM68217
Models	F-TYPE / X152
Title	Fuel Filler Flap
Category	Body
Last modified	13-Sep-2013 00:00:00
Symptom	108000 Ext. Trim/Accessories
	<p><u>Issue:</u> Fuel Filler Flap not lockable.</p>
Content	<p><u>Cause:</u> Dealers via ePQR have questioned if the fuel filler flap should be lockable?</p>
	<p><u>Action:</u> Engineering have clarified that on F-Type in the North American market it is a Non lockable item.</p>