


BEST PRACTICES – REAR BRAKE PAD WEAR

- There have been several FRED submissions for a customer allegation of a rear brake warning being illuminated on the instrument cluster.
- If the rear brakes are confirmed to be low, please capture photos of the brake lining thicknesses and indicate the numerical measurements in your statement.
- It is important that the submission attachments are clear, as this will justify the gateway for approval based on evidence of a manufacturing defect.



Photos of the brake lining thicknesses