

Latest Vehicle Concern Fixes



Satellite Radio (SDAR) Favorites replaced by “2500”	16MY – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System
Customer Voice: <ul style="list-style-type: none">InControl Touch Pro customer may experience a Satellite radio (SDAR) favorite missing and replaced with a “2500” status.	
Technical Description: <ul style="list-style-type: none">Potential internal corruption of Satellite radio (SDAR) favorite.	A screenshot of the InControl Touch Pro interface titled "SIRIUS XM FAVORITES" at 10:12. The screen shows a list of five entries, each consisting of a star icon, the number "2500", and a file path: "hb/channelart/l00091T00.png", "hb/channelart/l00557T00.png", "hb/channelart/l00025T00.png", "hb/channelart/l00044T00.png", and "hb/channelart/l00565T00.png". There are navigation icons at the bottom of the screen.
Status: <ul style="list-style-type: none">Please reference bulletins and utilize instructions:<ul style="list-style-type: none">LR – SSM 74454 has been released on June 13th 2019JAG – SSM 74455 has been released on June 13th 2019	

