

Reference	SSM39290
Models	S-TYPE / X200 X-TYPE / X400 XJ / X350
Title	Audio Connectivity Module (ACM)
Category	Electrical
Last modified	03-Dec-2008 00:00:00
Symptom	205000 Electrical Accessories
Content	Help with diagnosing any issues / faults can be gained by phoning your Jaguar Technical HelpLine

To help us with our analysis please ensure that you have the following information available before contacting Jaguar Cars:

VIN
Vehicle Type and model
Date ACM was fitted to the vehicle
A concise description of the problem and its regularity of occurrence
The software level and build date code of the ACM fitted.
work performed on the vehicle to solve the problem to date
Is this a problem seen immediately after installation
Is it permanent
How does the problem demonstrate itself
What i-pod is the customer using...etc

Many Thanks for your help