

# TECHNICAL TOPICS

## POWERTRAIN



### AJ20-P4 engine- Coolant leak from Thermostat

MY18- MY22: E-Pace/F-Type  
MY17-MY22: F-Pace/XE/ XF

#### Customer Voice:

- Customer concern will be a coolant leak or low coolant light on

#### Technical Description:

- MIL might be associated with P0128 DTC
- Evidence of a fresh leak [not gross] from thermostat.
- No evident fresh leak but only dried up coolant deposit is seen on the body of the thermostat

#### Status:

Check the coolant pipes on top of / around the thermostats for any leak / damage [pipes which has possibility of leaking coolant to the thermostat body]

Please raise an EPQR and attach all the information identified plus the session file(s), photograph(s) and video(s)

- Screenshot of the latest DTCs / warning light
- Share video evidence of fresh leak
- Check if the housing is sitting properly

Refer to SSM75559



PRINTED COPIES ARE UNCONTROLLED