

Latest Vehicle Concern Fixes

POWERTRAIN



FEAD tensioner	17MY Onward F PACE, F TYPE, XE, XF, XJ, Discovery, Range Rover, RR Sport, RR Velar equipped with AJ126
<p>Customer Voice:</p> <ul style="list-style-type: none">There is a noise from the engine which can vary from a squealing to rattling/bearing noise. <p>Technical Description:</p> <ul style="list-style-type: none">This topic is under investigation. <p>Status:</p> <ul style="list-style-type: none">Inspect for evidence of oil leaks from the vehicle and note the source with pictures.Take a sound recording of the noise.Raise an EPQR and include the sound recording and pictures to support the investigation.SSM74810 and SSM74811 have been published on the topic.	

