

Nyree Hinton
616 Masselin Ave, Apt 210
Los Angeles, CA 90036
nyreehinton@gmail.com
Direct: 732-979-6264

Re: Appeal of Case JAG2501941 - Hinton v. Jaguar (VIN:
SAJDD1GX4LCK67497)

BBB AUTO LINE

Appeals Division

1676 International Drive, Suite 550
McLean, VA 22102-3999
Phone 800.955.5100
Fax: 703.247.9700

cc' California Attorney General's Office

cc' California Department of Consumer Affairs (Reference #61C7-W8NBZH)

cc' Jaguar Land Rover North America, LLC

CA Repurchase Request: Case #8001315826
VIN: SAJDD1GX4LCK67497
BBB Auto Line Case #JAG2501941

Email: nyreehinton@gmail.com

Date: February 3, 2025

Dear Ms. Ortiz,

This letter serves as my formal appeal of BBB AUTO LINE's ineligibility determination due to its reliance on the recent California Supreme Court decision in **Rodriguez v. FCA US, LLC, S274625 (2024)**. While I respect the program's adherence to the Song-Beverly Consumer Warranty Act (the "Act"), I contend that the denial misapplies Rodriguez and overlooks the continuing obligations of Jaguar Land Rover North America, LLC ("JLRNA") under federal and state warranty laws where active manufacturer warranties remain in effect. Furthermore, this appeal highlights compliance with the Arbitration Rules, particularly Rule 3 (Jurisdiction of BBB AUTO LINE), and demonstrates that the exclusions listed under "Claims That Will Not Be Arbitrated" do not apply to my case.

First, pursuant to **Rule 3(a)**, my claim arises under Jaguar Land Rover North America's (JLRNA) written warranty for my 2020 Jaguar F-Type, which was active at the time of my purchase on September 17, 2024, which **JLRNA continued to honor through multiple repair attempts**. JLRNA's acceptance of warranty obligations and performance of repairs under warranty terms establishes their ongoing duty to provide warranty coverage per 15 U.S.C. § 2310(d). JLRNA's warranty obligations continue regardless of subsequent ownership, as established in *Duick v. Toyota Motor Sales, U.S.A., Inc.*, 198 Cal.App.4th 1316 (2011). This creates an independent basis for BBB Auto Line jurisdiction separate from Song-Beverly Act eligibility.

Second, **Rule 3(b)** grants jurisdiction to BBB AUTO LINE for disputes under the Magnuson-Moss Warranty Act (15 U.S.C. §§ 2301-2312). Per the Magnuson-Moss Act, manufacturers like JLRNA cannot disclaim their obligations to repair or replace defective warranted goods when "substantial nonconformities" cannot be rectified after a reasonable number of repair attempts. My case squarely fits this criterion: the vehicle's electrical and drivetrain issues were presented for repair multiple times within the warranty period (documentation included) without resolution, as required under 15 U.S.C. § 2304(a)(4).

In **Rodriguez v. FCA US, LLC**, the California Supreme Court clarified that a vehicle purchased with an unexpired manufacturer's new car warranty does not qualify as being sold "*with a manufacturer's new car warranty*" under Song-Beverly unless the new car warranty was issued contemporaneously with the

sale. However, the Court expressly limited its ruling to eligibility for Song-Beverly “new vehicle” remedies, such as buyback or replacement, and **explicitly preserved other warranty rights where defects arise within an active manufacturer’s warranty period**. Per Rodriguez, “[T]he decision does not eliminate a buyer’s ability to pursue other remedies when defects manifest under a manufacturer’s warranty,” including claims under the **federal Magnuson-Moss Warranty Act (15 U.S.C. §§ 2301–2312)** and related California Commercial Code provisions.

In addition to the federal warranty, California state law provides additional protections for defects arising in vehicles sold as “used” but still covered under active warranties. **California Commercial Code § 2313** preserves my right to enforce express warranties made by the manufacturer, and **Civil Code § 1795.5(c)** extends implied warranty protections to subsequent buyers of vehicles covered by a manufacturer’s warranty.

Given the vehicle’s repair history under Jaguar’s transferable warranty and the continued presence of unresolved defects that impair its use, value, and safety, I respectfully request that the BBB Auto Line arbitrator reverse the eligibility determination and exercise jurisdiction over this matter under federal warranty law and JLRNA's express delegation of warranty disputes to this forum as the platform remains the most efficient and equitable venue to resolve this ongoing dispute.

Respectfully,
Nyree Hinton



cc' California Department of Consumer Affairs
Consumer Information Center
1625 North Market Blvd., Suite N-112
Sacramento, California 95834
dca@dca.ca.gov

cc' Jaguar Land Rover North America, LLC
Dispute Resolution Agent
100 Jaguar Land Rover Way, Mahwah
New Jersey 07495 USA. If JLR USA
jagweb1@jaguarlandrover.com
privacy@jaguarlandrover.com

National Highway Traffic Safety Administration
U.S. Department of Transportation
1200 New Jersey Avenue, SE
Washington, D.C. 20590
888-327-4236
John Donaldson: Assistant Chief Counsel
john.donaldson@dot.gov

Subject: CASE:[8001315826]: CA Repurchase Request

Date: Thursday, January 30, 2025 at 12:25:30 PM Pacific Standard Time

From: jagweb1@jaguarlandrover.com <jagweb1@jaguarlandrover.com>

To: nyreehinton@gmail.com <nyreehinton@gmail.com>

*Due to the nature of this case, we want to ensure proper documentation on both ends, and request ***ALL communication pertaining to your repurchase request be *VIA EMAIL.***

- *By replying to this email, without changing the subject line, it will ensure all documents and communication are attached to this case accordingly.**

My name is Lauren and I am the Process Specialist assigned to your request for repurchase. I am truly sorry to hear about your experience thus far and I am writing to inform you of Consumer Affairs Determination.

This is in response to your 11/14/24 request for repurchase of your 2020 Jaguar F-PACE with VIN SAJDD1GX4LCK67497 under the California Song-Beverly Consumer Warranty Act.

- **After evaluating this matter in good faith, Consumer Affairs does not believe that your vehicle qualifies for repurchase or replacement.**

We highly advise returning to the retailer if you experience any concerns with your vehicle.

- *If you experience any re-occurring concerns and return to the retailer, we recommend that you request the Retailer involve JLRNA Technical Assistance & Engineering Team in the vehicle inspection to investigate any re-occurring concerns, and ensure all avenues for repair is met.*

JLRNA will continue to honor the terms of the New Vehicle Limited Warranty Agreement, if applicable, with respect to future repairs.

--

Under California Civil Code § 1793.2(d), a manufacturer is only obligated to repurchase or replace a vehicle for failure to repair after a reasonable number of repair attempts if a vehicle has a nonconformity that has not been repaired after a reasonable number of repair attempts and that nonconformity substantially impairs the use, value or safety of the vehicle.

Given Jaguar Land Rover North America, LLC's good faith belief that the vehicle does not qualify for repurchase under California Civil Code § 1793.2 (d), we respectfully decline your

request for repurchase or replacement.

At this time your case has been closed.

[You may reply to this email thread, without altering the subject line, if you have any questions or concerns]

Thank you for your understanding,

Lauren S

Process Specialist

T: 1-800-637-6837

F: 888-410-0938

E: jagweb1@jaguarlandrover.com

Jaguar Land Rover North America, LLC

jaguarusa.com | landroverusa.com

100 Jaguar Land Rover Way, Mahwah, NJ 07495

NYREE HINTON

INVOICE

Invoice #: 908960

Jaguar Land Rover South Bay

3233 Pacific Coast Highway
Torrance, CA 90505-6613
Phone: (310) 798-0550

Tag #: 124 =

Home: Bus: Customer #: 7913668

BAR REG. # AJ229534 E.P.A.# CAD981683915

Cell: 732-979-6264 Email: na@na.com/home Service Advisor: 7814 JOEL CRUZ

COLOR		YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN	MILEAGE OUT
		20	JAGUAR F-TYPE		SAJDD1GX4LCK67497			23072	23073
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN20 D			18:00 18OCT24		0.00	CASH	02OCT24	17:59 01OCT24	14:36 02OCT24

OPTIONS: DLR:0146

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty.

We also offer high quality non-OE parts that are suitable for your vehicle and fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP*." These non-OE (AP*) parts are not sourced from the vehicle's manufacturer or covered by its warranty. Non-OE parts come with a limited warranty backed by AutoNation and/or the parts manufacturer.

A CUSTOMER STATES DRIVERS SIDE WINDOW DOES NOT ROLL UP.

CAUSE:

None CUSTOMER STATES DRIVERS SIDE WINDOW DOES NOT ROLL UP.

8784 WJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: (N/C) 0.00
23072 VERIFIED CUSTOMER CONCERN FOUND WINDOW SWITCH NOT WORKING. CHECK SEAT SWITCH AND IT ALSO NOT WORKING SO IS THE LOCK AND UNLOCK SWITCH NOT WORKING. CHECK FUSE AT THE REAR JUNCTION BOX FOR FRONT LEFT DOOR MODULE AND FUSE WAS BLOWN. CHECK POWER WIRE FOR 12 VOLTS AND GOT 12VOLTS FROM JUNCTION BOX TO LEFT DOOR CONTROL MODULE. CHECK GROUND FROM JUNCTION BOX TO LEFT DOOR MODULE AND THERE WAS A SHORT TO GROUND. REPAIR GROUND WIRE AND REPLACE FUSE AND FUSE DIDN'T BLOW AGAIN. NOW GOT POWER TO LEFT FRONT DOOR MODULE AND WINDOW SWITCH IS NOW WORKING AS IT SHOULD.

B MULTI-A Customer requested to have Multi Point Inspection performed during this visit

MULTI-A MULTI-A Customer requested to have Multi Point Inspection performed during this visit

8784 CR 0.00 0.00

GTIRE ALL TIRES AT 9/32ND ... MINIMUM IS 3/32ND) 0.00 0.00

8784 CR 0.00 0.00

YBK FRONT BRAKES AT 6MM ... REAR BRAKES AT 4MM ... MINIMUM IS 3MM) 0.00 0.00

8784 CR 0.00 0.00

GBATT BATTERY TESTS GOOD 0.00 0.00

8784 CR 0.00 0.00

DSRB Declined Rear Brake Replacement 0.00 0.00

8784 CR 0.00 0.00

DSSM Declined Scheduled Maintenance 0.00 0.00

8784 CR 0.00 0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

23072 PERFORMED MPI

NOTICE TO CONSUMERS: PLEASE READ IMPORTANT INFORMATION ON ATTACHED PAGES.

CALL/TEXT AUTHORIZATION: YOU HEREBY AUTHORIZE US TO MAKE RECURRING CALLS, TEXTS, AND TRANSMIT VOICEMAILS TO YOU AT YOUR PHONE NUMBER(S), INCLUDING BY USE OF AN AUTOMATED SYSTEM, REGARDING SALES AND/OR SERVICE OF YOUR VEHICLE. YOU UNDERSTAND YOUR AGREEMENT IS NOT A CONDITION OF PURCHASING GOODS OR SERVICES AND YOU MAY OPT OUT YOUR PHONE NUMBER(S) BY NOTIFYING YOUR SERVICE ADVISOR OR TEXTING STOP TO ANY MESSAGE RECEIVED. MSG & DATA RATES MAY APPLY.

If we receive payments related to the goods or services provided hereunder from any third party (e.g., a check under a Service Contract), you agree that we may retain all such monies as if same was a payment from you and apply such funds to any outstanding indebtedness of yours. You hereby grant us a power of attorney to endorse or otherwise sign your name and to deposit such funds into the dealership's account to carry out the intent of this provision.

By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received for had the opportunity to inspect any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.

I acknowledge notice and oral approval of an increase in the original estimated price.

HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of hazardous waste or substances under California and Federal Law.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

☐ Some Parts Not Returnable

LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

NYREE HINTON

INVOICE

Invoice #: **908960**

Jaguar Land Rover South Bay

3233 Pacific Coast Highway
Torrance, CA 90505-6613
Phone: (310) 798-0550

Tag #: **124 =**

Home: Cell: 732-979-6264 Email: na@na.com/home Bus: Customer #: **7913668** Service Advisor: **7814 JOEL CRUZ** BAR REG. # AJ229534 E.P.A.# CAD981683915

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
	20	JAGUAR F-TYPE			SAJDD1GX4LCK67497			23072	23073
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN20D			18:00 18OCT24		0.00	CASH	02OCT24	17:59 01OCT24	14:36 02OCT24
OPTIONS: DLR:0146									

OPTIONS: DLR:0146

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty.

We also offer high quality non-OE parts that are suitable for your vehicle and fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP." These non-OE (AP*) parts are not sourced from the vehicle's manufacturer or covered by its warranty. Non-OE parts come with a limited warranty backed by AutoNation and/or the parts manufacturer.*

C PERFORM TIRE PRESSURE SERVICE
TPS PERFORM TIRE PRESSURE SERVICE
8784 CR
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00
23072 SET TIRES PRESSURE TO SPEC

ESTIMATE: 0.00 01OCT24 17:59 SA: 7814

*****THE FOLLOWING WORK WAS RECOMMENDED BUT NOT PERFORMED*****
,, DESCRIPTION: PPBPR AutoNation Parts - Aftermarket REAR BRAKE PADS/SHOES
,, REASON DENIED: LAT Customer will have work performed later
,, PERSON CONTACTED: NYREE HINTON
,, COMMENTS: None
,, RECOMMENDED BY: 7814 CRUZ DENIAL ADDED BY: 7814 CRUZ
,, LINE ASSOCIATED: ESTIMATE: 696.70
,, DESCRIPTION: B151A064000 Service - 64,000 Miles
,, REASON DENIED: LAT Customer will have work performed later
,, PERSON CONTACTED: NYREE HINTON
,, COMMENTS: None
,, RECOMMENDED BY: 7814 CRUZ DENIAL ADDED BY: 7814 CRUZ
,, LINE ASSOCIATED: ESTIMATE: 1428.79

NOTICE TO CONSUMERS: PLEASE READ IMPORTANT INFORMATION ON ATTACHED PAGES.

CALL/TEXT AUTHORIZATION: YOU HEREBY AUTHORIZE US TO MAKE RECURRING CALLS, TEXTS, AND TRANSMIT VOICEMAILS TO YOU AT YOUR PHONE NUMBER(S), INCLUDING BY USE OF AN AUTOMATED SYSTEM, REGARDING SALES AND/OR SERVICE OF YOUR VEHICLE. YOU UNDERSTAND YOUR AGREEMENT IS NOT A CONDITION OF PURCHASING GOODS OR SERVICES AND YOU MAY OPT OUT YOUR PHONE NUMBER(S) BY NOTIFYING YOUR SERVICE ADVISOR OR TEXTING STOP TO ANY MESSAGE RECEIVED. MSG & DATA RATES MAY APPLY.

If we receive payments related to the goods or services provided hereunder from any third party (e.g., a check under a Service Contract), you agree that we may retain all such monies as if same was a payment from you and apply such funds to any outstanding indebtedness of yours. You hereby grant us a power of attorney to endorse or otherwise sign your name and to deposit such funds into the dealership's account to carry out the intent of this provision.

By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.

I acknowledge notice and oral approval of an increase in the original estimated price.

DATE

CUSTOMER SIGNATURE

HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of hazardous waste or substances under California and Federal Law.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.
☐ Some Parts Not Returnable

LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

Dealer CAP 2023 CRK Global, LLC (10/23) SERVICE INVOICE TYPE 2 - XCA52C - AUTONATION "LIMITED WARRANTY" - CALIFORNIA - 8974054
Customer Copy

CUSTOMER #: 10012996

825649



INVOICE

JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

PAGE 1

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrla.com

SERVICE ADVISOR: 3391 Danny Sanchez
B.A.R. REG.# ARD303078 EPA# CAL000470554

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23963/23964	T4486
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
30SEP24 DD			17:00 18NOV24		299.00	CASH
R.O. OPENED	READY	OPTIONS:	ENG:2.0_Liter_Supercharged			

15:56 18NOV24 15:32 21NOV24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COOLING SYSTEM CLIENT STATES LOW COOLANT WARNING LIGHT IS ON CLIENT
REQUEST GOOD WILL BE SENT FOR REPAIRS VEHICLE WARRANTY EXPIRED
11/08/24 CLIENT ATTEMPTED TO BRING THE VEHICLE IN ON 11/07/24
BUT WAS UNABLE TO GET AN APPT UNTIL 11/18/24 CRC 8001315826
26 COOLING SYSTEM

40169 ISPJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: (N/C)
23964 REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE
PRESSURE TESTED COOLING SYSTEM FOUND BLEED PIPE FROM EXPANSION TANK
LEAKING COOLANT.

B CUSTOMER STATES RESET ALL TIRE PRESSURES
TP CUSTOMER STATES RESET ALL TIRE PRESSURES

40169 ISPJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: (N/C)
23964 LEFT 37PSI FRONT RIGHT 37PSI REAR LEFT 37PSI REAR RIGHT 37PSI

C COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION
99PJ COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION

40169 ISPJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: (N/C)
23963 mpi MPI AVAILABLE IN MYKAARMA

D I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM MY
VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE RESPONSIBLE FOR
THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE.

CAUSE: I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM
MY VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE RESPONSIBLE
FOR THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE.

100 I HAVE BEEN ADVISED AND I HAVE REMOVED
EVERYTHING OF VALUE FROM MY VEHICLE. I
UNDERSTAND THAT JLR LA WILL NOT BE

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)
Revised Estimate				☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)

☐ Tire pressure check/inflation service was performed.
RF _____ psi LF _____ psi RR _____ psi LR _____ psi
☐ Customer declined tire pressure check/inflation service.

By signing below, you acknowledge that you were notified of and authorized the
Dealership to perform the services/repairs itemized in this invoice and that you received
(or had the opportunity to inspect) any replaced parts as requested by you.

DATE _____ CUSTOMER SIGNATURE _____ INITIALS _____

*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	WASTE DISPOSAL COSTS *	
	TOTAL CHARGES	
	LESS INSURANCE	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

DealerCAP 2022 CDK Global, LLC (04/22) SERVICE INVOICE TYPE 2 - SIZC - "AS-IS/LIMITED WARRANTY" - CALIFORNIA 0609032

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.

CUSTOMER COPY

CUSTOMER #: 10012996

825649



JAGUAR LAND ROVER LOS ANGELES

INVOICE

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrla.com

NYREE HINTON

616 MASSELIN AVE APT 210
Los Angeles, CA 90036

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

PAGE 2

SERVICE ADVISOR: 3391 Danny Sanchez
B.A.R. REG.# ARD303078 EPA# CAL000470554

COLOR		YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
		20	JAGUAR F-TYPE		SAJDD1GX4LCK67497		23963/23964		T4486
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP24 DD			17:00 18NOV24			299.00	CASH	21NOV24	
R.O. OPENED		READY		OPTIONS: ENG:2.0_Liter_Supercharged					
15:56 18NOV24		15:32 21NOV24							

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
RESPONSIBLE FOR THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE.							

999 ISPJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: (N/C) 0.00

E UBER VOUCHER COMPLIMENTARY RIDE SERVICE

UBER UBER VOUCHER COMPLIMENTARY RIDE SERVICE

999 ISPJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: (N/C) 0.00

F** REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE

01 REPLACE EXPANSION TANK TO BLEED PIPE DUE TO
LEAK FROM PIPE

40169 CPL

1 T2R47919 HOSE

1 T2H59152 ANTIFREEZE

PARTS: 132.53 LABOR: 149.50 OTHER: 0.00 TOTAL LINE F: 282.03

23964 REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE
PRESSURE TESTED COOLING SYSTEM FOUND BLEED PIPE FROM EXPANSION TANK
LEAKING COOLANT. USING TOPIX CLOUD, STARTED A NEW FAULT WORK FLOW AND
ACQUIRED RVC 'TYKTIUC0'. REMOVED LEAKING BLEED PIPE AND REFITTED NEW
EXPANSION TANK BLEED PIPE. VACUUM FILLED EXPANSION TANK WITH COOLANT TO
CORRECT LEVEL. AFTER TEST DRIVE NO LEAKS WERE FOUND.

ESTIMATE: 593.62

21NOV24 12:18 SA: 3391

CONTACT:

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	
Revised Estimate	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)		PARTS AMOUNT	
						GAS, OIL, LUBE	
						SUBLET AMOUNT	
						WASTE DISPOSAL COSTS *	
☐ Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi ☐ Customer declined tire pressure check/inflation service. Initials _____						TOTAL CHARGES	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						LESS INSURANCE	
DATE _____ CUSTOMER SIGNATURE _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE _____						SALES TAX	
						PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.

CUSTOMER #: 10012996

825649



INVOICE

JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

PAGE 3

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlra.com



B.A.R. REG.# ARD303078 EPA# CAL000470554
SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23963/23964	T4486	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DD			17:00 18NOV24		299.00	CASH	21NOV24
R.O. OPENED	READY	OPTIONS: ENG:2.0_Liter_Supercharged					
15:56 18NOV24	15:32 21NOV24						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

ESTIMATE: 299.00 18NOV24 15:56 SA: 3391
CONTACT:

VEHICLE COMPLETED 11/21/24



Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	149.50
Revised Estimate	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)		PARTS AMOUNT	132.53
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						GAS, OIL, LUBE	0.00
						SUBLET AMOUNT	0.00
DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE						WASTE DISPOSAL COSTS *	0.00
						TOTAL CHARGES	282.03
						LESS INSURANCE	0.00
						SALES TAX	12.59
						PLEASE PAY THIS AMOUNT	294.62

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.



Outlook

Payment Received for Order Ref # 825649 , Amount \$294.62

From myKaarma Payments <jlrlajlrlaca-jaguarlandroverlos@kaarmadealer.com>

Date Thu 11/21/2024 4:09 PM

To Danny Sanchez <dsanchez@jlrla.com>; payments@kaarya.com <payments@kaarya.com>

Jaguar Land Rover Los Angeles

400 S La Brea Ave
Los Angeles, CA 90036

RECEIPT

Customer Information:

Nyree Hinton

Invoice Details:

Invoice #: 00M2W4ZE2K

Invoice Date: Thursday, November 21, 2024, 04:08 PM

Repair Order/Ref #: 825649

Description of Product/Services

Amount

Service Performed

\$294.62

Payment Details:

Paid On: Thursday, November 21, 2024, 04:09 PM

Payment Type: Chip

Creditcard: XXXXXXXXXXXX2000 Exp: XX/XXXX

Card Type: Amex

Cardholder Name: NA

Approval Code: 479385

Dealer Associate: DANNY SANCHEZ

Cashier: DANNY SANCHEZ

Vehicle Information:

2020 Jaguar F-Type

Tag #: T4486

License Plate:

VIN: SAJDD1GX4LCK67497

THANK YOU!

Customer Signature

Jaguar Land Rover Los Angeles

Processed by myKaarma

Multi-Point Inspection Summary

Thursday, November 21, 2024 03:33 PM

RO# 825649



CUSTOMER INFORMATION

Nyree Hinton

+17329796264, +17329796264

CAR INFORMATION

Jaguar

2020 F-Type

SAJDD1GX4LCK67497

Mileage: 23963

Tag # T4486

SERVICE ADVISOR INFO

DANNY SANCHEZ

(424) 329-5332

TECHNICIAN

Robert Salcido

ORIGINAL CUSTOMER REQUESTS

OTHER

	CUSTOMER STATES RESET ALL TIRE PRESSURES	Original Approved: \$0.00 Total Approved: \$0.00
	COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION	Original Approved: \$0.00 Total Approved: \$0.00
	I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM MY VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE RESPONSIBLE FOR THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE. _____	Original Approved: \$0.00 Total Approved: \$0.00
	UBER VOUCHER COMPLIMENTARY RIDE SERVICE	Original Approved: \$0.00 Total Approved: \$0.00

5 Needs Immediate Attention

UNDER HOOD: FLUIDS AND FILTERS

 Inspect air cleaner element at 15k or 1 year intervals Replace the Cabin Air Filter CONTAMINATED RENEW	Repair Estimate: \$183.03
---	---------------------------

BRAKES

 Brake Linings Thickness - Rear Rear Pads - 3mm Replace Rear Brake Pads and Rotors DUE TO LOW PADS AND WORN ROTORS	Repair Estimate: \$2,212.22
---	-----------------------------

UNDER CAR: SUSPENSION, DRIVELINE, EXHAUST, LEAKS

 Inspect engine cooling system for leaks REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE	Repair Estimate: \$294.62
---	---------------------------

CUSTOM RECOMMENDATION

 OIL SERVICE OIL LOW AND DIRTY RECOMMEND RENEWAL OF OIL AND ENGINE OIL FILTER	Repair Estimate: \$554.63
 REAR CAMERA MISALIGNMENT REFITTING OF REAR BUMPER FOR REAR CAMERA ADJUSTMENT	Repair Estimate: \$956.80

1 Needs Attention Soon

BRAKES

 Brake Linings Thickness - Front Front Brakes - 4mm Replace Front Brake Pads and Rotors with brake wear sensor DUE TO LOW PADS AND WORN ROTORS	Repair Estimate: \$2,668.92
---	-----------------------------

40 Passed Inspection

UNDER HOOD: FLUIDS AND FILTERS

- ✓ Inspect drive belts
- ✓ Inspect hood and decklid struts
- ✓ Inspect all hoses and clamps
- ✓ Inspect cabin air/HEPA micro filter(if equipped) at 15k or year intervals
- ✓ Check brake fluid level and condition

BATTERY PERFORMANCE

- ✓ Perform visual battery inspection
- ✓ Inspect battery terminal and cables

LIGHTS

- ✓ Instrument cluster warning lamps
- ✓ Inspect headlights, low and high beam operation
- ✓ Inspect fog/driving lights (if applicable)
- ✓ Inspect taillight, turn signal, side marker and license plate lights
- ✓ Inspect taillight, turn signal and side marker assemblies for cracks and damage
- ✓ Inspect brake light operation
- ✓ Inspect hazard light operation
- ✓ Inspect reverse light operation
- ✓ Inspect dash and interior lights
- ✓ Check horn operation

UNDER CAR: SUSPENSION, DRIVELINE, EXHAUST, LEAKS

- ✓ Inspect Engine for oil leaks
- ✓ Inspect brake system for leaks
- ✓ Inspect transmission for leaks
- ✓ Inspect steering system for leaks
- ✓ Check front differential for leaks
- ✓ Check rear differential for leaks
- ✓ Inspect transfer case for leaks(if applicable)
- ✓ Inspect fuel tank, lines and connections
- ✓ Inspect exhaust system for leaks, damage and loose parts
- ✓ Inspect engine mounts
- ✓ Inspect front suspension components
- ✓

GENERAL

- ✓ Inspect wiper and washer operation
- ✓ Inspect windshield wiper blades
- ✓ Inspect rear wiper blade (if applicable)

OTHER

- ✓ Inspect heat and air conditioning operation

TIRES AND ALIGNMENT

- ✓ Tread Depth Measurements - Fronts
Front Left - 8/32+/32nds
Front Right - 8/32+/32nds
- ✓ Tread Depth Measurements - Rears
Rear Left - 7/32/32nds
Rear Right - 7/32/32nds
- ✓ Inspect overall tire wear and condition

- ☐ Inspect transmission mounts
- ☒ Inspect steering components
- ☒ Inspect sway bar components
- ☒ Inspect rear suspension components
- ☒ Inspect axles, driveshaft(s), u-joints and CV joints/boots

OTHER COMMENTS

Windshield washer fluid

filled as needed - YES

Check and adjust tire pressures

Front Left - 37psi

Front Right - 37psi

Rear Left - 37psi

Rear Right - 37psi

SUMMARY OF VISIT:

Total Estimate:	\$6,870.22
-----------------	------------

	Approved	Declined	Undecided
Pre-approved amount:	\$0.00	-	-
Recommended amount:	\$282.03	\$0.00	\$6,274.90
Taxes:	\$12.59	\$0.00	\$300.70
Total:	\$294.62	\$0.00	\$6,575.60

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

INVOICE

DUPLICATE 1
PAGE 1

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrla.com

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23278/23282	T4591	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DD			14:00 08OCT24		299.00	CASH	14OCT24
R.O. OPENED		READY	OPTIONS: ENG:2.0 Liter Supercharged				

14:31 07OCT24 15:45 14OCT24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CLIENT STATES THAT THE DRIVERS SIDE DOOR ELECTRONICS DO NOT OPERATE

CHECK AND ADVISE

86 ELECTRICAL

3238 KESROUANI, ROY LIC#: 3238

WJ

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

23279 LEFT ENGINE JUNCTION BOX TO REAR JUNCTION BOX CIRCUIT SHORT
CIRCUIT TO GROUND ATTEMPTED TO CONNECT WITH VEHICLE. NO CONNECTION WAS
POSSIBLE. GAINED ACCESS TO ENGINE JUNCTION BOX LEFT AND FOUND FUSE FL01
IN GOOD CONDITION. GAINED ACCESS TO REAR JUNCTION BOX AND FOUND FUSE RF
08 BLOWN. OBTAINED RVC NUMBER: TW55OR3S AND REPLACED FUSE RF 08 IN REAR
JUNCTION BOX. TOPIX CONNECTION TO VEHICLE IS NOW ESTABLISHED AND DRIVER
DOOR BUTTONS FOR WINDOW OPERATIONS AND DOOR LOCK FEATURES ARE NOW
WORKING NORMALLY. DROVE 2 MILES, FUSE RF08 BLEW AGAIN AND DRIVER DOOR
ELECTRONICS STOPPED WORKING. REMOVED DRIVER DOOR TRIM PANEL. REMOVED
DRIVER FOOT WELL LOWER TRIM PANEL. REMOVED REAR LEFT LUGGAGE
COMPARTMENT TRIM PANEL. (START OF DIAG TIME) USING ELECTRICAL WIRING
DIAGRAMS CHECKED CIRCUIT FROM DRIVER DOOR MODULE TO REAR JUNCTION BOX
CONNECTOR TO FROM CAPW02BD-14 TO CABR02D-1 FOUND 0.2 OHMS. CHECKED
CIRCUIT FROM DIAGNOSTIC CONNECTOR TO LEFT ENGINE JUNCTION BOX FROM
C2DB04B-16 TO C1BB01A-16 FOUND 0.2 OHMS. CHECKED CIRCUIT FORM LEFT
ENGINE JUNCTION BOX TO REAR JUNCTION BOX FROM C1BB01A-15 TO C4BR02D-1
FOUND 1.8 OHMS TO 3 OHMS VARIABLE READING. DETERMINED HIGH RESISTANCE.
CHECKED HARNESS AND FOUND CIRCUIT FROM CONNECTOR C13H-13 TO LEFT ENGINE
JUNCTION BOX AT C1BB01A-15 SHORTED TO GROUND WHERE DRIVER RESTS HIS/HER
LEFT FOOT UNDERNEATH THE CARPET. OBTAINED RVC NUMBER: TAKITXQX.
PERFORMED HARNESS REPAIR FROM C13H-13 TO C1BB01A-15. REFITTED DRIVER
DOOR TRIM PANEL; . REFITTED LEFT SIDE LUGGAGE COMPARTMENT TRIM PANEL.
REFITTED DRIVER FOOT WELL LOWER PANEL. CLEARED ALL CODES. DIVER DOOR
ELECTRONICS ARE NOW WORKING CORRECTLY.

B CLIENT STATES LOW BATTERY WARNING LIGHT COMES ON THE CLUSTER CHECK

AND ADVISE

86 ELECTRICAL

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	
Revised Estimate	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)		PARTS AMOUNT	
\$	\$					GAS, OIL, LUBE	
						SUBLET AMOUNT	
☐ Tire pressure check/inflation service was performed. RF psi LF psi RR psi LR psi ☐ Customer declined tire pressure check/inflation service. Initials						WASTE DISPOSAL COSTS *	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						TOTAL CHARGES	
DATE						LESS INSURANCE	
CUSTOMER SIGNATURE						SALES TAX	
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE						PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264DUPLICATE 1
PAGE 2400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrla.com

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
	20	JAGUAR F-TYPE		SAJDD1GX4LCK67497			23278/23282		T4591
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP24 DD			14:00 08OCT24			299.00	CASH	14OCT24	

R.O. OPENED READY OPTIONS: ENG:2.0_Liter_Supercharged

14:31 07OCT24 15:45 14OCT24

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

3238 KESROUANI, ROY LIC#: 3238

WJ

(N/C)

1 T2H33020 BATTERY

(N/C)

1 BAT California Battery Fee

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

23279 START UP BATTERY FAILURE. CHECKED CODES AND PRINTED FOUND
CODE U3003-16 STORED IN GSM. USING TOPIX CLOUD, STARTED NEW FAULT
WORKFLOW AND FOUND BCM AND GWM SOFTWARE UP TO DATE. PERFORMED IN
VEHICLE BATTERY TEST. RECHARGED BATTERY AND PERFORMED ANOTHER IN
VEHICLE BATTERY TEST. BATTERY FAILED. PERFORMED OUT OF VEHICLE BATTERY
TEST. BATTERY FAILED. OBTAINED RVC NUMBER; RC9F5PLX AND REPLACED START
UP BATTERY. REST BATTERY MONITORING SYSTEM. "LOW BATTERY: MESSAGE IS NO
LONGER DISPLAYED IN INSTRUMENT CLUSTER.

C CUSTOMER STATES RESET ALL TIRE PRESSURES

TP CUSTOMER STATES RESET ALL TIRE PRESSURES

3238 KESROUANI, ROY LIC#: 3238

ISPJ

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

23278 TIRE PSI VALUES. LEFT 37PSI FRONT RIGHT 37PSI REAR LEFT 37PSI
REAR RIGHT 37PSI

D COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION

99PJ COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION

3238 KESROUANI, ROY LIC#: 3238

ISPJ

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

23278 MPI MPI AVAILABLE IN MYMKARMA

E** CLIENT REQUEST EST ON A NEW SIMS CARD.

01 VEHICLE INSPECTION

3238 KESROUANI, ROY LIC#: 3238

ISPJ

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)
Revised Estimate \$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)

☐ Tire pressure check/inflation service was performed.
RF _____ psi LF _____ psi RR _____ psi LR _____ psi
☐ Customer declined tire pressure check/inflation service. Initials _____

By signing below, you acknowledge that you were notified of and authorized the
Dealership to perform the services/repairs itemized in this invoice and that you received
(or had the opportunity to inspect) any replaced parts as requested by you.

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

*HAZARDOUS WASTE DISPOSAL
COSTS: We have added this
charge to cover costs associated
with the handling, management
and disposal of toxic wastes or
hazardous substances under
California and Federal Law.

ALL PARTS ARE NEW
UNLESS OTHERWISE
INDICATED.

☐ Some Parts Not Returnable

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
WASTE DISPOSAL COSTS *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

INVOICE
DUPLICATE 1
PAGE 3

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrla.com

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
	20	JAGUAR F-TYPE		SAJDD1GX4LCK67497			23278/23282		T4591
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP24 DD			14:00 08OCT24			299.00	CASH	14OCT24	


R.O. OPENED READY OPTIONS: ENG:2.0_Liter_Supercharged

14:31 07OCT24 15:45 14OCT24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

23279 ESTIMATE PROVIDED ESTIMATE ON A NEW SIM CARD. PART IS CURRENTLY OUT OF STOCK.

DRIVER SIDE DOOR CONTROL INOP



Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)
Revised Estimate				☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)

☐ Tire pressure check/inflation service was performed.
 RF _____ psi LF _____ psi RR _____ psi LR _____ psi
☐ Customer declined tire pressure check/inflation service. Initials _____

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

***HAZARDOUS WASTE DISPOSAL COSTS:** We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.

ALL PARTS ARE NEW
UNLESS OTHERWISE
INDICATED.

☐ Some Parts Not Returnable

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
WASTE DISPOSAL COSTS *	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrla.com

INVOICE

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

PAGE 1

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554
3391 Danny Sanchez

CELL: 752-979-6264

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23278/23279	T4566	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DD			14:00 08OCT24		299.00	CASH	10OCT24
R.O. OPENED		READY	OPTIONS: ENG:2.0_Liter_Supercharged				

14:31 07OCT24 12:44 10OCT24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CLIENT STATES THAT THE DRIVERS SIDE DOOR ELECTRONICS DO NOT OPERATE
CHECK AND ADVISE

86 ELECTRICAL

3238 KESROUANI, ROY LIC#: 3238

WJ

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: (N/C)
0.00

23279 BLOWN FUSE. ATTEMPTED TO CONNECT WITH VEHICLE. NO CONNECTION
WAS POSSIBLE. GAINED ACCESS TO ENGINE JUNCTION BOX LEFT AND FOUND FUSE
FL01 IN GOOD CONDITION. GAINED ACCESS TO REAR JUNCTION BOX AND FOUND
FUSE RF 08 BLOWN. OBTAINED RVC NUMBER: TW55OR3S AND REPLACED FUSE RF 08
IN REAR JUNCTION BOX. TOPIX CONNECTION TO VEHICLE IS NOW ESTABLISHED
AND DRIVER DOOR BUTTONS FOR WINDOW OPERATIONS AND DOOR LOCK FEATURES
ARE NOW WORKING NORMALLY.

B CLIENT STATES LOW BATTERY WARNING LIGHT COMES ON THE CLUSTER CHECK
AND ADVISE

86 ELECTRICAL

3238 KESROUANI, ROY LIC#: 3238

WJ

1 T2H33020 BATTERY

1 BAT California Battery Fee

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: (N/C)
0.00

23279 START UP BATTERY FAILURE. CHECKED CODES AND PRINTED FOUND
CODE U3003-16 STORED IN GSM. USING TOPIX CLOUD, STARTED NEW FAULT
WORKFLOW AND FOUND BCM AND GWM SOFTWARE UP TO DATE. PERFORMED IN
VEHICLE BATTERY TEST. RECHARGED BATTERY AND PERFORMED ANOTHER IN
VEHICLE BATTERY TEST. BATTERY FAILED. PERFORMED OUT OF VEHICLE BATTERY
TEST. BATTERY FAILED. OBTAINED RVC NUMBER: RC9F5PLX AND REPLACED START
UP BATTERY. REST BATTERY MONITORING SYSTEM. "LOW BATTERY: MESSAGE IS NO
LONGER DISPLAYED IN INSTRUMENT CLUSTER.

C CUSTOMER STATES RESET ALL TIRE PRESSURES

TP CUSTOMER STATES RESET ALL TIRE PRESSURES

3238 KESROUANI, ROY LIC#: 3238

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)		LABOR AMOUNT	
Revised Estimate	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)		PARTS AMOUNT	
☐ Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi ☐ Customer declined tire pressure check/inflation service.						GAS, OIL, LUBE	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						SUBLET AMOUNT	
DATE						WASTE DISPOSAL COSTS *	
CUSTOMER SIGNATURE						TOTAL CHARGES	
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE						LESS INSURANCE	
						SALES TAX	
						PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrla.com

NYREE HINTON

616 MASSELIN AVE APT 210

Los Angeles, CA 90036

HOME:

CONT: 732-979-6264

BUS:

CELL: 732-979-6264

INVOICE

PAGE 2

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
	20	JAGUAR F-TYPE		SAJDD1GX4LCK67497		23278/23279		T4566
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DD			14:00 08OCT24			299.00	CASH	10OCT24
R.O. OPENED		READY		OPTIONS: ENG:2.0_Liter_Supercharged				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
			ISPJ				(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE C:	0.00
23278 TIRE PSI VALUES. LEFT 37PSI FRONT RIGHT 37PSI REAR LEFT 37PSI REAR RIGHT 37PSI							

D COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION
99PJ COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION
3238 KESROUANI, ROY LIC#: 3238

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE D:	(N/C)
23278 MPI MPI AVAILABLE IN MYMKARMA							

E** CLIENT REQUEST EST ON A NEW SIMS CARD.

01 VEHICLE INSPECTION

3238 KESROUANI, ROY LIC#: 3238

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE E:	(N/C)
23279 ESTIMATE PROVIDED ESTIMATE ON A NEW SIM CARD. PART IS CURRENTLY OUT OF STOCK.							

DRIVER SIDE DOOR CONTROL INOP

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL	DESCRIPTION	TOTALS
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)	COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law. ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	0.00
Revised Estimate	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)		PARTS AMOUNT	0.00
						GAS, OIL, LUBE	0.00
						SUBLET AMOUNT	0.00
						WASTE DISPOSAL COSTS *	0.00
☐ Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi ☐ Customer declined tire pressure check/inflation service. Initials _____						TOTAL CHARGES	0.00
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						LESS INSURANCE	0.00
DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE				SALES TAX	0.00
						PLEASE PAY THIS AMOUNT	0.00

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.