

BEACH CITIES ROVER
529 N. PACIFIC COAST HWY
REDONDO BEACH, CA. 90277
(310) 921-8393
Writer: ALEX DALZIEL



INVOICE # 9361

JBULEN@BEACHCITIESROVER.COM
beachcitiesrover.com

NYREE HINTON 6401 WILSHIRE BOULEVARD LOS ANGELES, CA. 90048 Cell: (732) 979-6264	YEAR: 2020 MAKE/MODEL: JAGUAR F-TYPE P300 COU VIN: SAJDD1GX4LCK67497 ENGINE: 2.0L L4 DOHC 16V	TRANS/DRIVE: 8-SPEED AUTOMATIC/ LICENSE/STATE: 9PCM313/CA MILES IN/MILES OUT: 30294/30295
--	--	---

In: 10/29/2025 Out: 11/4/2025

AIR PRESSURE IN		AIR PRESSURE OUT		BRAKE MEASUREMENTS	
PSI		PSI	37 PSI	37 PSI	10mm
PSI		PSI	37 PSI	37 PSI	10mm

VEHICLE ISSUE #1: CUSTOMER STATES CHECK ENGINE LIGHT ON. CHECK AND ADVISE **NOTE** CUSTOMER PROVIDED DATA/SEE ATTACHED				
TECH REPORT: VERIFIED CONCERN. MULTIPLE CODES/SOME STORED PRIOR TO CHECK IN TODAY. P25A9-13 PISTON COOLING JET FAILURE/MULTI MISFIRE DETECTED. PERFORMED VISUAL INSPECTION OF SPARK PLUGS (WORN STATE) ADVISE TO REPLACE PISTON OIL JET AND REPLACE SPARK PLUGS TO START. **NOTE** PENDING CAT EFFICIENCY CODE BANK 1				
PART: AJ813393	VALVE CONTROL JET	1 @ \$354.43	\$354.43	NEW
LABOR: GUTIERRE	CHECK ENGINE LIGHT DIAGNOSIS // PISTON OIL JET REPLACEMENT	4 @ \$0.00	\$780.00	LABOR
Total for "CUSTOMER STATES CHECK ENGINE LIGHT ON. CHECK AND ADVISE **NOTE** CUSTOMER PROVIDED DATA/SEE ATTACHED":			\$1,134.43	
VEHICLE ISSUE #2: U/I SPARK PLUGS FOULED, CUSTOMER AUTH TO REPLACE				
TECH REPORT: REMOVE AND REPLACED FOULED SPARK PLUGS. CLEANED AREA. REINSTALLED ALL REMOVED COMPONENTS. TEST OPERATION. WORKING AS DESIGNED AT THIS TIME.				
PART: JDE38685	SPARK PLUG	4 @ \$31.24	\$124.96	NEW
LABOR: GUTIERRE	SPARK PLUG REPLACEMENT	2 @ \$0.00	\$390.00	LABOR
Total for "U/I SPARK PLUGS FOULED, CUSTOMER AUTH TO REPLACE":			\$514.96	
VEHICLE ISSUE #3: CUSTOMER AUTH TO PERFORM OIL AND FILTER CHANGE SERVICE				
TECH REPORT: PERFORMED OIL CHANGE SERVICE				
PART: JDE37128	INGENIUM OIL FILTER KIT	1 @ \$27.95	\$27.95	NEW
PART: OIL - SYNTHETIC 0W20	CASTROL SYNTHETIC 0W20	7 @ \$11.57	\$80.99	NEW
LABOR: GUTIERRE	OIL & FILTER CHANGE (ENGINE)	0.5 @ \$0.00	\$50.00	LABOR
Total for "CUSTOMER AUTH TO PERFORM OIL AND FILTER CHANGE SERVICE":			\$158.94	
VEHICLE ISSUE #4: MPI				
			Total for "MPI": \$0.00	

Recommended Repairs: *** ENGINE MOUNTS WORN, REC TO REPLACE (\$1,830) *** RADIATOR LEAKING, REC TO REPLACE (\$2,005) For a period of [12 months] or [12k miles], from BCR deeming the repair complete, whichever comes first, BCR will repair defects in material/workmanship to the repairs stated on this invoice. For coverage, repairs must be completed at BCR. Coverage does not include towing charges/damage. Not valid for customer supplied parts. A storage fee of \$50per day will be charged for vehicles not paid for & picked-up within 2 business days following written or verbal notification the vehicle is complete to BCR standards. Neglect/abuse of vehicle will immediately void any & all warranties. Diagnostic charges are nonrefundable & subject to the storage policy. BCR quotes may change at any time as parts/labor fluctuate. Parts, quote, storage & warranty disclosures are available upon request.	Labor/Jobs	\$1,657.50
	Parts	\$1,220.39
	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$2,877.89
	Tax @ 9.75%	\$118.99
	Total	\$2,996.88
	Payments	\$0.00
	Balance	\$2,996.88

Replaced parts may be requested by customer. I hereby authorize the above repair work to be completed along with all necessary materials. Beach Cities Rover (BCR), employees & 1099 representatives may operate the above vehicle 24/7 while in BCR possession at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. BCR will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond control. Clients requesting more than 24hours to approve or decline a recommended repair are responsible for rental & storage

X _____ Date 11/4/2025

2800 CASH
Page 1 OF 2

BEACH CITIES ROVER

529 N. PACIFIC COAST HWY
REDONDO BEACH, CA. 90277
(310) 921-8393
Writer: ALEX DALZIEL

**INVOICE # 9361**

JBULEN@BEACHCITIESROVER.COM
beachcitiesrover.com

NYREE HINTON
6401 WILSHIRE BOULEVARD
LOS ANGELES, CA. 90048
Cell: (732) 979-6264

YEAR: 2020
MAKE/MODEL: JAGUAR F-TYPE P300 COU
VIN: SAJDD1GX4LCK67497
ENGINE: 2.0L L4 DOHC 16V

TRANS/DRIVE: 8-SPEED AUTOMATIC/
LICENSE/STATE: 9PCM313/CA
MILES IN/MILES OUT: 30294/30295

VEHICLE ISSUE #5: TPS**VEHICLE ISSUE #6: REAR BRAKES @ 1MM. CUSTOMER AUTH TO REPLACE**

Total for "TPS": \$0.00

TECH REPORT: CUSTOMER AUTH TO REPLACE REAR BRAKES W/ AFTERMARKET & "BREMBO"; OPTION. TEST OPERATION.
WORKING AS DESIGNED AT THIS TIME.

PART: 10081	BRAKE CLEANER			
PART: STOP SQUEEK	STOP SQUEEK	1 @ \$3.95	\$3.95	NEW
		1 @ \$8.11	\$8.11	NEW
PART: T2R61946	REAR BRAKE PAD **BREMBO**			
PART: C2D29140	REAR BRAKE SENSOR	1 @ \$100.00	\$100.00	NEW
PART: T2R5941	BRAKE DISC **BREMBO**	1 @ \$40.00	\$40.00	NEW
LABOR: GUTIERRE	REPLACE REAR BRAKE PADS AND ROTORS	2 @ \$240.00	\$480.00	NEW
		2.5 @ \$0.00	\$437.50	LABOR

Total for "REAR BRAKES @ 1MM. CUSTOMER AUTH TO REPLACE": \$1,069.56

VEHICLE ISSUE #7: LEFT REAR TIRE HAS NAIL. PERFORMED TIRE REPAIR PER COURTESY.

Total for "LEFT REAR TIRE HAS NAIL. PERFORMED TIRE REPAIR PER COURTESY.": \$0.00

Recommended Repairs: *** ENGINE MOUNTS WORN, REC TO REPLACE (\$1,830) *** RADIATOR
LEAKING, REC TO REPLACE (\$2,005)

For a period of [12 months] or [12k miles], from BCR deeming the repair complete, whichever comes first, BCR will repair defects in material/workmanship to the repairs stated on this invoice. For coverage, repairs must be completed at BCR. Coverage does not include towing charges/damage. Not valid for customer supplied parts. A storage fee of \$50per day will be charged for vehicles not paid for & picked-up within 2 business days following written or verbal notification the vehicle is complete to BCR standards. Neglect/abuse of vehicle will immediately void any & all warranties. Diagnostic charges are nonrefundable & subject to the storage policy. BCR quotes may change at any time as parts/labor fluctuate. Parts, quote, storage & warranty disclosures are available upon request.

Labor/Jobs	\$1,657.50
Parts	\$1,220.39
Sublet	\$0.00
Total Fees	\$0.00
Subtotal	\$2,877.89
Tax @ 9.75%	\$118.99
Total	\$2,996.88
Payments	\$0.00
Balance	\$2,996.88

Replaced parts may be requested by customer. I hereby authorize the above repair work to be completed along with all necessary materials. Beach Cities Rover (BCR), employees & 1099 representatives may operate the above vehicle 24/7 while in BCR possession at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. BCR will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond control. Clients requesting more than 24hours to approve or decline a recommended repair are responsible for rental & storage

X

Date 11/4/2025