

Subject: CASE:[8001431709]: Repair Assistance

Date: Friday, November 28, 2025 at 9:30:18 AM Pacific Standard Time

From: jagweb1@jaguarlandrover.com <jagweb1@jaguarlandrover.com>

To: nyreehinton@gmail.com <nyreehinton@gmail.com>

Hello Mr. Hinton,

I hope this email finds you well!

I would like to use this email a follow-up to our phone conversation today as requested. As I advised, Jaguar Land Rover North America is not in a position to contribute towards your repairs.

I do apologize that this is not the resolution you were looking for, but all appropriate parties have reviewed your case, and I have also consulted with my supervisor about other possible options. After exhausting all possible options, I apologize that there is no assistance we are able to provide at this time.

Jaguar Land Rover North America provides what we believe to be a very generous warranty, given the terms of our warranties and what we cover. There is the expectation that as a consumer, you will be financially responsible for repairs of the vehicle at some point during your ownership. As with other vehicle manufacturers, this is generally at the end of the term of the warranty, in miles or time, whichever comes first.

Kindest regards,

Yours sincerely,

Diana S

Customer Relationship Centre

T: 1-800-637-6837, OPTION 9, Ext. 1310148

F: 888-410-0938

E: jagweb1@jaguarlandrover.com

Jaguar Land Rover North America, LLC

jaguarusa.com | landroverusa.com

100 Jaguar Land Rover Way, Mahwah, NJ 07495

Subject: Re: CASE:[8001431709]: Repair Assistance

Date: Friday, November 28, 2025 at 1:47:07 AM Pacific Standard Time

From: nyreehinton@gmail.com <nyreehinton@gmail.com>

To: jagweb1@jaguarlandrover.com <jagweb1@jaguarlandrover.com>

Dear Jaguar Land Rover Customer Relationship Center,

I am writing to formally request that Jaguar Land Rover North America (JLRNA) cover the costs for critical repairs identified during a service visit on November 5, 2025, at Jaguar Land Rover Los Angeles. The total amount in question is **\$3,132.53**, covering the replacement of a failed Vehicle Stability Control Module and two failed engine mounts.

This request is based on extensive documentation, including a detailed **Service Negligence**, which proves that these component failures are the direct result of a pattern of negligence by two of your authorized service centers: Jaguar Land Rover Los Angeles and Jaguar Land Rover South Bay.

Over the past year, my 2020 F-Type has experienced recurring and unresolved electrical and cooling system failures. Despite multiple visits, the dealerships failed to follow Jaguar's own explicit technical directives, leading to repeat repairs, extended vehicle downtime, and significant safety risks.

The analysis provides an irrefutable timeline, but the key points of negligence are:

- **Ignored Service Campaign for Cooling System (H291):** My vehicle was subject to Service Action H291, which was created to prevent the exact variable coolant pump failure my vehicle experienced (DTCs P2B61-73 & P26CB-72). This campaign was never performed by either dealership, leading directly to a repeat failure of the cooling system.
- **Failure to Follow Technical Bulletin for Cooling System (JLRTB02030):** When presented with a low coolant warning and a continuously running fan—the exact symptoms described in this TSB—the dealership failed to diagnose the known pump failure. Instead, they performed a superficial hose replacement, ensuring the problem would reoccur. The root cause was only identified by an independent specialist.
- **Incomplete Diagnosis of Electrical Faults:** A recurring electrical short that disabled the driver's door was improperly repaired by JLR South Bay, requiring a second, more intensive repair at JLR Los Angeles. The root cause was discoverable on the first visit, as documented in the analysis.
- **Leaving a Critical Network Fault Unresolved:** A permanent internal fault in the vehicle's Gateway Module (GWM) was identified but never addressed by either dealership. This represents a serious oversight that compromises the vehicle's entire electrical network.
- **Failure to Perform VVT Solenoid Campaign (H299):** The dealerships also failed to perform Service Action H299, a known campaign to prevent premature wear of the VCT solenoids—an issue that is now beginning to manifest in my vehicle's on-board diagnostics.

On November 5, 2025, these unresolved issues culminated in the vehicle entering "limp mode" and

being diagnosed with the following major failures:

1. **Vehicle Stability Control Module Failure:** \$1,164.13

1. **Engine Mount Failure (x2):** \$1,968.40

These are not standard wear-and-tear items; they are the foreseeable consequences of the dealerships' failure to apply Jaguar's own mandatory campaigns and repair bulletins. As an owner, I relied on the expertise of your authorized repair network and was failed. This negligence has compromised the safety and reliability of my vehicle and has resulted in significant out-of-pocket expenses for independent diagnosis and repair.

Therefore, I formally request that JLRNA take responsibility for its authorized dealers' service negligence by covering the full cost of **\$3,132.53** for the VSC module and engine mount replacements.

Sincerely,

Nyree Hinton

From: jagweb1@jaguarlandrover.com <jagweb1@jaguarlandrover.com>

Date: Monday, November 24, 2025 at 2:20 PM

To: nyreehinton@gmail.com <nyreehinton@gmail.com>

Subject: CASE:[8001431709]: Repair Assistance

Hello,

This is Paige from Jaguar North America. Your case number for your concern is 8001431709. While I'm taking the next steps to fully research your request, please feel free to reply back to this email at any time with questions that you may have.

Thank you for reaching out to Jaguar North America and for your patience as I work to resolve your concerns to the best of my abilities.

NOTE: Please do not adjust, delete, or modify the "Subject" portion of this email, as it would

adversely affect our ability to follow up on your case.

Paige S

Customer Relationship Centre

T: 1-800-452-4827,OPTION 9, Ext. [1310067]

F: 888-410-0938

E: jagweb1@jaguarlandrover.com

Jaguar Land Rover North America, LLC

jaguarusa.com | landroverusa.com

100 Jaguar Land Rover Way, Mahwah, NJ 07495