

NYREE HINTON

INVOICE

Invoice #: 908960

Jaguar Land Rover South Bay

3233 Pacific Coast Highway

Torrance, CA 90505-6613

Phone: (310) 798-0550

Home:

Bus:

Customer #: 7913668

BAR REG. # AJ229534

E.P.A.# CAD981683915

Cell: 732-979-6264 Email: na@na.com/home

Service Advisor: 7814 JOEL CRUZ

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE		MILEAGE IN		MILEAGE OUT	
	20	JAGUAR F-TYPE			SAJDD1GX4LCK67497				23072		23073	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED		READY		
01JAN20 D			18:00 18OCT24		0.00	CASH	02OCT24	17:59 01OCT24		14:36 02OCT24		
OPTIONS: DLR:0146												

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty.

We also offer high quality non-OE parts that are suitable for your vehicle and fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP*." These non-OE (AP*) parts are not sourced from the vehicle's manufacturer or covered by its warranty. Non-OE parts come with a limited warranty backed by AutoNation and/or the parts manufacturer.

A CUSTOMER STATES DRIVERS SIDE WINDOW DOES NOT ROLL UP.

CAUSE:

None CUSTOMER STATES DRIVERS SIDE WINDOW DOES NOT ROLL UP.

PARTS: 8784 WJ 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: (N/C) 0.00

23072 VERIFIED CUSTOMER CONCERN FOUND WINDOW SWITCH NOT WORKING. CHECK SEAT SWITCH AND IT ALSO NOT WORKING SO IS THE LOCK AND UNLOCK SWITCH NOT WORKING. CHECK FUSE AT THE REAR JUNCTION BOX FOR FRONT LEFT DOOR MODULE AND FUSE WAS BLOWN. CHECK POWER WIRE FOR 12 VOLTS AND GOT 12VOLTS FROM JUNCTION BOX TO LEFT DOOR CONTROL MODULE. CHECK GROUND FROM JUNCTION BOX TO LEFT DOOR MODULE AND THERE WAS A SHORT TO GROUND. REPAIR GROUND WIRE AND REPLACE FUSE AND FUSE DIDN'T BLOW AGAIN. NOW GOT POWER TO LEFT FRONT DOOR MODULE AND WINDOW SWITCH IS NOW WORKING AS IT SHOULD.

B MULTI-A Customer requested to have Multi Point Inspection performed during this visit

MULTI-A MULTI-A Customer requested to have Multi Point Inspection performed during this visit

8784 CR 0.00 0.00

GTIRE ALL TIRES AT 9/32ND ... MINIMUM IS 3/32ND) 0.00 0.00

8784 CR 0.00 0.00

YBK FRONT BRAKES AT 6MM ... REAR BRAKES AT 4MM ... MINIMUM IS 3MM) 0.00 0.00

8784 CR 0.00 0.00

GBATT BATTERY TESTS GOOD 0.00 0.00

8784 CR 0.00 0.00

DSRB Declined Rear Brake Replacement 0.00 0.00

8784 CR 0.00 0.00

DSSM Declined Scheduled Maintenance 0.00 0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

23072 PERFORMED MPI

NOTICE TO CONSUMERS: PLEASE READ IMPORTANT INFORMATION ON ATTACHED PAGES.

CALL/TEXT AUTHORIZATION: YOU HEREBY AUTHORIZE US TO MAKE RECURRING CALLS, TEXTS, AND TRANSMIT VOICEMAILS TO YOU AT YOUR PHONE NUMBER(S), INCLUDING BY USE OF AN AUTOMATED SYSTEM, REGARDING SALES AND/OR SERVICE OF YOUR VEHICLE. YOU UNDERSTAND YOUR AGREEMENT IS NOT A CONDITION OF PURCHASING GOODS OR SERVICES AND YOU MAY OPT OUT YOUR PHONE NUMBER(S) BY NOTIFYING YOUR SERVICE ADVISOR OR TEXTING STOP TO ANY MESSAGE RECEIVED. MSG & DATA RATES MAY APPLY.

If we receive payments related to the goods or services provided hereunder from any third party (e.g., a check under a Service Contract), you agree that we may retain all such monies as if same was a payment from you and apply such funds to any outstanding indebtedness of yours. You hereby grant us a power of attorney to endorse or otherwise sign your name and to deposit such funds into the dealership's account to carry out the intent of this provision.

By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.

I acknowledge notice and oral approval of an increase in the original estimated price.

HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of hazardous waste or substances under California and Federal Law.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

☐ Some Parts Not Returnable

DESCRIPTION	LABOR AMOUNT	TOTALS
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS INSURANCE	
SALES TAX		
PLEASE PAY THIS AMOUNT		

NYREE HINTON

INVOICE

Invoice #: **908960**

Jaguar Land Rover South Bay

3233 Pacific Coast Highway
Torrance, CA 90505-6613
Phone: (310) 798-0550

Tag #: **124=**

Home: Cell: 732-979-6264 Bus: Email: na@na.com/home Customer #: **7913668** Service Advisor: **7814 JOEL CRUZ** BAR REG. # AJ229534 E.P.A.# CAD981683915

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
	20	JAGUAR F-TYPE			SAJDD1GX4LCK67497			23072	23073
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN20 D			18:00 18OCT24		0.00	CASH	02OCT24	17:59 01OCT24	14:36 02OCT24
OPTIONS: DLR:0146									

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty.

We also offer high quality non-OE parts that are suitable for your vehicle and fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP." These non-OE (AP*) parts are not sourced from the vehicle's manufacturer or covered by its warranty. Non-OE parts come with a limited warranty backed by AutoNation and/or the parts manufacturer.*

C PERFORM TIRE PRESSURE SERVICE
TPS PERFORM TIRE PRESSURE SERVICE
8784 CR
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00
23072 SET TIRES PRESSURE TO SPEC

ESTIMATE: 0.00 01OCT24 17:59 SA: 7814

*****THE FOLLOWING WORK WAS RECOMMENDED BUT NOT PERFORMED*****
,, DESCRIPTION: PPBPR AutoNation Parts - Aftermarket REAR BRAKE PADS/SHOES
,, REASON DENIED: LAT Customer will have work performed later
,, PERSON CONTACTED: NYREE HINTON
,, COMMENTS: None
,, RECOMMENDED BY: 7814 CRUZ DENIAL ADDED BY: 7814 CRUZ
,, LINE ASSOCIATED: ESTIMATE: 696.70
,, DESCRIPTION: B151A064000 Service - 64,000 Miles
,, REASON DENIED: LAT Customer will have work performed later
,, PERSON CONTACTED: NYREE HINTON
,, COMMENTS: None
,, RECOMMENDED BY: 7814 CRUZ DENIAL ADDED BY: 7814 CRUZ
,, LINE ASSOCIATED: ESTIMATE: 1428.79

NOTICE TO CONSUMERS: PLEASE READ IMPORTANT INFORMATION ON ATTACHED PAGES.

CALL/TEXT AUTHORIZATION: YOU HEREBY AUTHORIZE US TO MAKE RECURRING CALLS, TEXTS, AND TRANSMIT VOICEMAILS TO YOU AT YOUR PHONE NUMBER(S), INCLUDING BY USE OF AN AUTOMATED SYSTEM, REGARDING SALES AND/OR SERVICE OF YOUR VEHICLE. YOU UNDERSTAND YOUR AGREEMENT IS NOT A CONDITION OF PURCHASING GOODS OR SERVICES AND YOU MAY OPT OUT YOUR PHONE NUMBER(S) BY NOTIFYING YOUR SERVICE ADVISOR OR TEXTING STOP TO ANY MESSAGE RECEIVED. MSG & DATA RATES MAY APPLY.

If we receive payments related to the goods or services provided hereunder from any third party (e.g., a check under a Service Contract), you agree that we may retain all such monies as if same was a payment from you and apply such funds to any outstanding indebtedness of yours. You hereby grant us a power of attorney to endorse or otherwise sign your name and to deposit such funds into the dealership's account to carry out the intent of this provision.

By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.

I acknowledge notice and oral approval of an increase in the original estimated price.

DATE

CUSTOMER SIGNATURE

HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of hazardous waste or substances under California and Federal Law.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

☐ Some Parts Not Returnable

LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

3233 PACIFIC COAST HWY

TORRANCE, CA 90505

Range Rover/Land Rover Multi-Point Inspection Report

The Range Rover/Land Rover Multi-Point Inspection is a series of thorough vehicle "health checks" and visual examinations performed by our factory-trained technicians. The focus of this complimentary service is to ensure that your Range Rover/Land Rover vehicle continues to perform at an optimum level, as well as to help minimize your chances of being inconvenienced while on the road.

In the event that additional service is recommended on a listed item, your Service Advisor will be happy to speak with you about service options.



Customer Name <u>HINTON, NYREE</u>		2020 F-TYPE	
Customer ID <u>908960</u>	Mileage <u>23072</u>	Year/Model <u>2020 F-TYPE</u>	Engine Size <u>SAJDD1GX4LCK67497</u>
RO/Tag <u> </u>	Date <u>10/02/2024</u>	VIN <u> </u>	

Checked and Okay at this Time	May Require Future Attention*	Requires Immediate Attention
-------------------------------	-------------------------------	------------------------------

Check Fluid Levels and Fill

OK	FILL	OK	FILL
☒	☐ Engine Oil	☒	☐ Brake Reservoir
☒	☐ Windshield Washer	☒	☐ Headlamp Washer
☒	☐ Power Steering	☒	☐ Coolant Recovery Reservoir
☒	☐ Transmission (if equipped w/ dipstick)		

Check Following Systems / Components

☒	☐	Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps
☒	☐	Visually inspect headlamp alignment
☒	☐	Windshield washer spray, wiper operation and wiper blades
☒	☐	Windshield cracks and/or chips
☒	☐	Heating, ventilation and air conditioning check
☒	☐	Engine air cleaner filter
☒	☐	Oil and/or fluid leaks
☒	☐	Constant velocity (CV) drive axle boots (if equipped)
☒	☐	Exhaust system (leaks, damage, loose parts)
☒	☐	Steering and steering linkages
☒	☐	Shocks/struts, air suspension and other suspension components for leaks and/or damage
☒	☐	Brake system (including lines, hoses and parking brake)
☒	☐	Engine cooling system, hoses and clamps
☒	☐	Radiator, heater and air conditioning hoses for leaks / damage
☒	☐	Accessory drive belt(s)
☐	☐	Clutch operation (if equipped)
☐	☐	Floor mats
☐	☐	Navigation map update required
☐	☐	State inspection due (if applicable) _____
		Month Day Year
☐	☐	Your last completed maintenance _____
		Mileage Month Year
☐	☐	Your next factory scheduled maintenance is due at _____
		Mileage Month Year

Comments:

Check Battery Condition

☒ Good	☐ Recharge	☐ Bad
Comments: _____		

Check Brakes Measure Front / Rear Brake Linings

RF	☒	☐	☐	RR	☒	☐	☐
6 mm				4 mm			
LF	☒	☐	☐	LR	☒	☐	☐
6 mm				4 mm			
Over 8mm or 10/32" 4 to 8mm or 5/32" to 10/32" Less than 4mm or 5/32"							
Brake Measurements Not Taken This Service Visit							

Comments:

Check Tires

LF	9/32"	TREAD DEPTH	9/32"
☒	7/32" or Greater		7/32" or Greater
☐	4/32" to 6/32"		4/32" to 6/32"
☐	3/32" or Less		3/32" or Less
☒	7/32" or Greater		7/32" or Greater
☐	4/32" to 6/32"		4/32" to 6/32"
☐	3/32" or Less		3/32" or Less
LR	9/32"		9/32"
☒	7/32" or Greater		7/32" or Greater
☒	4/32" to 6/32"		4/32" to 6/32"
☐	3/32" or Less		3/32" or Less
LF	☐ OK	Wear Pattern / Damage	RF ☒
LR	☐ OK	Tire Wear Indicators	RR ☒
☒ Alignment Check Recommended ☒ Wheel Balance Recommended			

Comments:

This Courtesy Inspection Completed By Your Land Rover Service Team

Service Advisor: Joel Cruz

Technician: CHAVEZ CUEVAS ...

Customer Signature: _____

8534 08/13

Tire Pressure Set to			
Factory Recommendations	PSI	Green	Front
		Green	Rear

*Brake/tire replacement will be required prior to the next scheduled maintenance service.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlra.com

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

PAGE 2

SERVICE ADVISOR: 3391 Danny Sanchez

B.A.R. REG # ARD303078 EPA# CAL000470554

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23278/23279	T4566
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
30SEP24 DL			14:00 08OCT24		299.00	CASH
R.O. OPENED	READY	OPTIONS: ENG:2.0_Liter_Supercharged				
14:31 07OCT24	12:44 10OCT24					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
			ISPJ				(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE C:	0.00

23278 TIRE PSI VALUES. LEFT 37PSI FRONT RIGHT 37PSI REAR LEFT 37PSI
REAR RIGHT 37PSI

D COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION
99PJ COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION
3238 KESROUANI, ROY LIC#: 3238

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE D:	(N/C)
23278 MPI MPI AVAILABLE IN MYMKARMA							0.00

E** CLIENT REQUEST EST ON A NEW SIMS CARD.
01 VEHICLE INSPECTION

3238 KESROUANI, ROY LIC#: 3238

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE E:	(N/C)
23279 ESTIMATE PROVIDED ESTIMATE ON A NEW SIM CARD. PART IS CURRENTLY OUT OF STOCK.							0.00

DRIVER SIDE DOOR CONTROL INOP.

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ In Person Approval ☐ Telephone ☐ Fax ☐ Computer (Not Allowed)	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	0.00
Revised Estimate	\$			☐ In Person Approval ☐ Telephone ☐ Fax ☐ Computer (Not Allowed)		PARTS AMOUNT	0.00
☐ Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi ☐ Customer declined tire pressure check/inflation service. Initials _____						GAS, OIL, LUBE	0.00
						SUBLET AMOUNT	0.00
						WASTE DISPOSAL COSTS *	0.00
						TOTAL CHARGES	0.00
						LESS INSURANCE	0.00
						SALES TAX	0.00
						PLEASE PAY THIS AMOUNT	0.00

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

NYRBE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

INVOICE

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrta.com

PAGE 1

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

SERVICE ADVISOR: B.A.R. REG.# ARD303078 EPA# CAL000470554
3391 Danny Sanchez

COLOR		YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
		20	JAGUAR F-TYPE		SAJDD1GX4LCK67497		23278/23279		T4566
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP24	DD		14:00 08OCT24			299.00	CASH	10OCT24	
R.O. OPENED		READY		OPTIONS: ENG:2.0 Liter Supercharged					

14:31 07OCT24 12:44 10OCT24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CLIENT STATES THAT THE DRIVERS SIDE DOOR ELECTRONICS DO NOT OPERATE
CHECK AND ADVISE

86 ELECTRICAL

3238 KESROUANI, ROY LIC#: 3238

WJ

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: (N/C)
0.00

23279 BLOWN FUSE. ATTEMPTED TO CONNECT WITH VEHICLE. NO CONNECTION
WAS POSSIBLE. GAINED ACCESS TO ENGINE JUNCTION BOX LEFT AND FOUND FUSE
FL01 IN GOOD CONDITION. GAINED ACCESS TO REAR JUNCTION BOX AND FOUND
FUSE RF 08 BLOWN. OBTAINED RVC NUMBER: TW55OR3S AND REPLACED FUSE RF 08
IN REAR JUNCTION BOX. TOPIX CONNECTION TO VEHICLE IS NOW ESTABLISHED
AND DRIVER DOOR BUTTONS FOR WINDOW OPERATIONS AND DOOR LOCK FEATURES
ARE NOW WORKING NORMALLY.

B CLIENT STATES LOW BATTERY WARNING LIGHT COMES ON THE CLUSTER CHECK
AND ADVISE

86 ELECTRICAL

3238 KESROUANI, ROY LIC#: 3238

WJ

1 T2H33020 BATTERY

1 BAT California Battery Fee

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: (N/C)
0.00

23279 START UP BATTERY FAILURE. CHECKED CODES AND PRINTED FOUND
CODE U3003-16 STORED IN GSM. USING TOPIX CLOUD, STARTED NEW FAULT
WORKFLOW AND FOUND BCM AND GWM SOFTWARE UP TO DATE. PERFORMED IN
VEHICLE BATTERY TEST. RECHARGED BATTERY AND PERFORMED ANOTHER IN
VEHICLE BATTERY TEST. BATTERY FAILED. PERFORMED OUT OF VEHICLE BATTERY
TEST. BATTERY FAILED. OBTAINED RVC NUMBER: RC9F5PLX AND REPLACED START
UP BATTERY. REST BATTERY MONITORING SYSTEM. "LOW BATTERY: MESSAGE IS NO
LONGER DISPLAYED IN INSTRUMENT CLUSTER.

C CUSTOMER STATES RESET ALL TIRE PRESSURES

TP CUSTOMER STATES RESET ALL TIRE PRESSURES

3238 KESROUANI, ROY LIC#: 3238

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ Tech ☐ Test ☐ Road Test (See Attached)		LABOR AMOUNT	
Revised Estimate	\$			☐ Tech ☐ Test ☐ Road Test (See Attached)		PARTS AMOUNT	
						GAS, OIL, LUBE	
						SUBLET AMOUNT	
☐ Tire pressure check/inflation service was performed.						WASTE DISPOSAL COSTS *	
RF: _____ psi LF: _____ psi RR: _____ psi LR: _____ psi						TOTAL CHARGES	
☐ Customer declined tire pressure check/inflation service.						LESS INSURANCE	
Initials: _____						SALES TAX	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						PLEASE PAY THIS AMOUNT	
DATE		CUSTOMER SIGNATURE		AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE			

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

INVOICE

DUPLICATE 1
PAGE 2

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlra.com

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554
SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23278/23282	T4591	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DD			14:00 08OCT24		299.00	CASH	14OCT24
R.O. OPENED		READY	OPTIONS: ENG:2.0 Liter Supercharged				

14:31 07OCT24 15:45 14OCT24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

3238 KESROUANI, ROY LIC#: 3238

WJ

1 T2H33020 BATTERY

1 BAT California Battery Fee

(N/C)

(N/C)

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

23279 START UP BATTERY FAILURE. CHECKED CODES AND PRINTED FOUND
CODE U3003-16 STORED IN GSM. USING TOPIX CLOUD, STARTED NEW FAULT
WORKFLOW AND FOUND BCM AND GWM SOFTWARE UP TO DATE. PERFORMED IN
VEHICLE BATTERY TEST. RECHARGED BATTERY AND PERFORMED ANOTHER IN
VEHICLE BATTERY TEST. BATTERY FAILED. PERFORMED OUT OF VEHICLE BATTERY
TEST. BATTERY FAILED. OBTAINED RVC NUMBER: RC9F5PLX AND REPLACED START
UP BATTERY. REST BATTERY MONITORING SYSTEM. "LOW BATTERY: MESSAGE IS NO
LONGER DISPLAYED IN INSTRUMENT CLUSTER.

C CUSTOMER STATES RESET ALL TIRE PRESSURES

TP CUSTOMER STATES RESET ALL TIRE PRESSURES

3238 KESROUANI, ROY LIC#: 3238

ISPJ

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

23278 TIRE PSI VALUES. LEFT 37PSI FRONT RIGHT 37PSI REAR LEFT 37PSI
REAR RIGHT 37PSI

D COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION

99PJ COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION

3238 KESROUANI, ROY LIC#: 3238

ISPJ

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

23278 MPI MPI AVAILABLE IN MYMKARMA

E** CLIENT REQUEST EST ON A NEW SIMS CARD.

01 VEHICLE INSPECTION

3238 KESROUANI, ROY LIC#: 3238

ISPJ

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ Vehicle Approved ☐ Telephone ☐ Fax ☐ Other (Please Specify)	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	
						PARTS AMOUNT	
						GAS, OIL, LUBE	
						SUBLET AMOUNT	
						WASTE DISPOSAL COSTS *	
						TOTAL CHARGES	
						LESS INSURANCE	
						SALES TAX	
						PLEASE PAY THIS AMOUNT	

☐ Tire pressure check/inflation service was performed.

RFI: _____ psi LF: _____ psi RR: _____ psi LR: _____ psi

☐ Customer declined tire pressure check/inflation service.

Initials

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

INVOICE

DUPLICATE 1
PAGE 1

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jrlla.com

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23278/23282	T4591	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DE			14:00 08OCT24		299.00	CASH	14OCT24
R.O. OPENED		READY		OPTIONS: ENG:2.0_Liter_Supercharged			
14:31 07OCT24		15:45 14OCT24					

LINE	OPCODE	TRCH	TYPE	HOURS	LIST	NET	TOTAL
A CLIENT STATES THAT THE DRIVERS SIDE DOOR ELECTRONICS DO NOT OPERATE							
CHECK AND ADVISE							
86 ELECTRICAL							
3238 KESROUANI, ROY LIC#: 3238							
WJ							
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	(N/C) 0.00

23279 LEFT ENGINE JUNCTION BOX TO REAR JUNCTION BOX CIRCUIT SHORT
CIRCUIT TO GROUND ATTEMPTED TO CONNECT WITH VEHICLE. NO CONNECTION WAS
POSSIBLE. GAINED ACCESS TO ENGINE JUNCTION BOX LEFT AND FOUND FUSE FL01
IN GOOD CONDITION. GAINED ACCESS TO REAR JUNCTION BOX AND FOUND FUSE RF
08 BLOWN. OBTAINED RVC NUMBER: TW55OR3S AND REPLACED FUSE RF 08 IN REAR
JUNCTION BOX. TOPIX CONNECTION TO VEHICLE IS NOW ESTABLISHED AND DRIVER
DOOR BUTTONS FOR WINDOW OPERATIONS AND DOOR LOCK FEATURES ARE NOW
WORKING NORMALLY. DROVE 2 MILES, FUSE RF08 BLEW AGAIN AND DRIVER DOOR
ELECTRONICS STOPPED WORKING. REMOVED DRIVER DOOR TRIM PANEL. REMOVED
DRIVER FOOT WELL LOWER TRIM PANEL. REMOVED REAR LEFT LUGGAGE
COMPARTMENT TRIM PANEL. (START OF DIAG TIME) USING ELECTRICAL WIRING
DIAGRAMS CHECKED CIRCUIT FROM DRIVER DOOR MODULE TO REAR JUNCTION BOX
CONNECTOR TO FROM CAPW02BD-14 TO CABR02D-1 FOUND 0.2 OHMS. CHECKED
CIRCUIT FROM DIAGNOSTIC CONNECTOR TO LEFT ENGINE JUNCTION BOX FROM
C2DB04B-16 TO C1BB01A-16 FOUND 0.2 OHMS. CHECKED CIRCUIT FROM LEFT
ENGINE JUNCTION BOX TO REAR JUNCTION BOX FROM C1BB01A-15 TO C4BR02D-1
FOUND 1.8 OHMS TO 3 OHMS VARIABLE READING. DETERMINED HIGH RESISTANCE.
CHECKED HARNESS AND FOUND CIRCUIT FROM CONNECTOR C13H-13 TO LEFT ENGINE
JUNCTION BOX AT C1BB01A-15 SHORTED TO GROUND WHERE DRIVER RESTS HIS/HER
LEFT FOOT UNDERNEATH THE CARPET. OBTAINED RVC NUMBER: TAKITXQX.
PERFORMED HARNESS REPAIR FROM C13H-13 TO C1BB01A-15. REFITTED DRIVER
DOOR TRIM PANEL;. REFITTED LEFT SIDE LUGGAGE COMPARTMENT TRIM PANEL.
REFITTED DRIVER FOOT WELL LOWER PANEL. CLEARED ALL CODES. DRIVER DOOR
ELECTRONICS ARE NOW WORKING CORRECTLY.

B CLIENT STATES LOW BATTERY WARNING LIGHT COMES ON THE CLUSTER CHECK
AND ADVISE
86 ELECTRICAL

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ In-Shop Approval ☐ Telephone ☐ Text ☐ Signature (See Attachment) ☐ In Person Approval ☐ Telephone ☐ Text ☐ Other (See Attachment)	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	
				PARTS AMOUNT			
				GAS, OIL, LUBE			
				SUBLET AMOUNT			
				WASTE DISPOSAL COSTS *			
Revised Estimate \$	\$					TOTAL CHARGES	
☐ Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi ☐ Customer declined tire pressure check/inflation service. Initials _____						LESS INSURANCE	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						SALES TAX	
DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE				PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

INVOICE

DUPLICATE 1
PAGE 1

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jrlla.com

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23278/23282	T4591	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DE			14:00 08OCT24		299.00	CASH	14OCT24
R.O. OPENED		READY		OPTIONS: ENG:2.0_Liter_Supercharged			
14:31 07OCT24		15:45 14OCT24					

LINE	OPCODE	TRCH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CLIENT STATES THAT THE DRIVERS SIDE DOOR ELECTRONICS DO NOT OPERATE
CHECK AND ADVISE

86 ELECTRICAL

3238 KESROUANI, ROY LIC#: 3238

WJ

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

23279 LEFT ENGINE JUNCTION BOX TO REAR JUNCTION BOX CIRCUIT SHORT
CIRCUIT TO GROUND ATTEMPTED TO CONNECT WITH VEHICLE. NO CONNECTION WAS
POSSIBLE. GAINED ACCESS TO ENGINE JUNCTION BOX LEFT AND FOUND FUSE FL01
IN GOOD CONDITION. GAINED ACCESS TO REAR JUNCTION BOX AND FOUND FUSE RF
08 BLOWN. OBTAINED RVC NUMBER: TW55OR3S AND REPLACED FUSE RF 08 IN REAR
JUNCTION BOX. TOPIX CONNECTION TO VEHICLE IS NOW ESTABLISHED AND DRIVER
DOOR BUTTONS FOR WINDOW OPERATIONS AND DOOR LOCK FEATURES ARE NOW
WORKING NORMALLY. DROVE 2 MILES, FUSE RF08 BLEW AGAIN AND DRIVER DOOR
ELECTRONICS STOPPED WORKING. REMOVED DRIVER DOOR TRIM PANEL. REMOVED
DRIVER FOOT WELL LOWER TRIM PANEL. REMOVED REAR LEFT LUGGAGE
COMPARTMENT TRIM PANEL. (START OF DIAG TIME) USING ELECTRICAL WIRING
DIAGRAMS CHECKED CIRCUIT FROM DRIVER DOOR MODULE TO REAR JUNCTION BOX
CONNECTOR TO FROM CAPW02BD-14 TO CABR02D-1 FOUND 0.2 OHMS. CHECKED
CIRCUIT FROM DIAGNOSTIC CONNECTOR TO LEFT ENGINE JUNCTION BOX FROM
C2DB04B-16 TO C1BB01A-16 FOUND 0.2 OHMS. CHECKED CIRCUIT FROM LEFT
ENGINE JUNCTION BOX TO REAR JUNCTION BOX FROM C1BB01A-15 TO C4BR02D-1
FOUND 1.8 OHMS TO 3 OHMS VARIABLE READING. DETERMINED HIGH RESISTANCE.
CHECKED HARNESS AND FOUND CIRCUIT FROM CONNECTOR C13H-13 TO LEFT ENGINE
JUNCTION BOX AT C1BB01A-15 SHORTED TO GROUND WHERE DRIVER RESTS HIS/HER
LEFT FOOT UNDERNEATH THE CARPET. OBTAINED RVC NUMBER: TAKITXQX.
PERFORMED HARNESS REPAIR FROM C13H-13 TO C1BB01A-15. REFITTED DRIVER
DOOR TRIM PANEL;. REFITTED LEFT SIDE LUGGAGE COMPARTMENT TRIM PANEL.
REFITTED DRIVER FOOT WELL LOWER PANEL. CLEARED ALL CODES. DRIVER DOOR
ELECTRONICS ARE NOW WORKING CORRECTLY.

B CLIENT STATES LOW BATTERY WARNING LIGHT COMES ON THE CLUSTER CHECK
AND ADVISE

86 ELECTRICAL

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ In-Shop Approval ☐ Telephone ☐ Text ☐ Signature (See Attachment) ☐ In Person Approval ☐ Telephone ☐ Text ☐ Other (See Attachment)	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	
				PARTS AMOUNT			
				GAS, OIL, LUBE			
				SUBLET AMOUNT			
				WASTE DISPOSAL COSTS *			
Revised Estimate \$	\$					TOTAL CHARGES	
☐ Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi ☐ Customer declined tire pressure check/inflation service. Initials _____						LESS INSURANCE	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						SALES TAX	
DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE				PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

- ☐ Inspect transmission mounts
- ☒ Inspect steering components
- ☒ Inspect sway bar components
- ☒ Inspect rear suspension components
- ☒ Inspect axles, driveshaft(s), u-joints and CV joints/boots

OTHER COMMENTS

Windshield washer fluid

filled as needed - YES

Check and adjust tire pressures

Front Left - 37psi

Rear Left - 37psi

Front Right - 37psi

Rear Right - 37psi

SUMMARY OF VISIT:

Total Estimate:	\$6,870.22
-----------------	------------

	Approved	Declined	Undecided
Pre-approved amount:	\$0.00	-	-
Recommended amount:	\$282.03	\$0.00	\$6,274.90
Taxes:	\$12.59	\$0.00	\$300.70
Total:	\$294.62	\$0.00	\$6,575.60

40 Passed Inspection

UNDER HOOD: FLUIDS AND FILTERS

- ✓ Inspect drive belts
- ✓ Inspect hood and decklid struts
- ✓ Inspect all hoses and clamps
- ✓ Inspect cabin air/HEPA micro filter(if equipped) at 15k or year intervals
- ✓ Check brake fluid level and condition

BATTERY PERFORMANCE

- ✓ Perform visual battery inspection
- ✓ Inspect battery terminal and cables

LIGHTS

- ✓ Instrument cluster warning lamps
- ✓ Inspect headlights, low and high beam operation
- ✓ Inspect fog/driving lights (if applicable)
- ✓ Inspect taillight, turn signal, side marker and license plate lights
- ✓ Inspect taillight, turn signal and side marker assemblies for cracks and damage
- ✓ Inspect brake light operation
- ✓ Inspect hazard light operation
- ✓ Inspect reverse light operation
- ✓ Inspect dash and interior lights
- ✓ Check horn operation

UNDER CAR: SUSPENSION, DRIVELINE, EXHAUST, LEAKS

- ✓ Inspect Engine for oil leaks
- ✓ Inspect brake system for leaks
- ✓ Inspect transmission for leaks
- ✓ Inspect steering system for leaks
- ✓ Check front differential for leaks
- ✓ Check rear differential for leaks
- ✓ Inspect transfer case for leaks(if applicable)
- ✓ Inspect fuel tank, lines and connections
- ✓ Inspect exhaust system for leaks, damage and loose parts
- ✓ Inspect engine mounts
- ✓ Inspect front suspension components
- ✓

GENERAL

- ✓ Inspect wiper and washer operation
- ✓ Inspect windshield wiper blades
- ✓ Inspect rear wiper blade (if applicable)

OTHER

- ✓ Inspect heat and air conditioning operation

TIRES AND ALIGNMENT

- ✓ Tread Depth Measurements - Fronts
Front Left - 8/32+/32nds
Front Right - 8/32+/32nds
- ✓ Tread Depth Measurements - Rears
Rear Left - 7/32/32nds
Rear Right - 7/32/32nds
- ✓ Inspect overall tire wear and condition

5 Needs Immediate Attention

UNDER HOOD: FLUIDS AND FILTERS

 Inspect air cleaner element at 15k or 1 year intervals Replace the Cabin Air Filter CONTAMINATED RENEW	Repair Estimate: \$183.03
---	---------------------------

BRAKES

 Brake Linings Thickness - Rear Rear Pads - 3mm Replace Rear Brake Pads and Rotors DUE TO LOW PADS AND WORN ROTORS	Repair Estimate: \$2,212.22
---	-----------------------------

UNDER CAR: SUSPENSION, DRIVELINE, EXHAUST, LEAKS

 Inspect engine cooling system for leaks REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE	Repair Estimate: \$294.62
---	---------------------------

CUSTOM RECOMMENDATION

 OIL SERVICE OIL LOW AND DIRTY RECOMMEND RENEWAL OF OIL AND ENGINE OIL FILTER	Repair Estimate: \$554.63
 REAR CAMERA MISALIGNMENT REFITTING OF REAR BUMPER FOR REAR CAMERA ADJUSTMENT	Repair Estimate: \$956.80

1 Needs Attention Soon

BRAKES

 Brake Linings Thickness - Front Front Brakes - 4mm Replace Front Brake Pads and Rotors with brake wear sensor DUE TO LOW PADS AND WORN ROTORS	Repair Estimate: \$2,668.92
---	-----------------------------

Multi-Point Inspection Summary

Thursday, November 21, 2024 03:33 PM
RO# 825649



CUSTOMER INFORMATION
Nyree Hinton
+17329796264, +17329796264

CAR INFORMATION
Jaguar
2020 F-Type
SAJDD1GX4LCK67497
Mileage: 23963
Tag # T4486

SERVICE ADVISOR INFO
DANNY SANCHEZ
(424) 329-5332
TECHNICIAN
Robert Salcido

ORIGINAL CUSTOMER REQUESTS

OTHER

 CUSTOMER STATES RESET ALL TIRE PRESSURES	Original Approved: \$0.00 Total Approved: \$0.00
 COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION	Original Approved: \$0.00 Total Approved: \$0.00
 I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM MY VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE RESPONSIBLE FOR THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE. _____	Original Approved: \$0.00 Total Approved: \$0.00
 UBER VOUCHER COMPLIMENTARY RIDE SERVICE	Original Approved: \$0.00 Total Approved: \$0.00

Payment Received for Order Ref # 825649 , Amount \$294.62

From myKaarma Payments <jlrlajlrlaca-jaguarlandroverlos@kaarmadealer.com>

Date Thu 11/21/2024 4:09 PM

To Danny Sanchez <dsanchez@jlrla.com>; payments@kaarya.com <payments@kaarya.com>

Jaguar Land Rover Los Angeles

400 S La Brea Ave
Los Angeles, CA 90036

RECEIPT

Customer Information:

Nyree Hinton

Invoice Details:

Invoice #: 00M2W4ZE2K

Invoice Date: Thursday, November 21, 2024, 04:08 PM

Repair Order/Ref #: 825649

Description of Product/Services

Amount

Service Performed

\$294.62

Payment Details:

Paid On: Thursday, November 21, 2024, 04:09 PM

Payment Type: Chip

Creditcard: XXXXXXXXXXXX2000 Exp: XX/XXXX

Card Type: Amex

Cardholder Name: NA

Approval Code: 479385

Dealer Associate: DANNY SANCHEZ

Cashier: DANNY SANCHEZ

Vehicle Information:

2020 Jaguar F-Type

Tag #: T4486

License Plate:

VIN: SAJDD1GX4LCK67497

THANK YOU!

Customer Signature

825649



JAGUAR LAND ROVER LOS ANGELES

400 S. La Brea Avenue
Los Angeles CA 90038
(310) 274-5133
www.irla.com

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

* INVOICE *

PAGE 3

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23963/23964	T4486
DEL DATE	BROD DATE	WARR EXP	SERVICE			

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24			17:00 18NOV24		299.00	CASH	21NOV24

R.O. OPENED	READY	OPTIONS: ENG:2.0 Liter Supercharged
-------------	-------	-------------------------------------

15:56 18NOV24	15:32 21NOV24
---------------	---------------

LINE	OPCODE	TECH	TYPE	HOURS
1	0000	0000	0000	0000
2	0000	0000	0000	0000
3	0000	0000	0000	0000
4	0000	0000	0000	0000
5	0000	0000	0000	0000
6	0000	0000	0000	0000
7	0000	0000	0000	0000
8	0000	0000	0000	0000
9	0000	0000	0000	0000
10	0000	0000	0000	0000
11	0000	0000	0000	0000
12	0000	0000	0000	0000
13	0000	0000	0000	0000
14	0000	0000	0000	0000
15	0000	0000	0000	0000
16	0000	0000	0000	0000
17	0000	0000	0000	0000
18	0000	0000	0000	0000
19	0000	0000	0000	0000
20	0000	0000	0000	0000
21	0000	0000	0000	0000
22	0000	0000	0000	0000
23	0000	0000	0000	0000
24	0000	0000	0000	0000
25	0000	0000	0000	0000
26	0000	0000	0000	0000
27	0000	0000	0000	0000
28	0000	0000	0000	0000
29	0000	0000	0000	0000
30	0000	0000	0000	0000
31	0000	0000	0000	0000
32	0000	0000	0000	0000
33	0000	0000	0000	0000
34	0000	0000	0000	0000
35	0000	0000	0000	0000
36	0000	0000	0000	0000
37	0000	0000	0000	0000
38	0000	0000	0000	0000
39	0000	0000	0000	0000
40	0000	0000	0000	0000
41	0000	0000	0000	0000
42	0000	0000	0000	0000
43	0000	0000	0000	0000
44	0000	0000	0000	0000
45	0000	0000	0000	0000
46	0000	0000	0000	0000
47	0000	0000	0000	0000
48	0000	0000	0000	0000
49	0000	0000	0000	0000
50	0000	0000	0000	0000
51	0000	0000	0000	0000
52	0000	0000	0000	0000
53	0000	0000	0000	0000
54	0000	0000	0000	0000
55	0000	0000	0000	0000
56	0000	0000	0000	0000
57	0000	0000	0000	0000
58	0000	0000	0000	0000
59	0000	0000	0000	0000
60	0000	0000	0000	0000
61	0000	0000	0000	0000
62	0000	0000	0000	0000
63	0000	0000	0000	0000
64	0000	0000	0000	0000
65	0000	0000	0000	0000
66	0000	0000	0000	0000
67	0000	0000	0000	0000
68	0000	0000	0000	0000
69	0000	0000	0000	0000
70	0000	0000	0000	0000
71	0000	0000	0000	0000
72	0000	0000	0000	0000
73	0000	0000	0000	0000
74	0000	0000		

LIST	NET	TOTAL
------	-----	-------

***** LIST *****

ESTIMATE: 299.00 18NOV24 15:56 SA: 3391

CONTACT:

VEHICLE COMPLETED 11/21/24

JAGUAR

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
1	\$			☐ In Person Approval ☐ Telephone ☐ Fax ☐ On/Off (See Authorized)		LABOR AMOUNT	149.50
Revised Estimate	\$			☐ In Person Approval ☐ Telephone ☐ Fax ☐ On/Off (See Authorized)		PARTS AMOUNT	132.53
☐ Tire pressure check/inflation service was performed. R# _____ psi LF _____ psi RR _____ psi LR _____ psi ☐ Customer declined tire pressure check/inflation service. _____ Initials _____						GAS, OIL, LUBE	0.00
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						SUBLET AMOUNT	0.00
DATE						WASTE DISPOSAL COSTS *	0.00
CUSTOMER SIGNATURE						TOTAL CHARGES	282.03
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE						LESS INSURANCE	0.00
					☐ ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	SALES TAX	12.59
						PLEASE PAY THIS AMOUNT	294.62

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER COPY

CUSTOMER #: 10012996

825649



JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

INVOICE

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlr.com

PAGE 2

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

SERVICE ADVISOR: 3391 Danny Sanchez
B.A.R. REG.# ARD303078 EPA# CAL000470554

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23963/23964	T4486

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DE			17:00 18NOV24		299.00	CASH	21NOV24

R.O. OPENED	READY	OPTIONS:
15:56 18NOV24	15:32 21NOV24	ENG:2.0_Liter_Supercharged

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

RESPONSIBLE FOR THE LOSS OR DAMAGE OF ANY
ITEMS LEFT IN MY VEHICLE.

999 ISPJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: (N/C)
0.00

E UBER VOUCHER COMPLIMENTARY RIDE SERVICE
UBER VOUCHER COMPLIMENTARY RIDE SERVICE

999 ISPJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: (N/C)
0.00

F** REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE

01 REPLACE EXPANSION TANK TO BLEED PIPE DUE TO
LEAK FROM PIPE

40169 CPL

1 T2R47919 HOSE

1 T2H59152 ANTIFREEZE

PARTS: 132.53 LABOR: 149.50 OTHER: 0.00 TOTAL LINE F: 282.03

23964 REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE
PRESSURE TESTED COOLING SYSTEM FOUND BLEED PIPE FROM EXPANSION TANK
LEAKING COOLANT. USING TOPIX CLOUD, STARTED A NEW FAULT WORK FLOW AND
ACQUIRED RVC 'TYKTIUC0'. REMOVED LEAKING BLEED PIPE AND REFITTED NEW
EXPANSION TANK BLEED PIPE. VACUUM FILLED EXPANSION TANK WITH COOLANT TO
CORRECT LEVEL. AFTER TEST DRIVE NO LEAKS WERE FOUND.

ESTIMATE: 593.62 21NOV24 12:18 SA: 3391

CONTACT:

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ In House Approval ☐ Telephone ☐ Fax ☐ Email (Not Approved) ☐ In Person Approval ☐ Telephone ☐ Fax ☐ Email (Not Approved)	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	
Revised Estimate	\$					PARTS AMOUNT	
						GAS, OIL, LUBE	
						SUBLET AMOUNT	
						WASTE DISPOSAL COSTS *	
☐ Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi ☐ Customer declined tire pressure check/inflation service.						TOTAL CHARGES	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						LESS INSURANCE	
DATE	CUSTOMER SIGNATURE		AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE			SALES TAX	
						PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.

CUSTOMER #: 10012996

825649



INVOICE

JAGUAR LAND ROVER LOS ANGELES

400 S. La Brea Avenue
Los Angeles CA 90038
(310) 274-5133
www.jlr-la.com

NYREE HINTON

616 MASSELIN AVE APT 210
Los Angeles, CA 90036

HOME: CONT: 732-979-6264

BUS: CELL: 732-979-6264

PAGE 1

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23963/23964	T4486
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
30SEP24 DI			17:00 18NOV24		299.00	CASH
R.O. OPENED	READY	OPTIONS: ENG:2.0_Liter_Supercharged				
15:56 18NOV24	15:32 21NOV24					
						INV. DATE
						21NOV24

LINE OPCODE TECH TYPE HOURS

A COOLING SYSTEM CLIENT STATES LOW COOLANT WARNING LIGHT IS ON CLIENT LIST NET TOTAL

REQUEST GOOD WILL BE SENT FOR REPAIRS VEHICLE WARRANTY EXPIRED
11/08/24 CLIENT ATTEMPTED TO BRING THE VEHICLE IN ON 11/07/24
BUT WAS UNABLE TO GET AN APPT UNTIL 11/18/24 CRC 8001315826

26 COOLING SYSTEM

40169 ISPJ

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: (N/C)
23964 REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE 0.00
PRESSURE TESTED COOLING SYSTEM FOUND BLEED PIPE FROM EXPANSION TANK
LEAKING COOLANT.

B CUSTOMER STATES RESET ALL TIRE PRESSURES

TP CUSTOMER STATES RESET ALL TIRE PRESSURES

40169 ISPJ

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: (N/C)
23964 LEFT 37PSI FRONT RIGHT 37PSI REAR LEFT 37PSI REAR RIGHT 37PSI 0.00

C COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION

99PJ COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION

40169 ISPJ

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: (N/C)
23963 mpi MPI AVAILABLE IN MYKAARMA 0.00

D I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM MY
VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE RESPONSIBLE FOR
THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE.

CAUSE: I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM
MY VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE RESPONSIBLE
FOR THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE.

100 I HAVE BEEN ADVISED AND I HAVE REMOVED
EVERYTHING OF VALUE FROM MY VEHICLE. I
UNDERSTAND THAT JLR LA WILL NOT BE

Original Estimate (Parts & Labor)	Total Additional Costs Authorized	Approved By	Date & Time	Authorized Signature
\$	\$			
Revised Estimate				
\$	\$			

☐ Tire pressure check/inflation service was performed.
RF: psi LF: psi RR: psi LR: psi
☐ Customer declined tire pressure check/inflation service.

By signing below, you acknowledge that you were notified of and authorized the
Dealership to perform the services/repairs itemized in this invoice and that you received
for had the opportunity to inspect any replaced parts as requested by you.

DATE CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

*HAZARDOUS WASTE DISPOSAL
COSTS: We have added this
charge to cover costs associated
with the handling, management
and disposal of toxic wastes or
hazardous substances under
California and Federal Law.

ALL PARTS ARE NEW
UNLESS OTHERWISE
INDICATED.

☐ Some Parts Not Returnable

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
WASTE DISPOSAL COSTS *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.

CUSTOMER COPY

NYREE HINTON

INVOICE

Invoice #: **908960**

Jaguar Land Rover South Bay

3233 Pacific Coast Highway
Torrance, CA 90505-6613
Phone: (310) 798-0550

Tag #: **124=**

Home: Bus: Customer #: **7913668**

Cell: 732-979-6264 Email: na@na.com/home

Service Advisor: **7814 JOEL CRUZ**

BAR REG. # AJ229534

E.P.A.# CAD981683915

COLOR		YEAR		MAKE/MODEL		VIN		LICENSE		MILEAGE IN		MILEAGE OUT							
		20		JAGUAR F-TYPE		SAJDD1GX4LCK67497				23072		23073							
DEL DATE		PROD. DATE		WARR. EXP.		PROMISED		PO NO.		RATE		PAYMENT		INV. DATE		R.O. OPENED		READY	
01JAN20 D						18:00 18OCT24				0.00		CASH		02OCT24		17:59 01OCT24		14:36 02OCT24	
OPTIONS: DLR:0146																			

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty.

We also offer high quality non-OE parts that are suitable for your vehicle and fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP." These non-OE (AP*) parts are not sourced from the vehicle's manufacturer or covered by its warranty. Non-OE parts come with a limited warranty backed by AutoNation and/or the parts manufacturer.*

C PERFORM TIRE PRESSURE SERVICE
TPS PERFORM TIRE PRESSURE SERVICE
8784 CR
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00
23072 SET TIRES PRESSURE TO SPEC

ESTIMATE: 0.00 01OCT24 17:59 SA: 7814

*****THE FOLLOWING WORK WAS RECOMMENDED BUT NOT PERFORMED*****
,, DESCRIPTION: PPBPR AutoNation Parts - Aftermarket REAR BRAKE PADS/SHOES
,, REASON DENIED: LAT Customer will have work performed later
,, PERSON CONTACTED: NYREE HINTON
,, COMMENTS: None
,, RECOMMENDED BY: 7814 CRUZ DENIAL ADDED BY: 7814 CRUZ
,, LINE ASSOCIATED: ESTIMATE: 696.70
,, DESCRIPTION: B151A064000 Service - 64,000 Miles
,, REASON DENIED: LAT Customer will have work performed later
,, PERSON CONTACTED: NYREE HINTON
,, COMMENTS: None
,, RECOMMENDED BY: 7814 CRUZ DENIAL ADDED BY: 7814 CRUZ
,, LINE ASSOCIATED: ESTIMATE: 1428.79

NOTICE TO CONSUMERS: PLEASE READ IMPORTANT INFORMATION ON ATTACHED PAGES.

CALL/TEXT AUTHORIZATION: YOU HEREBY AUTHORIZE US TO MAKE RECURRING CALLS, TEXTS, AND TRANSMIT VOICEMAILS TO YOU AT YOUR PHONE NUMBER(S), INCLUDING BY USE OF AN AUTOMATED SYSTEM, REGARDING SALES AND/OR SERVICE OF YOUR VEHICLE. YOU UNDERSTAND YOUR AGREEMENT IS NOT A CONDITION OF PURCHASING GOODS OR SERVICES AND YOU MAY OPT OUT YOUR PHONE NUMBER(S) BY NOTIFYING YOUR SERVICE ADVISOR OR TEXTING STOP TO ANY MESSAGE RECEIVED. MSG & DATA RATES MAY APPLY.

If we receive payments related to the goods or services provided hereunder from any third party (e.g., a check under a Service Contract), you agree that we may retain all such monies as if same was a payment from you and apply such funds to any outstanding indebtedness of yours. You hereby grant us a power of attorney to endorse or otherwise sign your name and to deposit such funds into the dealership's account to carry out the intent of this provision.

By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.

I acknowledge notice and oral approval of an increase in the original estimated price.

DATE

CUSTOMER SIGNATURE

HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of hazardous waste or substances under California and Federal Law.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

☐ Some Parts Not Returnable

DESCRIPTION	LABOR AMOUNT	
	PARTS AMOUNT	0.00
	GAS, OIL, LUBE	0.00
	SUBLET AMOUNT	0.00
	MISC. CHARGES	0.00
	TOTAL CHARGES	0.00
	LESS INSURANCE	0.00
	SALES TAX	0.00
	PLEASE PAY THIS AMOUNT	0.00

NYREE HINTON

INVOICE

Invoice #: 908960

Jaguar Land Rover South Bay

3233 Pacific Coast Highway

Torrance, CA 90505-6613

Phone: (310) 798-0550

Home:

Bus:

Customer #: 7913668

BAR REG. # AJ229534

E.P.A.# CAD981683915

Cell: 732-979-6264 Email: na@na.com/home

Service Advisor: 7814 JOEL CRUZ

COLOR										YEAR										MAKE/MODEL										VIN										LICENSE										MILEAGE IN										MILEAGE OUT									
										20										JAGUAR F-TYPE										SAJDD1GX4LCK67497																				23072										23073									
DEL DATE					PROD. DATE					WARR. EXP.					PROMISED					PO NO.					RATE					PAYMENT					INV. DATE					R.O. OPENED					READY																								
01JAN20 D															18:00 18OCT24										0.00					CASH					02OCT24					17:59 01OCT24					14:36 02OCT24																								

OPTIONS: DLR:0146

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty.

We also offer high quality non-OE parts that are suitable for your vehicle and fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP*." These non-OE (AP*) parts are not sourced from the vehicle's manufacturer or covered by its warranty. Non-OE parts come with a limited warranty backed by AutoNation and/or the parts manufacturer.

A CUSTOMER STATES DRIVERS SIDE WINDOW DOES NOT ROLL UP.

CAUSE:

None CUSTOMER STATES DRIVERS SIDE WINDOW DOES NOT ROLL UP.

8784 WJ
0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A:
23072 VERIFIED CUSTOMER CONCERN FOUND WINDOW SWITCH NOT WORKING. CHECK SEAT SWITCH AND IT ALSO NOT WORKING SO IS THE LOCK AND UNLOCK SWITCH NOT WORKING. CHECK FUSE AT THE REAR JUNCTION BOX FOR FRONT LEFT DOOR MODULE AND FUSE WAS BLOWN. CHECK POWER WIRE FOR 12 VOLTS AND GOT 12VOLTS FROM JUNCTION BOX TO LEFT DOOR CONTROL MODULE. CHECK GROUND FROM JUNCTION BOX TO LEFT DOOR MODULE AND THERE WAS A SHORT TO GROUND. REPAIR GROUND WIRE AND REPLACE FUSE AND FUSE DIDN'T BLOW AGAIN. NOW GOT POWER TO LEFT FRONT DOOR MODULE AND WINDOW SWITCH IS NOW WORKING AS IT SHOULD.

(N/C)
0.00

B MULTI-A Customer requested to have Multi Point Inspection performed during this visit

MULTI-A MULTI-A Customer requested to have Multi Point Inspection performed during this visit

8784 CR 0.00 0.00

GTIRE ALL TIRES AT 9/32ND ... MINIMUM IS 3/32ND) 0.00 0.00

YBK FRONT BRAKES AT 6MM ... REAR BRAKES AT 4MM ... MINIMUM IS 3MM) 0.00 0.00

8784 CR 0.00 0.00

GBATT BATTERY TESTS GOOD 0.00 0.00

8784 CR 0.00 0.00

DSRB Declined Rear Brake Replacement 0.00 0.00

8784 CR 0.00 0.00

DSSM Declined Scheduled Maintenance 0.00 0.00

8784 CR 0.00 0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

23072 PERFORMED MPI

NOTICE TO CONSUMERS: PLEASE READ IMPORTANT INFORMATION ON ATTACHED PAGES.

CALL/TEXT AUTHORIZATION: YOU HEREBY AUTHORIZE US TO MAKE RECURRING CALLS, TEXTS, AND TRANSMIT VOICEMAILS TO YOU AT YOUR PHONE NUMBER(S), INCLUDING BY USE OF AN AUTOMATED SYSTEM, REGARDING SALES AND/OR SERVICE OF YOUR VEHICLE. YOU UNDERSTAND YOUR AGREEMENT IS NOT A CONDITION OF PURCHASING GOODS OR SERVICES AND YOU MAY OPT OUT YOUR PHONE NUMBER(S) BY NOTIFYING YOUR SERVICE ADVISOR OR TEXTING STOP TO ANY MESSAGE RECEIVED. MSG & DATA RATES MAY APPLY.

If we receive payments related to the goods or services provided hereunder from any third party (e.g., a check under a Service Contract), you agree that we may retain all such monies as if same was a payment from you and apply such funds to any outstanding indebtedness of yours. You hereby grant us a power of attorney to endorse or otherwise sign your name and to deposit such funds into the dealership's account to carry out the intent of this provision.

By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.

I acknowledge notice and oral approval of an increase in the original estimated price.

HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of hazardous waste or substances under California and Federal Law.

ALL PARTS ARE NEW
UNLESS OTHERWISE
INDICATED.

☐ Some Parts Not Returnable

DESCRIPTION	TOTALS	
	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
TOTALS	LESS INSURANCE	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE

CUSTOMER #: 10012996

825556



NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

WORKORDER

JAGUAR LAND ROVER LOS ANGELES

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrta.com

PAGE 1

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Sanchez, Danny

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23915/	T4466	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DD			13:00 18NOV24		299.00	CASH	
R.O. OPENED		READY		OPTIONS: ENG:2.0_Liter_Supercharged			
14NOV2024 16:34							

LINE OP CODE TECH... TYPE DESCRIPTIONS/INSTRUCTIONS

A CLIENT STATES LOW COOLANT WARNING LIGHT IS ON CLIENT
REQUEST GOOD WILL BE SENT FOR REPAIRS VEHICLE
WARRANTY EXPIRED 11/08/24 CLIENT ATTEMPTED TO BRING
THE VEHICLE IN ON 11/07/24 BUT WAS UNABLE TO GET AN
APPT UNTIL 11/18/24 CRC 8001315826
26 CPJ COOLING SYSTEM
EST: TOTAL 299.00

B TP ISPJ CUSTOMER STATES RESET ALL TIRE PRESSURES

C 99PJ ISPJ COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION

Preliminary Estimate : \$0.00
Current Estimate : \$299.00 14NOV 16:34 SA 3391

TEARDOWN/REASSEMBLY: If you authorize teardown of the vehicle or commencement of repairs, but do not authorize completion of a repair or service, a charge may be imposed for teardown, reassembly or partially completed work and you agree to pay the same.

It is necessary to disassemble the vehicle to provide an estimated price for repairs. The estimated teardown and reassembly charge (including parts and labor) is \$. X

You understand that disassembly may prevent restoration of the vehicle to its former condition. X

☐ **SUBLET REPAIRS:** Some repairs must be sublet due to the type of service required. The location will be disclosed upon request.

PAYMENT TERMS: I agree to pay for all labor and materials in cash or approved credit card (unless the Dealership agrees to other payment arrangements in advance) simultaneously with delivery of the vehicle to me or 3 days after receiving notice that the vehicle is ready to be picked up. An express mechanics lien is hereby acknowledged on the vehicle to secure the cost of labor, materials, storage and/or towing charges. I understand that a storage charge equal to \$125.00 will be assessed and shall accrue daily if I fail to pick up the vehicle within 5 days from the date I am notified that the repairs have been completed or after the communication of an estimate if I fail to authorize repairs.

POWER-OF-ATTORNEY: I hereby appoint the Dealership as my attorney-in-fact and authorize it to sign my name upon any checks, drafts or other forms of payment issued in payment of this Repair Order. X

By Signing Below: I agree that: (1) I have read this Repair Order and I authorize the completion of the services/repairs listed above in accordance with the terms and conditions herein; (2) the Dealership is not responsible for loss or damage to the vehicle or articles left in the vehicle in case of fire, theft, hail, wind or any other cause beyond its control; (3) the Dealership may operate the vehicle on streets, highways or public roadways for the purpose of testing and/or inspecting the vehicle; (4) I authorize the retrieval of on-board data as needed to facilitate vehicle repairs and the sharing of that data with the vehicle manufacturer for diagnostic or research purposes; and (5) I expressly consent to receive text messages, phone calls, and e-mails regarding the repairs/services I request at any telephone number and e-mail address I provide to the Dealership, even if the contact results in a charge to me.

Customer _____ Date _____
Dealer CAR 2021 CR Sheet, 11/21/21 WORKORDER TYPE 2 - 2022 - "AutoMated Warranty" - California - 11/21/21

PARTS: All parts are new unless otherwise indicated. Remanufactured and refurbished parts that meet manufacturer approved source part requirements may be installed at our discretion. Additional information is available upon request. You may inspect all parts removed from the vehicle upon request. If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request.

☐ Some Parts Not Returnable ☐ Please Save Replaced Parts

ESTIMATE: PLEASE CHOOSE THE KIND OF ESTIMATE YOU WANT TO RECEIVE BY INITIALIZING BESIDE ONE OF THE FOLLOWING CHOICES AND INDICATE THE BEST WAY TO CONTACT YOU IF NECESSARY.

WRITTEN ESTIMATE _____ ORAL ESTIMATE _____ ELECTRONIC EST. _____

By Telephone to: _____ By Fax to: _____

By E-Mail to: _____

PRELIMINARY ESTIMATE \$ _____

DESIGNATION OF PERSON TO AUTHORIZE ADDITIONAL DIAGNOSIS, REPAIR, OR PARTS.

I hereby designate the individual named below to authorize any additional work not specified or parts not included in the original estimate for parts and labor.

Name of Designee: _____ Phone Number: _____

Fax Number: _____ E-Mail Address: _____

Customer X _____ Date: _____

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
\$	\$			☐ Telephone
				☐ Text
				☐ Email/Fax (See Attached)
Revised Estimate	\$			☐ Telephone
				☐ Text
				☐ Email/Fax (See Attached)

I acknowledge notice and oral approval of an increase in the original estimated price.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER COPY

CUSTOMER #: 10012996

824373



NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

WORKORDER
REPRINT
PAGE 1

JAGUAR LAND ROVER LOS ANGELES

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jrla.com

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Sanchez, Danny

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23278/	T4566
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
30SEP24 DD			14:00 08OCT24		299.00	CASH
R.O. OPENED	READY	OPTIONS: ENG:2.0_Liter_Supercharged				

07OCT2024 14:31

LINE	OP CODE	TECH...	TYPE	DESCRIPTIONS/INSTRUCTIONS
# A				CLIENT STATES THAT THE DRIVERS SIDE DOOR ELECTRONICS DO NOT OPERATE CHECK AND ADVISE
86			WJ	ELECTRICAL
# B				CLIENT STATES LOW BATTERY WARNING LIGHT COMES ON THE CLUSTER CHECK AND ADVISE
86			WJ	ELECTRICAL
# C	TP		ISPJ	CUSTOMER STATES RESET ALL TIRE PRESSURES
# D	99PJ		ISPJ	COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION
# E *	01		WJ	CLIENT REQUEST EST ON A NEW SIMS CARD. VEHICLE INSPECTION

TEARDOWN/REASSEMBLY: If you authorize teardown of the vehicle or commencement of repairs, but do not authorize completion of a repair or service, a charge may be imposed for teardown, reassembly or partially completed work and you agree to pay the same.

It is necessary to disassemble the vehicle to provide an estimated price for repairs. The estimated teardown and reassembly charge (including parts and labor) is \$.
The maximum time for reassembly will be . X

You understand that disassembly may prevent restoration of the vehicle to its former condition. X

☐ **SUBLET REPAIRS:** Some repairs must be sublet due to the type of service required. The location will be disclosed upon request.

PAYMENT TERMS: I agree to pay for all labor and materials in cash or approved credit card (unless the Dealership agrees to other payment arrangements in advance) simultaneously with delivery of the vehicle to me or 3 days after receiving notice that the vehicle is ready to be picked up. An express mechanics lien is hereby acknowledged on the vehicle to secure the cost of labor, materials, storage and/or towing charges. I understand that a storage charge equal to \$125.00 will be assessed and shall accrue daily if I fail to pick up the vehicle within 5 days from the date I am notified that the repairs have been completed or after the communication of an estimate if I fail to authorize repairs.

POWER-OF-ATTORNEY: I hereby appoint the Dealership as my attorney-in-fact and authorize it to sign my name upon any checks, drafts or other forms of payment issued in payment of this Repair Order. X

By Signing Below: I agree that: (1) I have read this Repair Order and I authorize the completion of the services/repairs listed above in accordance with the terms and conditions herein; (2) the Dealership is not responsible for loss or damage to the vehicle or articles left in the vehicle in case of fire, theft, hail, wind or any other cause beyond its control; (3) the Dealership may operate the vehicle on streets, highways or public roadways for the purpose of testing and/or inspecting the vehicle; (4) I authorize the retrieval of on-board data as needed to facilitate vehicle repairs and the sharing of that data with the vehicle manufacturer for diagnostic or research purposes; and (5) I expressly consent to receive text messages, phone calls, and e-mails regarding the repairs/services I request at any telephone number and e-mail address I provide to the Dealership, even if the contact results in a charge to me.

Customer _____ Date _____
Dealership: 3021 COK Drive, LLC 10821 WORKORDER TYPE 2 - SW20 "Six Month Warranty" CALIFORNIA 90045

PARTS: All parts are new unless otherwise indicated. Remanufactured and refurbished parts that meet manufacturer approved source part requirements may be installed at our discretion. Additional information is available upon request. You may inspect all parts removed from the vehicle upon request. If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request.

☐ Some Parts Not Returnable ☐ Please Save Replaced Parts

ESTIMATE: PLEASE CHOOSE THE KIND OF ESTIMATE YOU WANT TO RECEIVE BY INITIALING BESIDE ONE OF THE FOLLOWING CHOICES AND INDICATE THE BEST WAY TO CONTACT YOU IF NECESSARY.

WRITTEN ESTIMATE _____ ORAL ESTIMATE _____ ELECTRONIC EST. _____

By Telephone to: _____ By Fax to: _____

By E-Mail to: _____

PRELIMINARY ESTIMATE \$ _____

DESIGNATION OF PERSON TO AUTHORIZE ADDITIONAL DIAGNOSIS, REPAIR, OR PARTS.

I hereby designate the individual named below to authorize any additional work not specified or parts not included in the original estimate for parts and labor.

Name of Designee: _____ Phone Number: _____

Fax Number: _____ E-Mail Address: _____

Customer X _____ Date: _____

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
\$	\$			☐ Telephone ☐ Fax ☐ Email/Fax (See Attached)
Revised Estimate	\$			☐ Telephone ☐ Fax ☐ Email/Fax (See Attached)
Description:				

I acknowledge notice and oral approval of an increase in the original estimated price.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER COPY

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

INVOICE

DUPLICATE 1
PAGE 1

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrta.com

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	20	JAGUAR F-TYPE	SAJDD1GX4LCK67497		23278/23282	T4591	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP24 DE			14:00 08OCT24		299.00	CASH	14OCT24
R.O. OPENED		READY		OPTIONS: ENG:2.0_Liter_Supercharged			
14:31 07OCT24		15:45 14OCT24					

LINE	OPCODE	TRCH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CLIENT STATES THAT THE DRIVERS SIDE DOOR ELECTRONICS DO NOT OPERATE
CHECK AND ADVISE

86 ELECTRICAL

3238 KESROUANI, ROY LIC#: 3238

WJ

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

23279 LEFT ENGINE JUNCTION BOX TO REAR JUNCTION BOX CIRCUIT SHORT
CIRCUIT TO GROUND ATTEMPTED TO CONNECT WITH VEHICLE. NO CONNECTION WAS
POSSIBLE. GAINED ACCESS TO ENGINE JUNCTION BOX LEFT AND FOUND FUSE FL01
IN GOOD CONDITION. GAINED ACCESS TO REAR JUNCTION BOX AND FOUND FUSE RF
08 BLOWN. OBTAINED RVC NUMBER: TW55OR3S AND REPLACED FUSE RF 08 IN REAR
JUNCTION BOX. TOPIX CONNECTION TO VEHICLE IS NOW ESTABLISHED AND DRIVER
DOOR BUTTONS FOR WINDOW OPERATIONS AND DOOR LOCK FEATURES ARE NOW
WORKING NORMALLY. DROVE 2 MILES, FUSE RF08 BLEW AGAIN AND DRIVER DOOR
ELECTRONICS STOPPED WORKING. REMOVED DRIVER DOOR TRIM PANEL. REMOVED
DRIVER FOOT WELL LOWER TRIM PANEL. REMOVED REAR LEFT LUGGAGE
COMPARTMENT TRIM PANEL. (START OF DIAG TIME) USING ELECTRICAL WIRING
DIAGRAMS CHECKED CIRCUIT FROM DRIVER DOOR MODULE TO REAR JUNCTION BOX
CONNECTOR TO FROM CAPW02BD-14 TO CABR02D-1 FOUND 0.2 OHMS. CHECKED
CIRCUIT FROM DIAGNOSTIC CONNECTOR TO LEFT ENGINE JUNCTION BOX FROM
C2DB04B-16 TO C1BB01A-16 FOUND 0.2 OHMS. CHECKED CIRCUIT FROM LEFT
ENGINE JUNCTION BOX TO REAR JUNCTION BOX FROM C1BB01A-15 TO C4BR02D-1
FOUND 1.8 OHMS TO 3 OHMS VARIABLE READING. DETERMINED HIGH RESISTANCE.
CHECKED HARNESS AND FOUND CIRCUIT FROM CONNECTOR C13H-13 TO LEFT ENGINE
JUNCTION BOX AT C1BB01A-15 SHORTED TO GROUND WHERE DRIVER RESTS HIS/HER
LEFT FOOT UNDERNEATH THE CARPET. OBTAINED RVC NUMBER: TAKITXQX.
PERFORMED HARNESS REPAIR FROM C13H-13 TO C1BB01A-15. REFITTED DRIVER
DOOR TRIM PANEL;. REFITTED LEFT SIDE LUGGAGE COMPARTMENT TRIM PANEL.
REFITTED DRIVER FOOT WELL LOWER PANEL. CLEARED ALL CODES. DRIVER DOOR
ELECTRONICS ARE NOW WORKING CORRECTLY.

B CLIENT STATES LOW BATTERY WARNING LIGHT COMES ON THE CLUSTER CHECK
AND ADVISE

86 ELECTRICAL

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ In-Shop Approval ☐ Telephone ☐ Text ☐ Signature (See Attachment) ☐ In Person Approval ☐ Telephone ☐ Text ☐ Other (See Attachment)	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. ☐ Some Parts Not Returnable	LABOR AMOUNT	
				PARTS AMOUNT			
				GAS, OIL, LUBE			
				SUBLET AMOUNT			
				WASTE DISPOSAL COSTS *			
Revised Estimate \$	\$					TOTAL CHARGES	
☐ Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi ☐ Customer declined tire pressure check/inflation service. Initials _____						LESS INSURANCE	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						SALES TAX	
DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE				PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER #: 10012996

824373



JAGUAR LAND ROVER LOS ANGELES

NYRBE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

INVOICE

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrta.com

PAGE 1

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

SERVICE ADVISOR: B.A.R. REG.# ARD303078 EPA# CAL000470554
3391 Danny Sanchez

COLOR		YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
		20	JAGUAR F-TYPE		SAJDD1GX4LCK67497		23278/23279		T4566
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP24	DD		14:00 08OCT24			299.00	CASH	10OCT24	
R.O. OPENED		READY		OPTIONS: ENG:2.0 Liter Supercharged					

14:31 07OCT24 12:44 10OCT24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CLIENT STATES THAT THE DRIVERS SIDE DOOR ELECTRONICS DO NOT OPERATE
CHECK AND ADVISE

86 ELECTRICAL

3238 KESROUANI, ROY LIC#: 3238

WJ

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: (N/C)
0.00

23279 BLOWN FUSE. ATTEMPTED TO CONNECT WITH VEHICLE. NO CONNECTION
WAS POSSIBLE. GAINED ACCESS TO ENGINE JUNCTION BOX LEFT AND FOUND FUSE
FL01 IN GOOD CONDITION. GAINED ACCESS TO REAR JUNCTION BOX AND FOUND
FUSE RF 08 BLOWN. OBTAINED RVC NUMBER: TW55OR3S AND REPLACED FUSE RF 08
IN REAR JUNCTION BOX. TOPIX CONNECTION TO VEHICLE IS NOW ESTABLISHED
AND DRIVER DOOR BUTTONS FOR WINDOW OPERATIONS AND DOOR LOCK FEATURES
ARE NOW WORKING NORMALLY.

B CLIENT STATES LOW BATTERY WARNING LIGHT COMES ON THE CLUSTER CHECK
AND ADVISE

86 ELECTRICAL

3238 KESROUANI, ROY LIC#: 3238

WJ

1 T2H33020 BATTERY

1 BAT California Battery Fee

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: (N/C)
0.00

23279 START UP BATTERY FAILURE. CHECKED CODES AND PRINTED FOUND
CODE U3003-16 STORED IN GSM. USING TOPIX CLOUD, STARTED NEW FAULT
WORKFLOW AND FOUND BCM AND GWM SOFTWARE UP TO DATE. PERFORMED IN
VEHICLE BATTERY TEST. RECHARGED BATTERY AND PERFORMED ANOTHER IN
VEHICLE BATTERY TEST. BATTERY FAILED. PERFORMED OUT OF VEHICLE BATTERY
TEST. BATTERY FAILED. OBTAINED RVC NUMBER: RC9F5PLX AND REPLACED START
UP BATTERY. REST BATTERY MONITORING SYSTEM. "LOW BATTERY: MESSAGE IS NO
LONGER DISPLAYED IN INSTRUMENT CLUSTER.

C CUSTOMER STATES RESET ALL TIRE PRESSURES

TP CUSTOMER STATES RESET ALL TIRE PRESSURES

3238 KESROUANI, ROY LIC#: 3238

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			☐ Tech ☐ Test ☐ Road Test (See Attached)		LABOR AMOUNT	
Revised Estimate				☐ Tech ☐ Test ☐ Road Test (See Attached)		PARTS AMOUNT	
						GAS, OIL, LUBE	
						SUBLET AMOUNT	
☐ Tire pressure check/inflation service was performed.						WASTE DISPOSAL COSTS *	
RF: _____ psi LF: _____ psi RR: _____ psi LR: _____ psi						TOTAL CHARGES	
☐ Customer declined tire pressure check/inflation service.						LESS INSURANCE	
Initials: _____						SALES TAX	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						PLEASE PAY THIS AMOUNT	
DATE		CUSTOMER SIGNATURE		AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE			

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT
INFORMATION ON BACK.