

CUSTOMER #: 10012996

825649



INVOICE

JAGUAR LAND ROVER LOS ANGELES

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrla.com

NYREE HINTON

616 MASSELIN AVE APT 210
Los Angeles, CA 90036

HOME: CONT: 732-979-6264

BUS: CELL: 732-979-6264

PAGE 1

B.A.R. REG.# ARD303078 EPA# CAL000470554

SERVICE ADVISOR: 3391 Danny Sanchez

COLOR		YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
		20	JAGUAR F-TYPE		SAJDD1GX4LCK67497		23963/23964		T4486
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP24 DD			17:00 18NOV24			299.00	CASH	21NOV24	
R.O. OPENED		READY		OPTIONS: ENG:2.0_Liter_Supercharged					

15:56 18NOV24 15:32 21NOV24

LINE OPCODE TECH TYPE HOURS

	LIST	NET	TOTAL
A COOLING SYSTEM CLIENT STATES LOW COOLANT WARNING LIGHT IS ON CLIENT REQUEST GOOD WILL BE SENT FOR REPAIRS VEHICLE WARRANTY EXPIRED 11/08/24 CLIENT ATTEMPTED TO BRING THE VEHICLE IN ON 11/07/24 BUT WAS UNABLE TO GET AN APPT UNTIL 11/18/24 CRC 8001315826			
26 COOLING SYSTEM			
40169 ISPJ			
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A:			(N/C) 0.00
23964 REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE PRESSURE TESTED COOLING SYSTEM FOUND BLEED PIPE FROM EXPANSION TANK LEAKING COOLANT.			

B CUSTOMER STATES RESET ALL TIRE PRESSURES
TP CUSTOMER STATES RESET ALL TIRE PRESSURES
40169 ISPJ

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: (N/C) 0.00

23964 LEFT 37PSI FRONT RIGHT 37PSI REAR LEFT 37PSI REAR RIGHT 37PSI

C COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION
99PJ COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION
40169 ISPJ

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: (N/C) 0.00

23963 mpi MPI AVAILABLE IN MYKAARMA

D I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM MY VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE RESPONSIBLE FOR THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE.

CAUSE: I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM MY VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE RESPONSIBLE FOR THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE.

100 I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM MY VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)
Revised Estimate \$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)

☐ Tire pressure check/inflation service was performed.
RF _____ psi LF _____ psi RR _____ psi LR _____ psi

☐ Customer declined tire pressure check/inflation service.

Initials

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

☐ Some Parts Not Returnable

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
WASTE DISPOSAL COSTS *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER #: 10012996

825649



JAGUAR LAND ROVER LOS ANGELES

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

INVOICE

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrla.com

PAGE 2

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554
SERVICE ADVISOR: 3391 Danny Sanchez

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
	20	JAGUAR F-TYPE		SAJDD1GX4LCK67497			23963 / 23964		T4486
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP24 DD			17:00 18NOV24			299.00	CASH	21NOV24	
R.O. OPENED		READY		OPTIONS: ENG:2.0_Liter_Supercharged					

15:56 18NOV24 15:32 21NOV24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
RESPONSIBLE FOR THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE.							

999 ISPJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: (N/C)
0.00

E UBER VOUCHER COMPLIMENTARY RIDE SERVICE
UBER VOUCHER COMPLIMENTARY RIDE SERVICE

999 ISPJ
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: (N/C)
0.00

F** REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE
01 REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE

40169 CPL 149.50 149.50
1 T2R47919 HOSE 89.33 89.33 89.33
1 T2H59152 ANTIFREEZE 43.20 43.20 43.20
PARTS: 132.53 LABOR: 149.50 OTHER: 0.00 TOTAL LINE F: 282.03

23964 REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE
PRESSURE TESTED COOLING SYSTEM FOUND BLEED PIPE FROM EXPANSION TANK
LEAKING COOLANT. USING TOPIX CLOUD, STARTED A NEW FAULT WORK FLOW AND
ACQUIRED RVC 'TYKTIUC0'. REMOVED LEAKING BLEED PIPE AND REFITTED NEW
EXPANSION TANK BLEED PIPE. VACUUM FILLED EXPANSION TANK WITH COOLANT TO
CORRECT LEVEL. AFTER TEST DRIVE NO LEAKS WERE FOUND.

ESTIMATE: 593.62 21NOV24 12:18 SA: 3391

CONTACT:

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By
\$	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)
Revised Estimate	\$			☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)

☐ Tire pressure check/inflation service was performed.
RF _____ psi LF _____ psi RR _____ psi LR _____ psi
☐ Customer declined tire pressure check/inflation service.

Initials

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.

ALL PARTS ARE NEW
UNLESS OTHERWISE
INDICATED.

☐ Some Parts Not Returnable

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
WASTE DISPOSAL COSTS *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER #: 10012996

825649



INVOICE

JAGUAR LAND ROVER LOS ANGELES

400 S. La Brea Avenue
Los Angeles CA 90036
(310) 274-5133
www.jlrta.com

NYREE HINTON
616 MASSELIN AVE APT 210
Los Angeles, CA 90036

PAGE 3

HOME: CONT: 732-979-6264
BUS: CELL: 732-979-6264

B.A.R. REG.# ARD303078 EPA# CAL000470554
SERVICE ADVISOR: 3391 Danny Sanchez



COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
	20	JAGUAR F-TYPE		SAJDD1GX4LCK67497			23963/23964		T4486
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP24 DD			17:00 18NOV24			299.00	CASH	21NOV24	
R.O. OPENED		READY		OPTIONS: ENG:2.0_Liter_Supercharged					

15:56 18NOV24 15:32 21NOV24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

ESTIMATE: 299.00 18NOV24 15:56 SA: 3391
CONTACT:

VEHICLE COMPLETED 11/21/24



Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By ☐ In Person Approval ☐ Telephone ☐ Text ☐ Email/Fax (See Attached)	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$					LABOR AMOUNT	149.50
Revised Estimate	\$					PARTS AMOUNT	132.53
						GAS, OIL, LUBE	0.00
						SUBLET AMOUNT	0.00
						WASTE DISPOSAL COSTS *	0.00
						TOTAL CHARGES	282.03
						LESS INSURANCE	0.00
						SALES TAX	12.59
						PLEASE PAY THIS AMOUNT	294.62

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER COPY



Outlook

Payment Received for Order Ref # 825649 , Amount \$294.62

From myKaarma Payments <jlrlajlrlaca-jaguarlandroverlos@kaarmadealer.com>

Date Thu 11/21/2024 4:09 PM

To Danny Sanchez <dsanchez@jlrla.com>; payments@kaarya.com <payments@kaarya.com>

Jaguar Land Rover Los Angeles

400 S La Brea Ave
Los Angeles, CA 90036

RECEIPT

Customer Information:

Nyree Hinton

Invoice Details:

Invoice #: 00M2W4ZE2K

Invoice Date: Thursday, November 21, 2024, 04:08 PM

Repair Order/Ref #: 825649

Description of Product/Services

Amount

Service Performed

\$294.62

Payment Details:

Paid On: Thursday, November 21, 2024, 04:09 PM

Payment Type: Chip

Creditcard: XXXXXXXXXXXX2000 Exp: XX/XXXX

Card Type: Amex

Cardholder Name: NA

Approval Code: 479385

Dealer Associate: DANNY SANCHEZ

Cashier: DANNY SANCHEZ

Vehicle Information:

2020 Jaguar F-Type

Tag #: T4486

License Plate:

VIN: SAJDD1GX4LCK67497

THANK YOU!

Customer Signature

Jaguar Land Rover Los Angeles

Processed by myKaarma

Multi-Point Inspection Summary

Thursday, November 21, 2024 03:33 PM

RO# 825649



CUSTOMER INFORMATION

Nyree Hinton

+17329796264, +17329796264

CAR INFORMATION

Jaguar

2020 F-Type

SAJDD1GX4LCK67497

Mileage: 23963

Tag # T4486

SERVICE ADVISOR INFO

DANNY SANCHEZ

(424) 329-5332

TECHNICIAN

Robert Salcido

ORIGINAL CUSTOMER REQUESTS

OTHER

 CUSTOMER STATES RESET ALL TIRE PRESSURES	Original Approved: \$0.00 Total Approved: \$0.00
 COMPLIMENTARY JAGUAR MULTI-POINT INSPECTION	Original Approved: \$0.00 Total Approved: \$0.00
 I HAVE BEEN ADVISED AND I HAVE REMOVED EVERYTHING OF VALUE FROM MY VEHICLE. I UNDERSTAND THAT JLR LA WILL NOT BE RESPONSIBLE FOR THE LOSS OR DAMAGE OF ANY ITEMS LEFT IN MY VEHICLE. _____	Original Approved: \$0.00 Total Approved: \$0.00
 UBER VOUCHER COMPLIMENTARY RIDE SERVICE	Original Approved: \$0.00 Total Approved: \$0.00

5 Needs Immediate Attention

UNDER HOOD: FLUIDS AND FILTERS

 Inspect air cleaner element at 15k or 1 year intervals Replace the Cabin Air Filter CONTAMINATED RENEW	Repair Estimate: \$183.03
---	---------------------------

BRAKES

 Brake Linings Thickness - Rear Rear Pads - 3mm Replace Rear Brake Pads and Rotors DUE TO LOW PADS AND WORN ROTORS	Repair Estimate: \$2,212.22
---	-----------------------------

UNDER CAR: SUSPENSION, DRIVELINE, EXHAUST, LEAKS

 Inspect engine cooling system for leaks REPLACE EXPANSION TANK TO BLEED PIPE DUE TO LEAK FROM PIPE	Repair Estimate: \$294.62
---	---------------------------

CUSTOM RECOMMENDATION

 OIL SERVICE OIL LOW AND DIRTY RECOMMEND RENEWAL OF OIL AND ENGINE OIL FILTER	Repair Estimate: \$554.63
 REAR CAMERA MISALIGNMENT REFITTING OF REAR BUMPER FOR REAR CAMERA ADJUSTMENT	Repair Estimate: \$956.80

1 Needs Attention Soon

BRAKES

 Brake Linings Thickness - Front Front Brakes - 4mm Replace Front Brake Pads and Rotors with brake wear sensor DUE TO LOW PADS AND WORN ROTORS	Repair Estimate: \$2,668.92
---	-----------------------------

40 Passed Inspection

UNDER HOOD: FLUIDS AND FILTERS

- ✓ Inspect drive belts
- ✓ Inspect hood and decklid struts
- ✓ Inspect all hoses and clamps
- ✓ Inspect cabin air/HEPA micro filter(if equipped) at 15k or year intervals
- ✓ Check brake fluid level and condition

BATTERY PERFORMANCE

- ✓ Perform visual battery inspection
- ✓ Inspect battery terminal and cables

LIGHTS

- ✓ Instrument cluster warning lamps
- ✓ Inspect headlights, low and high beam operation
- ✓ Inspect fog/driving lights (if applicable)
- ✓ Inspect taillight, turn signal, side marker and license plate lights
- ✓ Inspect taillight, turn signal and side marker assemblies for cracks and damage
- ✓ Inspect brake light operation
- ✓ Inspect hazard light operation
- ✓ Inspect reverse light operation
- ✓ Inspect dash and interior lights
- ✓ Check horn operation

UNDER CAR: SUSPENSION, DRIVELINE, EXHAUST, LEAKS

- ✓ Inspect Engine for oil leaks
- ✓ Inspect brake system for leaks
- ✓ Inspect transmission for leaks
- ✓ Inspect steering system for leaks
- ✓ Check front differential for leaks
- ✓ Check rear differential for leaks
- ✓ Inspect transfer case for leaks(if applicable)
- ✓ Inspect fuel tank, lines and connections
- ✓ Inspect exhaust system for leaks, damage and loose parts
- ✓ Inspect engine mounts
- ✓ Inspect front suspension components
- ✓

GENERAL

- ✓ Inspect wiper and washer operation
- ✓ Inspect windshield wiper blades
- ✓ Inspect rear wiper blade (if applicable)

OTHER

- ✓ Inspect heat and air conditioning operation

TIRES AND ALIGNMENT

- ✓ Tread Depth Measurements - Fronts
Front Left - 8/32+/32nds
Front Right - 8/32+/32nds
- ✓ Tread Depth Measurements - Rears
Rear Left - 7/32/32nds
Rear Right - 7/32/32nds
- ✓ Inspect overall tire wear and condition

- ☐ Inspect transmission mounts
- ☒ Inspect steering components
- ☒ Inspect sway bar components
- ☒ Inspect rear suspension components
- ☒ Inspect axles, driveshaft(s), u-joints and CV joints/boots

OTHER COMMENTS

Windshield washer fluid

filled as needed - YES

Check and adjust tire pressures

Front Left - 37psi

Rear Left - 37psi

Front Right - 37psi

Rear Right - 37psi

SUMMARY OF VISIT:

Total Estimate:	\$6,870.22
-----------------	------------

	Approved	Declined	Undecided
Pre-approved amount:	\$0.00	-	-
Recommended amount:	\$282.03	\$0.00	\$6,274.90
Taxes:	\$12.59	\$0.00	\$300.70
Total:	\$294.62	\$0.00	\$6,575.60