POWER MIRROR CONTROL SYSTEM PROBLEM SYMPTOMS TABLE

700H5-02

Symptom	Suspected Area	See page
Mirror does not operate	ECU–ACC fuse (Instrument panel J/B)	68–1
	2. Mirror switch	70–25
	3. Mirror motor	70–25
	4. Wire harness	_
Mirror operates abnormally	1. Mirror switch	70–25
	2. Mirror motor	70–25
	3. Wire harness	_