HORN SYSTEM PROBLEM SYMPTOMS TABLE

69021 -06

Symptom	Suspected Area	See Page
Horn does not sound.	Horn button switch	_
	2. High pitched horn	_
	3. Low pitched horn	-
	4. HORN relay	69–3
	5. Wire harness	-