
DTC	C1251/51	PUMP MOTOR IS LOCKED/OPEN CIRCUIT	
		IN PUMP MOTOR GROUND	

CIRCUIT DESCRIPTION

DTC No.	DTC Detection Condition	Trouble Area
C1251/51	 Actuator pump motor does not operate properly. Open in actuator pump motor circuit continues for at least 2 sec. 	ABS pump motor (Brake actuator assy)

WIRING DIAGRAM



INSPECTION PROCEDURE

1 RECONFIRM DTC

- (a) Clear the DTCs (see page 05-938).
- (b) Turn the ignition switch to the ON position.

Are the same DTCs recorded?

NO END

HINT:

This DTC may be memorized due to a malfunction in the connector terminal.

YES

CHECK AND REPLACE BRAKE ACTUATOR ASSY (SEE PAGE 32-58)