STARTING & CHARGING PREPARATION

020WB 01

SST

	09249-63010	Torque Wrench Adaptor	GENERATOR ASSY(1AZ-FE)
B			GENERATOR ASSY(2AZ-FE)

Recomended Tools

(09083-00150)	Test Lead Set	STARTING SYSTEM(1AZ-FE) STARTING SYSTEM(1MZ-FE) STARTING SYSTEM(2AZ-FE)
09216-00021	Belt Tension Gauge	GENERATOR ASSY(1MZ-FE)

Equipment

Ammmeter(A)	
Ohmmeter	
Torque wrench	