## **PROBLEM SYMPTOMS TABLE**

700BO-01

Symptom	Suspected Area	See page
Mirror does not operate	ECU-ACC fuse (Instrument panel J/B)	68-1
	2. Mirror switch	70-24
	3. Mirror motor	70-24
	4. Wire harness	-
Mirror operates abnormally	1. Mirror switch	70-24
	2. Mirror motor	70-24
	3. Wire harness	_