REAR SUSPENSION SERVICE DATA

030GA-01

	Toe-in (total)		$0^{\circ}22' \pm 11' (0.4^{\circ} \pm 0.2^{\circ}, 4.0 \pm 2.0 \; \text{mm}, 0.16 \pm 0.08 \; \text{in.})$
Rear wheel align-	Camber	HI-UP	$-1^{\circ}00' \pm 45' (-1.00^{\circ} \pm 0.75^{\circ})$
ment		Except HI-UP	-1°13' ± 45' (-1.22° ± 0.75°)
		Right-left error	45' (0.75°) or less
Rear suspension	Stabilizer bar link ball joint turning torque		0.05 – 1.0 N·m (0.5 – 10 kgf·cm, 0.4 – 8.7 in.·lbf)