## KEY UNLOCK WARNING SYSTEM PROBLEM SYMPTOMS TABLE

7307W-0

Symptom	Suspected Area	See page
Key reminder buzzer does not sound	Unlock warning switch	73–15
	Front door courtesy lamp switch	73–15
	3. Instrument panel J/B (Body ECU)	73–13
	4. Combination meter	_
	5. Wire harness	_